

STUDY ON MASONRY WALLS WITH TREES

GEO REPORT No. 257

C.M. Wong & Associates Limited & C.Y. Jim

**GEOTECHNICAL ENGINEERING OFFICE
CIVIL ENGINEERING AND DEVELOPMENT DEPARTMENT
THE GOVERNMENT OF THE HONG KONG
SPECIAL ADMINISTRATIVE REGION**

STUDY ON MASONRY WALLS WITH TREES

GEO REPORT No. 257

C.M. Wong & Associates Limited & C.Y. Jim

**This report was prepared by C.M. Wong & Associates Limited and C.Y. Jim in
November 2005 under Consultancy Agreement No. CE 11/2004(GE)
for the sole and specific use of the Government of the
Hong Kong Special Administrative Region**

© The Government of the Hong Kong Special Administrative Region

First published, January 2011

Prepared by:

Geotechnical Engineering Office,
Civil Engineering and Development Department,
Civil Engineering and Development Building,
101 Princess Margaret Road,
Homantin, Kowloon,
Hong Kong.

PREFACE

In keeping with our policy of releasing information which may be of general interest to the geotechnical profession and the public, we make available selected internal reports in a series of publications termed the GEO Report series. The GEO Reports can be downloaded from the website of the Civil Engineering and Development Department (<http://www.cedd.gov.hk>) on the Internet. Printed copies are also available for some GEO Reports. For printed copies, a charge is made to cover the cost of printing.

The Geotechnical Engineering Office also produces documents specifically for publication. These include guidance documents and results of comprehensive reviews. These publications and the printed GEO Reports may be obtained from the Government's Information Services Department. Information on how to purchase these documents is given on the second last page of this report.



R.K.S. Chan
Head, Geotechnical Engineering Office
January 2011

EXECUTIVE SUMMARY

C.M. Wong & Associates Ltd (CMWAL) was appointed by the Geotechnical Engineering Office (GEO) of the Civil Engineering and Development Department (CEDD) to conduct a study on masonry walls. The task is part of Agreement No. CE 11/2004 (GE), 10-year Extended LPM Project, Phase 5, Package E, Tai Po, Landslip Preventive Works on Government Slopes and Related Studies - Investigation, Design and Construction.

The Brief for the Special Task requires CMWAL, with the support of a tree specialist, to conduct a study on the methods of upgrading masonry walls with the objective of preserving the masonry blocks and existing trees thereon as far as possible.

This study of this special task commenced in November 2004. Professor C.Y. Jim of the Department of Geography, HKU, was appointed as the tree specialist.

This study aims to assess the effects of wall trees on masonry walls. The stability of wall trees was not studied. This study included literature review, site inspections and information search. Based on the study, if trees grow on masonry walls, tree roots have minimal harmful effect and some beneficial effect on the stability of masonry walls. Due to the difficulty in quantifying the effect of roots, it may be ignored during stability analysis of masonry walls with trees. Surcharge of wall trees were found to have adverse effect on the stability of masonry walls. Wind forces on wall trees may cause additional sliding forces and overturning moments to act on the masonry walls. In the assessment of stability of retaining wall with trees, professional judgement should be exercised regarding whether the root anchorage is strong enough to sustain the design wind forces. If not, the effects of wind forces on wall trees could be ignored as far as the consequential effect on masonry walls is concerned.

In order to upgrade substandard masonry walls with the existing trees preserved and existing masonry patterns retained, installation of soil nails, construction of hand-dug caissons, flying buttresses (where space permits) or a combination of the methods is recommended under different site conditions. Safety standards for checking the stability of masonry walls with trees are also recommended in this report.

Special measures should be carried out during the upgrading of masonry walls that deserve preservation of the existing trees and the existing masonry patterns. The recommended special measures are presented in this report.

CONTENTS

	Page No.
Title Page	1
PREFACE	3
EXECUTIVE SUMMARY	4
CONTENTS	5
1. INTRODUCTION	9
1.1 Summary of the Brief Requirements	9
1.2 Main Tasks of the Study	9
1.3 Outline of the Study	9
2. EXISTING TREES GROWING ON MASONRY WALLS IN HONG KONG	10
2.1 Wall Trees in Hong Kong	10
2.2 Wall Tree Species	12
3. EFFECTS OF EXISTING TREES GROWING ON A MASONRY WALL	13
3.1 Effects of Tree Roots	14
3.1.1 Effect of Tree Roots on Masonry Block Integrity	14
3.1.1.1 Strangler Rooting Habit of Banyans	14
3.1.1.2 Banyans as Pre-adapted Wall Trees	15
3.1.1.3 Co-existence between Banyan Roots and Walls	16
3.1.1.4 Banyan Roots As a Wall Stabilizing Force	16
3.1.2 Effect of Tree Roots on Soil behind Retaining Walls	17
3.1.2.1 Root Strengthening	17
3.1.2.2 Tree Root Decay	17
3.1.2.3 Quantifying Root Strengthening Effect	18
3.1.3 Relevant Wall Failures	18
3.1.3.1 Search for Relevant Wall Failures	18
3.1.3.2 Records of Relevant Wall Failures	21

	Page No.
3.1.4 Recommendations	25
3.2 Effects of Tree Stem	25
3.2.1 Surcharge of Trees on Masonry Walls	26
3.2.1.1 Regression Method	27
3.2.1.2 Species Group Adopted	29
3.2.1.3 Moisture in Wall Trees	30
3.2.1.4 Recommendation	30
3.2.2 The Wind Effect on Trees and Thus on Masonry Walls	30
3.2.2.1 Stem Failure	31
3.2.2.2 Uprooting	33
3.2.2.3 Static Effect	34
3.2.2.4 Basic Wind Pressure	34
3.2.2.5 Drag Coefficient	35
3.2.2.6 Frontal Area	38
3.2.2.7 Dynamic Effects	39
3.2.2.8 Recommendation	41
3.2.3 Recommendation	42
4. EXAMPLES OF UPGRADING WORKS	44
4.1 Search for Examples of Upgrading Works	44
4.2 Preservation of the Existing Masonry Pattern (or Façade)	45
4.3 Preservation of Existing Trees on the Walls	46
5. PROPOSED METHODS OF UPGRADING MASONRY WALLS	50
5.1 Soil Nails	50
5.2 Buttresses	51
5.2.1 Conventional Buttresses	51
5.2.2 Flying Buttresses	52
5.3 Hand-dug Caissons	54
5.4 Recommendation	55
6. SPECIAL MEASURES ON UPGRADING MASONRY WALLS WITH TREES	55

	Page No.
6.1 Guiding Principles	56
6.2 Preserving the Existing Masonry Pattern (or Façade)	56
6.3 Protecting Tree Roots and Stems From Damage	57
6.3.1 Importance of Protecting Tree Roots from Damage	57
6.3.2 Tree Root Pruning	57
6.3.3 Trimming of Branches, Leaves or Roots of Wall Trees	58
6.4 Continued Growth of Existing Trees	58
6.4.1 Keeping Joints Unsealed	59
6.5 Conclusion	59
7. SAFETY STANDARD FOR CHECKING MASONRY RETAINING WALLS WITH TREES	59
7.1 Approaches	60
7.2 Existing Walls, New Walls and Remedial Works	60
7.3 Factor of Safety for Masonry Walls	61
7.3.1 Structural Failure	61
7.3.2 Sliding, Overturning and Bearing Capacity	61
7.4 Recommended Factor of Safety for Walls with Trees	61
7.4.1 Structural Failure	62
7.4.2 Sliding, Overturning and Bearing Capacity	62
7.4.2.1 Sliding	62
7.4.2.2 Overturning	62
7.4.2.3 Bearing	63
7.5 Conclusion	63
8. CONCLUSION	65
9. REFERENCES	67
APPENDIX A	70
APPENDIX B	72
APPENDIX C	133
APPENDIX D	136

	Page No.
APPENDIX E	139
APPENDIX F	147

1. INTRODUCTION

1.1 Summary of the Brief Requirements

C.M. Wong & Associates Ltd (CMWAL) was appointed by the Geotechnical Engineering Office (GEO) of the Civil Engineering and Development Department (CEDD) to conduct a study on masonry walls. The task is part of Agreement No. CE 11/2004 (GE), 10-year Extended LPM Project, Phase 5, Package E, Tai Po, Landslip Preventive Works on Government Slopes and Related Studies - Investigation, Design and Construction.

The Brief for the Special Task requires CMWAL, with the support of a tree specialist, to conduct a study on the methods of upgrading masonry walls with the objective of preserving the masonry blocks and existing trees thereon as far as possible.

The study of this special task commenced in November 2004. Professor C.Y. Jim of the Department of Geography, HKU, was appointed as the tree specialist.

1.2 Main Tasks of the Study

The main tasks of the study are to:

- (i) propose methodology to assess the following effects of existing trees growing on a masonry wall on the stability and structural integrity of the wall:
 - (a) the wind effect on wall trees and thus on masonry walls;
 - (b) the surcharge of trees on masonry walls; and
 - (c) the effect of tree roots;
- (ii) propose methods of upgrading masonry walls under various scenarios taking into account the following aspects:
 - (a) stability of the wall with due account of the effect of the existing trees thereon;
 - (b) preservation of existing trees on the walls; and
 - (c) preservation of the existing masonry pattern (or façade).

1.3 Outline of the Study

In order to study the effects of existing trees growing on a masonry wall on the stability and structural integrity of masonry walls, the species of existing trees was first studied. Detailed discussion is included in Section 2.

Based on the tree species found on masonry walls in Hong Kong, the effects of the trees were classified based on the following tree portions:

- (i) tree roots; and
- (ii) tree stem.

The effects of tree roots can be further classified into the following aspects:

- (i) effect of tree roots on masonry block integrity; and
- (ii) effect of tree roots on soil behind retaining walls.

The details are discussed in Sections 3.1.1 and 3.1.2.

In addition to the theory of effects of tree roots on the stability of masonry walls, wall failures related to wall trees were collected and assessed. Detailed discussion is included in Section 3.1.3.

The effects of aboveground portion of wall trees are further classified into the following aspects:

- (i) surcharge of trees on masonry walls; and
- (ii) wind effect on wall trees and thus on masonry walls.

The details are discussed in Section 3.2.1 and 3.2.2.

In order to review upgrading methods for masonry walls, examples were collected and are presented in Section 4. The proposed upgrading methods are presented in Section 5. During the upgrading of masonry walls, special measures should be carried out and these measures are presented in Section 6.

The existing stability of masonry walls and the adequacy of upgrading works should be checked against the safety standard. The proposed safety standard for checking masonry walls with trees is presented in Section 7.

2. EXISTING TREES GROWING ON MASONRY WALLS IN HONG KONG

2.1 Wall Trees in Hong Kong

Hong Kong's territory consists of mainly hilly areas. During the urban development of Hong Kong in early days, slopes were cut and masonry retaining walls were built for constructing houses and roads. Frequently, trees were found growing spontaneously on these old masonry walls. The majority of these old masonry walls with trees are found in northern part of Hong Kong Island, especially in the Mid-Levels.

The walls-cum-vegetation, many exceeding 100 years old, furnish a precious natural-cum-cultural heritage and decorate some otherwise drab neighbourhoods. As masonry walls with trees constitute an important and beautiful landscape element of urban Hong Kong, efforts should be made on preserving the existing trees and the existing masonry pattern on masonry walls.

In this report, the effects of a tree growing on a masonry wall, wall tree, were assessed. According to Jim (1998), a wall tree was defined as “one with most of its roots spreading on or penetrating through the wall face, and with the trunk base situated within the confines of a wall. A tree overhanging above a wall but not physically attached to it, and a tree with trunk base and most roots located outside a wall’s boundaries, did not qualify.”



Figure 1 - A Chinese Banyan Growing Spontaneously on a Masonry Wall at High Street



Figure 2 - A Chinese Banyan Clinging on a Masonry Wall at Bonham Road

2.2 Wall Tree Species

The most common wall tree species found in Hong Kong is *Ficus microcarpa*, commonly known as Chinese Banyan.

According to Jim (1998), “Some 505 walls with 1275 trees (>1 m tall) were found mainly in residential areas”. Among these wall trees, there were 30 wall tree species, which are dominated by Moraceae (Mulberry family). Eight of which contribute 88% of the population and Chinese Banyan, the dominant wall tree species, contributes about half the population.

The following table shows the frequency of trees growing on masonry walls in urban Hong Kong. The Chinese names of the 30 tree species are included in Appendix A.

Table 1 - Species Composition and Frequency of Trees Growing on Stone Retaining Walls in Urban Hong Kong (Jim, 1998)

Scientific Name	Common Name	Family	Tree Frequency	
			Count	%
<i>Ficus microcarpa</i>	Chinese banyan	Moraceae	637	49.96
<i>Ficus superba</i>	Superb fig	Moraceae	184	14.43
<i>Ficus hispida</i>	Rough-leaf stem fig	Moraceae	105	8.24
<i>Ficus virens</i>	Big-leaved fig	Moraceae	74	5.80
<i>Celtis sinensis</i>	Chinese hackberry	Ulmaceae	59	4.63
<i>Broussonetia papyrifera</i>	Paper mulberry	Moraceae	54	4.24
<i>Ficus variegata</i>	Red-stem fig	Moraceae	50	3.92
<i>Ligustrum sinense</i>	Chinese privet	Oleaceae	18	1.41
<i>Maesa perlaris</i>	(nil)	Myrsinaceae	15	1.18
<i>Ficus religiosa</i>	Peepul tree	Moraceae	13	1.02
<i>Bridelia monoica</i>	Pop-gun seed	Euphorbiaceae	12	0.94
<i>Litsea glutinosa</i>	Pond spice	Lauraceae	11	0.86
<i>Macaranga tanarius</i>	Elephant's ear	Euphorbiaceae	8	0.63
<i>Cassia surattensis</i>	Sunshine tree	Caesalpinaceae	6	0.47
<i>Mallotus paniculatus</i>	Turn-in-the-wind	Euphorbiaceae	6	0.47
<i>Cratogeomys ligustrinum</i>	Yellow-cow wood	Hypericaceae	5	0.39
<i>Dalbergia balansae</i>	South China rosewood	Papilionaceae	3	0.24
<i>Alangium chinense</i>	Chinese alangium	Alangiaceae	2	0.16
<i>Delonix regia</i>	Flame of the forest	Caesalpinaceae	2	0.16
<i>Albizia lebeck</i>	Lebeck tree	Mimosaceae	1	0.08
<i>Aporosa chinensis</i>	Aporosa	Euphorbiaceae	1	0.08
<i>Bauhinia blakeana</i>	Hong Kong orchid tree	Caesalpinaceae	1	0.08
<i>Carica papaya</i>	Papaya	Cariaceae	1	0.08
<i>Liquidambar formosana</i>	Sweet gum	Hamelidaceae	1	0.08
<i>Litsea monoptala</i>	Persimmon-leaf litsea	Lauraceae	1	0.08
<i>Nerium indicum</i>	Oleander	Apocynaceae	1	0.08
<i>Punica granatum</i>	Pomegranate	Punicaceae	1	0.08
<i>Sapium sebiferum</i>	Tallow tree	Euphorbiaceae	1	0.08
<i>Schefflera octophylla</i>	Ivy tree	Araliaceae	1	0.08
<i>Thevetia peruviana</i>	Yellow oleander	Apocynaceae	1	0.08

Chinese Banyan is a large evergreen tree with simple ovate leaf. It can easily be recognised by an abundance of aerial roots.


To facilitate field assessments and calculations, the effects of wall trees are determined based on the dominant wall tree species, Chinese Banyan. Detailed discussions on the effects of wall trees are included in Sections 3 and 4.

3. EFFECTS OF EXISTING TREES GROWING ON A MASONRY WALL

One of the main tasks of this study is assessing the effects of wall trees on the stability and structural integrity of masonry walls. Literature review, information search and site inspections were carried out and the effects were classified based on the following tree portions:

- (i) tree roots; and
- (ii) tree stem.

Detailed discussions are included in Sections 3 and 4.



3.1 Effects of Tree Roots

The effects of tree roots can be further classified into the following aspects:

- (i) effect of tree roots on masonry block integrity; and
- (ii) effect of tree roots on soil behind retaining walls.

The details are discussed in Sections 3.1.1 and 3.1.2.

In order to review the effects of tree roots on the stability of masonry walls, past wall failures related to wall trees were collected and assessed. Detailed discussion is included in Section 3.1.3.

3.1.1 Effect of Tree Roots on Masonry Block Integrity

In order to review the effect of tree roots on the stability of masonry blocks integrity and the walls as a whole, the following characteristics of ecological association between walls and trees were studied:

- (i) strangler rooting habit of Banyans;
- (ii) Banyans as pre-adapted wall trees;
- (iii) co-existence between Banyan roots and walls; and
- (iv) Banyan roots as a wall stabilizing force.

3.1.1.1 Strangler Rooting Habit of Banyans

Wall trees, especially the *Ficus* species (Banyan or Fig trees in general), tend to develop an exceptionally strong and extensive root system in comparison with other tropical tree species. Other tree species could seldom grow on walls because their root growth habit does not permit them to hold onto the vertical face and explore the soil behind it. This is closely related to the natural strangler habit of some *Ficus* trees which have evolved a life strategy to suppress and eventually kill existing forest trees literally by strangulation using its highly versatile and vigorous roots.

Strangler

A strangler is a woody plant, usually a vine or a tree, that grows on a host tree by developing aerial roots to extend down the trunk of the host, coalesce around it, and eventually killing it by strangling.

Many Banyan trees have the natural ability to divert a good proportion of their energy and resources to develop a profusion of aerial roots to hang down from the host trees in the natural tropical forest, aiming at reaching the soil eventually. Originally the aerial roots are soft and flexible like ropes. Upon striking the soil, numerous “normal” soil-dwelling roots will permeate the soil to extract water and nutrients. The increase in food supply could be diverted to support even more new aerial root growths. The survival strategy is to extend the

aerial roots to reach the soil so that it could gain a strong foothold and acquire the sustenance for the tree to expand and flourish. The host tree will soon be wrapped around by masses of lignified (become woody) Banyan roots.



Host Tree

A host tree is a tree that has a strangler tree, usually a Banyan, growing on it. The strangler will gradually grow bigger and wrap around the branches and trunk of the host tree. The aerial roots of the strangler will thicken, become woody, and fuse together to form a tight basket-like enclosure around the host. Eventually the host tree may be killed literally by strangulation.

Sustenance

Sustenance is the means whereby an organism lives; for plants, it refers to water and nutrients from the soil, carbon dioxide and oxygen from the atmosphere, and energy from sunshine.

With continued secondary thickening of the host trunk and that of the encircling Banyan roots, the host tree's vascular system for the transport of food, which is the phloem layer situated below the bark, is squeezed and eventually cut off. The strangled tree will gradually decline and finally die. The niche originally occupied by the host tree is thus taken over by the strangler Banyan.

Niche

Niche is the location and functional role played by an organism in an ecosystem.

Phloem

Phloem is the inner bark, a thin layer of tissues of a plant's vascular system, responsible for the transport of food in solution form produced by photosynthesis to different parts of a plant.

Vascular

Vascular describes the thin tube-like channels that conduct and circulate fluids inside higher forms of plants such as trees, shrubs and herbs.

3.1.1.2 Banyans as Pre-adapted Wall Trees

Growing on a stone retaining wall, the Banyans could be considered as pre-adapted to the cliff-like and inherently stressful habitat. The wall face is equivalent to the body of the host, and the soil behind the stone façade is the ultimate destination of its probing aerial roots. The joints between the masonry blocks will be probed and penetrated by the aerial roots, whereupon they will extend into the soil lying behind the stone structure to search for water, nutrients and anchorage. Upon striking the soil, the aerial roots will ramify and develop a normal soil-dwelling root system. The water and nutrients thus captured will be sent to the leaves for photosynthesis to manufacture food, some of which will be sent back to the roots to permit their continual extension and expansion.

Ramify

To ramify means to divide into two or more branches or roots.

With a reinforced supply of food, the originally soft aerial roots will gradually thicken and become lignified. This secondary thickening process would seldom cause displacement of masonry blocks, because the stones are tightly packed together in a wall and the resultant mechanical resistance to root expansion is so great that no plant roots could exert enough pressure to overcome it. Thus the secondary thickening takes a rather unique mode by spreading laterally to fill the narrow gap afforded by the joint. The root in the joint therefore adapts itself into a sheet-like configuration, moulding itself to fit snugly the shape and size of the gap. It is likened to a mutual accommodation between wall and tree, allowing both to continue to exist.

This is consistent with Biddle (1998). Biddle (1998) stated that “roots are not capable of picking the mortar out from between the bricks to create a gap and are quite incapable of damaging normal brickwork by their increase in diameter. They are merely exploiting existing gaps in the mortar, to obtain the water and nutrients contained in the brickwork.”

3.1.1.3 Co-existence between Banyan Roots and Walls

Thus the common notion that roots will thicken into a cylindrical or rod-like feature that could wedge open joints in a stone wall, based on field assessment of Banyan root growth habit on walls, is not substantiated by empirical evidence. That the wall surface roots are largely cylindrical before they enter the joints might have given the wrong impression or interpretation. The chance of Banyan roots in the joints pushing masonry blocks apart is very rare. The few cases of such stone displacements occur mainly at the end or the top of a wall where the mechanical resistance to stone movement is relatively low. Where they occur, they affect usually at the most a few blocks restricted to the end-most or top-most positions. A thorough inspection of the old stone walls with trees will lend testimony to this observation.

At the wall top, occasionally the stones (the capping or coping stone) are slightly lifted because of the lower overburden pressure. Due to the largely horizontal placement of the slab-like blocks, the risk of them falling down is not high.

Failure of walls due to root action of trees is rare. However, special attention should still be paid on any masonry block displacement during site inspection of masonry walls with trees.

3.1.1.4 Banyan Roots As a Wall Stabilizing Force

Living roots have strong tensile strength, and as long as they live and are not damaged or weakened, the strength remains. A Banyan tree could send from a few to hundreds of roots through the joints to reach the soil. Before they enter the joints, the surface roots sometimes form a dense network covering the stone façade, and provide support not only to the tree but also to the stone face. Additionally, the surface roots have a tendency to fuse together by spontaneous self-grafting, thus forming a basket-like network of interconnected woody strands that collectively could supply a lot of mechanical strength. The effect is analogous to laying a net made of high strength synthetic materials on the wall face.



Figure 3 - The Surface Roots of Chinese Banyan Form a Dense Network Covering the Stone Façade at Hospital Road

3.1.2 Effect of Tree Roots on Soil behind Retaining Walls

In order to review the effect of tree roots on soil behind retaining walls and the method of quantifying the effect, a literature review was carried out.

3.1.2.1 Root Strengthening

Tree roots can strengthen soil. In masonry walls with trees, the roots of wall trees that penetrate the joints would move into the soil situated behind the stones, and there they will ramify and anchor the tree. Therefore, the soil behind tree walls is likely to be strengthened by tree roots. This is consistent with Chan (1996) and Lee (1985).



Chan (1996) thought that “if the tree root system penetrates a wall into the retained soil, it will reinforce the soil locally and increase the friction between the soil and the wall. This reinforcement effect should be more prominent for dense soils. Again, the amount of this effect is not known and it is unlikely that it can be found analytically.”

Lee (1985) stated that “the root system of vegetation also serves the function of slope stabilisation by providing reinforcement and additional resistance to the soil mass.”

3.1.2.2 Tree Root Decay

Decay of tree roots will create voids in soil. However, all soils contain porosity to

permit the transfer of air and water and for the storage of moisture, a part of which is available to plant growth. Some porosity is due to natural grain packing, some to natural soil structural formation, and some to biological activities such as the channels left by burrowing worms or after the death of roots. The smaller roots grow and die continually, and the pores formed after the decay of such roots are small and can be considered a part of natural soil forming processes. They do not concentrate subsurface water flows and will not threaten wall stability.

Decay of larger roots may increase the permeability of soil and the stability of soil behind masonry walls may be affected. Most trees will keep most of the larger roots, just like they will keep most of the branches. However, being living creatures, some branches and some large roots will occasionally die usually due to the invasion of wood-decay fungus or to diseases induced by other pathogenic organisms. Special attention should be paid on decay of large tree roots to ascertain that the strength of soil is not affected.

3.1.2.3 Quantifying Root Strengthening Effect

Based on literature review, the following simplified equation was found in Gray & Sotir (1995), Greenway (1987) and Lee (1985) for determining the effect of root reinforcement and strength on soil.

$$\Delta s = 1.2 T_R (A_R/A)$$

where Δs is the shear strength increase
 T_R is the tensile strength of root
 A_R/A is the root area ratio

Based on Gray & Sotir (1995), this model assumes that the roots are well anchored and do not pull out under tension. The root fibers must be long enough and/or subjected to sufficient interface friction for this assumption to be satisfied.

Greenway (1987) also reported that the tensile strength of root for Chinese Banyan was 16 MPa.

3.1.3 Relevant Wall Failures

3.1.3.1 Search for Relevant Wall Failures

In order to review the effects of tree roots on the stability of masonry walls, wall failures that are possibly related to wall trees were collected from the following sources and assessed:

- (i) a list provided by LPM Division 1, Geotechnical Engineering Office (GEO);
- (ii) records from Leisure and Cultural Services Department (LCSD);
- (iii) records from Agriculture, Fisheries & Conservation Department (AFCD);

- (iv) record provided by GEO in a meeting;
- (v) Chan (1996) - GEO Report No. 31; and
- (vi) newspapers.

A list provided by LPM Division 1, Geotechnical Engineering Office (GEO)

A list of features in Central and Western District and Wan Chai District were received from LPM Division 1, GEO in Nov 2004. There were totally 2642 features in the list. These features are all retaining walls (CR, FR and R types) of masonry or unknown wall types. Out of these 2642 features, there were 55 features with landslide incident reports and two of them had past instability related to trees.

Records from Leisure and Cultural Services Department (LCSD)

Letters were sent to 18 Districts of LCSD in Dec 2004 and Jan 2005 to retrieve records of cases involving tree collapse on masonry walls. 13 Districts replied and only two Districts had records. A summary table showing the replies from LCSD is included in Appendix B, Page B1.

Records from Agriculture, Fisheries & Conservation Department (AFCD)

A Letter was sent to AFCD in Dec 2004 to retrieve records of cases involving tree collapse on masonry walls. No records of tree collapse on masonry walls were under the maintenance responsibility of AFCD.

Record provided by GEO in a meeting

A case related to tree was provided by GEO in a meeting for this special task on 14 Dec 2004.

Chan (1996) - GEO Report No. 31

Chan (1996) studied 10 case histories of instability of masonry retaining walls in Hong Kong. None of them were related to trees.

Newspapers

A wall tree failure was reported on 9 Aug 2005 at 67 Wyndham Street, Central.

Table 2 - Summary of Landslide Incident Records Related to Trees

Feature No.	Location	Incident No. (Date of Incident)	Type of Failure	Scale	Possible Contributing Causes of Failure	Source of Information
11SW-A/FR24	Behind Hillview Garden, Hill Road, Pokfulam	HK97/5/2 (09/05/1997)	Non landslip case (tree fall and masonry blocks fall)	Two masonry blocks involved	Tree fall	LPM1/GEO
11SW-A/R120	Ka Wai Man Road Garden	- (9/2003)	-	-	-	LCSD
		HK99/8/3 (22/08/1999)	Non landslip case (tree uprooted with 6 m x 4 m x 1 m soil mass on slope)	24 m ³	Tree uprooted under typhoon	
11SW-A/R751	South of 450-456, Queen's Road West, Hong Kong	HK1999/8/4 (23/08/1999)	Retaining wall hit by fallen tree which grew above the wall	N/A	N/A	LPM1/GEO
	Clarence Terrace Children's Playground	- (06/2003)	-	-	-	LCSD
11SE-A/C897 (old no. 11SE-A/R51)	Front of Lai Sing Court, Tai Hang Road, Tai Hang	HK2003/9/0180 (04/09/2003)	Tree fall and adjacent stone pitching blocks on wall pulled down	1 m ³ volume of slip scar	Tree uprooted by strong wind pull down the adjacent stone pitching block near the crest of wall	Meeting on 14 Dec 04
11NW-B/C321	Lei Cheng Uk Swimming Pool	- (09/2004)	-	-	-	LCSD
11SW-B/R735	Behind and below 61-67 Wyndham Street, Central	- (09/08/2005)	-	-	-	Newspapers

3.1.3.2 Records of Relevant Wall Failures

From the records collected, the following five features were found to have wall failures related to trees:

- (i) Feature No. 11SW-A/FR24;
- (ii) Feature No. 11SW-A/R120;
- (iii) Feature No. 11SW-A/R751;
- (iv) Feature No. 11SE-A/C897 (old no. 11SE-A/R51); and
- (v) Feature No. 11NW-B/C321.

The details of the above features were summarized in Table 2. The basic information and detailed information, photographs, plans, SIFT report and landslide incident reports were included in Appendix B.

Feature No. 11SW-A/FR24

Based on the landslide incident report (HK97/5/2), Feature No. 11SW-A/FR24 was a dry-packed random rubble wall. A tree was located on the wall face near the crest of the feature. The incident recorded was a non landslip case. (See Appendix B, Pages B2-B12) A tree fell down and caused localized damage to the masonry wall (two masonry blocks fell down). No signs of past instability could be found on the feature during the site inspection carried out in Nov 2004.



Figure 4 - Feature No. 11SW-A/FR24

Feature No. 11SW-A/R120

Photographs about the incident in Ka Wai Man Road Garden on Sep 2003 were received from LCSD. (See Appendix B, Pages B13-B29) From site inspection in Feb 2005, the fallen tree was located at Feature No. 11SW-A/R120. Minor repair works were noted on the wall. The joints between masonry blocks at the location of the fallen tree were repaired by cement mortar.



Figure 5 - Feature No. 11SW-A/R120



Figure 6 - Joints between Masonry Blocks at the Location of Fallen Tree were Repaired

An incident report (HK99/8/3) was found in GEO on this feature. However, the incident happened in 1999, but not 2003. The incident report indicated that the failure in 1999 involved failure in soil cut slope portion only and the fallen tree was located at the crest of a slope.

As the photographs from LCSD did not indicate any wall failure and no landslide incident report of the wall were found in GEO about this incident, it appears that the wall was not failed. Small blocks might have fallen down or only cracks appeared in the pointing.

Feature No. 11SW-A/R751

Based on the landslide incident report (HK1999/8/4) of Feature No. 11SW-A/R751, the incident recorded involved a fallen tree only. (See Appendix B, Pages B30-B38) The masonry retaining wall was not failed. Although trees were found on the wall face of the feature, the incident report indicated that the tree fallen was located behind the crest of the feature. Therefore, this incident did not involve any wall trees. No signs of past instability could be found on the feature during the site inspection carried out in Nov 2004 and Feb 2005.

Photographs about the incident in Clarence Terrace Children's Playground were received from LCSD. (See Appendix B, Pages B39-B40) From the photos and site inspection carried on Feb 2005, the fallen tree was likely to be located at the children's playground behind the crest of Feature No. 11SW-A/R751, not on the wall. No incident records in 1999 at Feature No. 11SW-A/R751 could be found in GEO. As the photographs did not indicate any wall failure and no landslide incident report of the wall were found in GEO, it appears that this incident involved fallen tree only. The masonry wall did not fail.



Figure 7 - Feature No. 11SW-A/R751



Figure 8 - Crest of Feature No. 11SW-A/R751

Feature No. 11SE-A/C897 (old no. 11SE-A/R51)

Based on the landslide incident report (HK2003/9/0180) of Feature No. 11SE-A/C897, stone pitching blocks near the crest of wall were pulled down by a tree uprooted by strong wind. However, the tree causing the failure was located behind the crest of the feature (See Appendix B, Pages B41-B50) and the feature was a cut slope, not a retaining wall. The

stone pitching blocks were a facing only. Therefore, this incident did not involve any wall trees and wall failures. The stone blocks were pulled down by a tree uprooted by strong wind not associated with the growth of the tree roots.



Figure 9 - Photo Extracted from Landslide Incident Report (HK2003/9/0180)




Figure 10 - Photo Extracted from Landslide Incident Report (HK2003/9/0180)

Feature No. 11NW-B/C321

Based on LCSD's records, a tree fell from a cut slope Feature No. 11NW-B/C321, but it was not a retaining wall. (See Appendix B, Pages B51-B60) The incident involved a fallen tree only and did not involve any wall trees and wall failures.

Feature No. 11SW-B/R735

Based on the newspapers, a wall tree on Feature No. 11SW-B/R735 failed on 9 Aug 2005. Site inspection was carried out on 10 Aug 2005. The masonry wall was not damaged.

The incidents in Feature Nos. 11SW-A/FR24 and 11SW-A/R120, although involved or might involve falling down of masonry blocks caused by wall trees, the failures were localized and the scales were small. They were caused by failure of a tree due to its own weight or wind load, not related to the growth of tree roots.

The failure of the wall tree on Feature No. 11SW-B/R735 did not cause any wall failure. The trees that failed near Feature No. 11SW-A/R751 were not actually wall trees per se. The incidents in Feature Nos. 11SE-A/C897 and 11NW-B/C321 did not involve masonry walls and thus are not related to this study.

Based on the above past instability records, there is no direct evidence to show that the roots of wall trees resulted in instability of masonry walls.



Figure 11 - Tree failure on Feature No. 11SW-B/R735

3.1.4 Recommendations

Based on the above studies, tree roots seldom cause displacement of masonry blocks. The few cases of such stone displacements occur mainly at the end or the top of a masonry wall. The tree roots may even strengthen the wall face by forming a dense network on it. However, attention should still be paid to masonry block displacement, if any, during inspections to ascertain that such displacement is not due to tree roots.

The soil behind masonry walls is likely to be strengthened by tree roots. However, attention should still be paid to possible decay of large tree roots, if any, during inspections to ascertain that the strength of the soil vulnerability to water ingress is not adversely affected. A simplified equation, presented in Section 3.1.2.3, was found for quantifying the root strengthening effect. However, it is difficult to determine the root area ratio, the extent of tree roots and thus the extent of soil that might be strengthened. The root strengthening effect may also vary greatly from place to place.

As the potential beneficial effects of the tree roots on the stability of masonry walls are difficult to quantify in a reliable manner, these beneficial effects may be conservatively ignored during stability analysis of masonry walls with trees.

3.2 Effects of Tree Stem

The effects of aboveground portion of wall trees are further classified into the following aspects:

- (i) surcharge of trees on masonry walls; and
- (ii) wind effect on wall trees and thus on masonry walls.

The details are discussed in Section 3.2.1 and 3.2.2.

Final Tree Dimensions

As trees are living beings, they will grow up until reaching the final dimensions. Therefore, instead of the current tree dimensions, the estimated final dimensions should be used during the stability of the wall analysis.


Different individual trees have different genetic constitution (the genotype) that could determine its biological potential dimensions (BPD). However, not every tree could attain its BPD. For trees growing normally on the ground, various abiotic and biotic factors interacting with or impinging on a tree will reduce the final dimensions that could be reached. This is generally known as phenotypic plasticity which is very much a function of the multivariate and changeable tree-environment interactions. In other words, the phenotype can only express itself within the boundaries circumscribed by the genotype.

Trees living on stone walls are subject to a lot more stresses than ground-growing ones, and hence they normally may not be able to attain their BPD. The amount of discount will be estimated by assessing the opportunities or stresses to tree growth on individual walls, and by evaluating the vigour of the trees in question.

In order to estimate the final dimension of each wall tree, site inspection by a tree expert should be carried out. The final dimension should be based on the expert judgment by evaluating selected ecological information of the wall tree on its past growth regime and its associated wall conditions in detail.

3.2.1 Surcharge of Trees on Masonry Walls

Aboveground biomass of wall trees furnishes additional surcharges on masonry walls. Since all wall trees are located on the front face of the walls, it causes additional overturning moments to act on the walls.




3.2.1.1 Regression Method

Based on literature review, aboveground biomass of trees was commonly determined by regression method using diameter at breast height (DBH) as the main parameter. The published equations and coefficients were found to be different with different tree species and in different literature. No studies on tree species of Chinese Banyan could be found.

Among the literature using regression method, Jenkins et al. (2003) developed more generalizable biomass regression equations for use. They “compiled all available diameter-based allometric regression equations for estimating total aboveground and component biomass, defined in dry weight terms, for trees in the United States”. They then “implemented a modified meta-analysis based on the published equations to develop a set of consistent, national-scale aboveground biomass regression equations for U.S. species”. Therefore, in this report, the equations developed by Jenkins et al. (2003) were recommended.

Diameter at breast height (DBH)



Diameter at breast height (DBH) is an important tree measurement for estimating the tree's biomass. In the United States, DBH is measured at a height 4½ft (1.37 m) above ground. In some other countries using metric system, DBH is measured at either 1.3 m or 1.4 m above ground. In this report, DBH was taken to be at 1.3 m above ground, following the practice of Agriculture, Fisheries and Conservation Department (AFCD). The measurement of DBH should follow the guidance provided in AFCD (2003) - Nature Conservation Practice Note No. 02/2003.

The trunk of a Chinese Banyan and some related *Ficus* species is often irregularly shaped mainly due to:

- (1) the self-grafting of lignified aerial roots (LAR) onto the surface of the trunk, and as a result the tissues of the previously disparate units have fused together; and
- (2) LAR that are hanging closely around the trunk but remain detached from it with a gap in between, that is showing no sign of fusion.

In measuring the DBH, for case (1) the fused LAR should be considered for all intents and purposes as part of the trunk and be included in the measurement. For case (2), the detached LAR should be excluded from the measurement.

For a tree growing on a stone wall, the position of the trunk base may not be so clear-cut because the contact face between trunk and wall is often vertical or nearly vertical. In such a case, the lower and an upper edges of the trunk base could be identified and a mid-point could be taken as the trunk base to reckon the 1.3 m height for DBH measurement.

The biomass regression equations and coefficients developed by Jenkins et al. (2003) are as follows:

(i) Total aboveground biomass equation

$$b_m = \text{Exp} (\alpha_0 + \alpha_1 \ln DBH)$$

where b_m = total aboveground biomass (kg) for trees 2.4 cm *DBH* and larger
DBH = diameter at breast height (cm)
 Exp = exponential function
 ln = natural log base “e” (2.718282)
 α_0, α_1 = coefficients (see Table 3)

Table 3 - Coefficients α_0, α_1 for Estimating Total Aboveground Biomass

Species Class	Species Group	α_0	α_1
Hardwood	Aspen / alder / cottonwood / willow	-2.2094	2.3867
	Soft maple / birch	-1.9123	2.3651
	Mixed hardwood	-2.4800	2.4835
	Hard maple / oak / hickory / beech	-2.0127	2.4342
Softwood	Cedar / larch	-2.0336	2.2592
	Douglas-fir	-2.2304	2.4435
	True fir / hemlock	-2.5384	2.4814
	Pine	-2.5356	2.4349
	Spruce	-2.0773	2.3323
Woodland	Juniper / oak / mesquite	-0.7152	1.7029

(ii) Biomass ratio equation

$$\text{ratio} = \text{Exp} (\beta_0 + \beta_1 / DBH)$$

where ratio = ratio of component to total aboveground biomass for trees
 β_0, β_1 = coefficients (see Table 4)

Table 4 - Coefficients β_0, β_1 for Estimating Component Ratios of Total Aboveground Biomass

Species Class	Biomass Component	β_0	β_1
Hardwood	Foliage	-4.0813	5.8816
	Coarse roots	-1.6911	0.8160
	Stem bark	-2.0129	-1.6805
	Stem wood	-0.3065	-5.4240
Softwood	Foliage	-2.9584	4.4766
	Coarse roots	-1.5619	0.6614
	Stem bark	-2.0980	-1.1432
	Stem wood	-0.3737	-1.8055

Branch biomass can be obtained by subtracting total above ground biomass by other components (foliage, stem bark and stem wood).

The Chinese name of the species group is included in Appendix C, Page C1.

3.2.1.2 Species Group Adopted

The equations published by Jenkins et al. (2003) were developed for U.S. species and these species are temperate latitude tree species. However, wall trees in Hong Kong are tropical tree species. They do not belong to any species groups in Table 3. In order to use the equations published by Jenkins et al. (2003), a suitable species group should be chosen.

Species Group Based on Chinese Banyan

Surcharge of trees on masonry walls depends on its aboveground biomass. Trunk and branches (the woody parts) rather than foliage are the principal contributor of aboveground biomass of trees.

Among the 30 tree species found on masonry walls in Hong Kong, the *Ficus* species and *Celtis sinensis* species tend to develop heavy trunk and branches. For the same diameter at breast height (DBH), tree height and crown spread, they should have similar weight. As discussed in Section 2.2, Chinese Banyan is the dominant wall tree species in Hong Kong. Therefore, the aboveground biomass of wall trees is determined based on Chinese Banyan trees.

Chinese Banyan

Chinese Banyan is an evergreen broadleaf tree with a decurrent tree architecture, meaning that it has no clear central leader and the main (scaffold) branches are quite thick and they tend to be more or less similar in diameter to share the co-dominance. Branches tend to bifurcate at many levels until they reach the smallest twigs at the outer rim of the crown. The leaves are flat blades which have a relatively higher specific surface area and higher wind resistance than conifer needle-shaped leaves. The overall tree form of a Banyan is a broad crown with a rounded top with dense foliage.

Twig

A twig is the smallest division of a branch, usually composed of rather new branches of the current or preceding year.

Species Group Adopted

Based on the above characteristics, to estimate the surcharge of a Chinese Banyan tree, the best choice is “hard maple / oak / hickory / beech” under Hardwood category although equations adopted for tropical trees may over-estimate the bark weight in tropical trees.

Moreover, among the species group in Jenkins et al. (2003), “hard maple / oak / hickory / beech”, the total aboveground biomass of “Hard maple/oak/hickory/beech” is

generally the largest (See Appendix C, Page C2). Therefore, the species group of “hard maple / oak / hickory /beech” was recommended.

3.2.1.3 Moisture in Wall Trees

Biomass of trees with moisture should be considered during stability analysis. However, the regression equation recommended in Section 3.2.1.1 estimates total aboveground and component biomass, defined in dry weight terms. Therefore weight of water should further be allowed for.

The weight of water in living trees can vary according to species, tree age, tree size, tree health, soil moisture, wind speed, air temperature, relative humidity and stomatal conductance. Therefore, literature review has been conducted on the moisture content of trees.

The amount of wood moisture varies by the position above the ground, with a tendency to have more moisture in the heartwood at the base of the trunk and a gradual decrease with height. Therefore, an average value of 50% of the dry weight of the wood is recommended to denote the water content in living trees during the stability analysis.

Moisture content

Moisture content of wood is defined as the weight of water in wood expressed as a fraction, usually a percentage, of the weight of oven-dry wood.

Stomatal conductance

Stomatal conductance is the rate of passage of water vapour and air through the stomata which are tiny pores on leaf surfaces.

Heartwood

As a tree increases in age and diameter, an inner portion of the sapwood becomes inactive and finally ceases to function, as the cells die. This inert or dead portion is called heartwood.

Sapwood

Sapwood is comparatively new wood, comprising living cells in the growing tree, situated in the outer part of a trunk or branch. All wood in a tree is first formed as sapwood.


3.2.1.4 Recommendation

The equations developed by Jenkins et al. (2003) may over-estimate the bark weight in determining aboveground biomass of Chinese Banyan. However, these equations were comparatively more consistent and national-scale and no publications could be found for Chinese Banyan. Therefore, in this report, the equations developed by Jenkins et al. (2003) were recommended to determine the dry weight of wall trees and the species group of “hard maple / oak / hickory /beech” was recommended.

The surcharge of the tree trunk should be increased by 50% to allow for the moisture content of wall trees.

3.2.2 The Wind Effect on Trees and Thus on Masonry Walls

Wind forces on wall trees may cause additional sliding forces and overturning moments to act on the masonry walls. As a wall tree is not a temporary structure, according to Building (Construction) Regulations, the wind load shall be based on the velocity and gust effect of winds from any direction suitably determined from a return period of not less than 50 years.



When the tree stem and anchorage between the tree roots and the masonry wall are strong enough to resist stem failure and uprooting, the wind load acting on wall trees will be transmitted to the masonry wall and cause additional sliding forces and overturning moments. Details of calculation of wind loading on masonry walls are included in Sections 3.2.2.3 to 3.2.2.7.

However, wall trees, which are different to buildings or structures, grow naturally and are not designed to provide supports. Wall trees may therefore fail before sustaining a significant wind pressure. Therefore, whether wind load should be checked or not will principally depend on the resistive bending moment of the tree that can be developed at failure.

There are two potential modes of failure for wall tree: stem failure and uprooting. Uprooting is more prevalent in tree failures. If the root anchorage is strong enough to prevent a tree from uprooting, the force will be transferred to the tree stem and could result in stem breakage. Details of stem failure and uprooting are included in Sections 3.2.2.1 and 3.2.2.2.

3.2.2.1 Stem Failure

Maximum resistive bending moment of tree

Based on Moore (2000) and Peltola et al. (2000), the theoretical maximum resistive bending moment for stem failure can be calculated as follows:

$$BM_T = \pi \times MOR \times DBH^3 / 32$$

where BM_T = theoretical maximum resistive bending moment (MNm)
 MOR = modulus of rupture of tree stem (MPa)
 DBH = diameter at breast height (m)

Based on Lei et al. (2005) and Wang et al. (2005), the modulus of rupture (MOR) for the tested black spruce and young Taiwania trees ranges from 29.33 MPa to 65.48 MPa.

As the modulus of rupture of tree stem varies greatly for different trees, a literature review was carried out on the wind speed for stem failure and compared with the design wind speed.

Wind speed for tree failure

Johnson et al. (1982) summarized the calculated and recorded wind speeds at stem failure of several loblolly pines in the area of Mobile County, Alabama. From the table, the failure wind speeds ranged from 75 to 129 mph with diameter of tree bole ranging from 0.8 to 1.1 feet, i.e. the failure wind speeds ranged from 34 m/s to 58 m/s with diameter of tree bole ranging from 0.24 m to 0.34 m (1 mph = 1.61 km/h, 1 ft = 0.305 m).

Height and Crown Spread of Chinese Banyan

According to Jim (1988), Chinese Banyan trees growing healthily on the ground “can reach a final dimension of 30m height, and a rounded-spreading crown 1½ times wider than tall in uncluttered environments.” On a stone retaining wall, the biological potential dimensions (BPD, see Section 3.2) cannot be attained. Based on empirical assessment, the maximum height of Chinese Banyan on wall is 20 m.

Design wind speed

A wall tree generally cannot reach a final dimension of 30 m high. Therefore, only the design wind speed of height up to 30 m above site-ground level are considered in this report. Based on BD (2004b) (hereinafter referred to as “Explanatory Material to The Wind Code”), the corresponding gust velocities for trees with heights ranging from ≤ 5 m - 30 m are summarized in the following table:

Table 5 - Design Wind Speed

Tree Height	Design Wind Speed (m/s)
≤ 5 m	55.1
10 m	57.9
20 m	61.0
30 m	62.8

Conclusion

Based on Johnson et al. (1982), the wind speed for stem failure ranged from 34 m/s to 58 m/s. The design wind speed adopted in Hong Kong ranged from 55.1 m/s to 62.8 m/s for trees of up to 30 m high. These values are close to the maximum failure wind speed in the literature (58 m/s). Therefore, the maximum resistive bending moment for stem failure is generally in the same order as the moment that can be induced by design wind load.

3.2.2.2 Uprooting

Based on the literature review, uprooting is more prevalent than stem failure for ground-growing trees (more than 70% of the tested trees in Moore (2000), Peltola et al. (2000) and Cucchi et al. (2004) failed by uprooting). The maximum resistive bending moments under uprooting are related to the root architecture, root depth, root plates, soil type, etc, which vary from place to place and from tree to tree. This makes the maximum resistive bending moments under uprooting very difficult to estimate reliably.



Figure 12 - Wall Tree with Weak Anchorage between Roots and Wall



Figure 13 - Wall Tree with Strong Anchorage between Roots and Wall

For wall trees, it is likely that uprooting is also more common as compared with stem failure. In Section 3.1.3, records of more than 2600 retaining walls were checked and past instability between 1984 and 2005 were found on more than 55 features. Only three of the records were related to masonry wall with trees. Two incidents (Feature Nos.

11SW A/FR24 and 11SW-A/R120) involved or might have involved localized failures of masonry blocks caused by wall tree failures. The third incident (Feature No. 11SW-B/R735) involved failure of a wall tree only and the masonry wall itself was not damaged. In these three incidents, all the wall trees failed probably at the root anchorage and caused little or no damage to the walls. Therefore, in these three cases, the maximum resistive bending moments under uprooting limited the wind load that could be transmitted to the walls.

Conclusion

Uprooting may be more common than stem failure in wall tree failure for commonly encountered wall trees in Hong Kong. However, owing to the limited number of records (only three incidents related to masonry walls with trees), it cannot be concluded that all wall trees will fail in uprooting before transferring significant wind load to the wall. If the root anchorage is strong enough to prevent uprooting, the wind load will be transferred to the stems and the walls. In the assessment of the stability of masonry walls with trees, professional judgement should be exercised regarding whether the root anchorage is strong enough to sustain the design wind forces. If not, the wind forces on wall trees could be ignored as far as the consequential effect on masonry walls is concerned.

3.2.2.3 Static Effect

Based on literature review, classical formula was commonly used to determine wind load induced on a tree (Mayhead (1973); Johnson et al. (1982); Stathers et al. (1994); Spatz & Bruechert (2000); Rudnicki et al. (2004)). Therefore, the classical formula was adopted in this report.

Using the classical formula, the wind force in the direction of wind flow on an object placed in a steady airstream is calculated as:

$$\begin{aligned} F &= 1/2 \rho C_D A V^2 \\ &= C_D A q_z \dots \dots \dots \text{eq.1} \end{aligned}$$

where F = the wind force (newtons, N)
 ρ = the density of air (kg/m^3)
 C_D = the drag coefficient (dimensionless)
 A = the frontal area (m^2)
 V = the wind velocity (m/s)
 q_z = basic wind pressure at height z (N/m^2) = $(1/2\rho V^2)$

Discussion on basic wind pressure (q_z), drag coefficient (C_D) and frontal area (A) is provided in Sections 3.2.2.1, 3.2.2.2 and 3.2.2.3 respectively.

3.2.2.4 Basic Wind Pressure

The pressures extracted from BD (2004a), (hereinafter referred to as “Wind Code”) are listed in the following table:

Table 6 - Design Wind Pressure Extracted from the Wind Code

Height above Site-ground Level	Design Wind Pressure (kPa)
≤ 5 m	1.82
10 m	2.01
20 m	2.23
30 m	2.37

For assessing wind loads on trees, the site-ground level should be taken as the level at which the most adverse effect would be caused to the stability of the wall. Where topography is considered significant, topography factor should be determined based on the Wind Code.

3.2.2.5 Drag Coefficient

In order to determine the drag coefficient, a literature review was carried out. Based on the literature review, the drag coefficients have been found to depend on the porosity of tree crown, degree of permeability for air movements and flexibility of tree crown and these parameters vary considerably between tree species. Drag coefficients used in some literature were summarized. In order to determine the suitable drag coefficients for wall trees in Hong Kong, testing wind speed and tree species used in literature were studied.

Porosity and Permeability of Tree Crown

Porosity and permeability of tree crown would affect the drag coefficient. Spatz & Bruechert (2000) stated that “since the secondary branches never fully overlap and the actual silhouette is not that of a solid cone, some degree of permeability of the crown for air movements has to be taken into account” for the drag coefficient.

Flexibility of Tree Crown

Based on the following literature, the drag coefficient was found to decrease when wind speed increases. As tree crowns are flexible, they tend to bend and become more streamlined when wind speed increases. The frontal area will thus decrease. As a fixed frontal area is assumed in calculating critical wind speeds, the drag coefficient will thus decrease to take into account of streamlining effect. However, the rate of reduction in drag coefficient is low for high wind speeds.

Johnson et al. (1982) stated that “Result of Mayhead’s 1973 research ‘indicated a reduction of the drag coefficient with increased windspeed and a large variation in drag coefficients both between and within a species’ ”.

Rudnicki et al. (2004) stated that “As wind force increases, branches and foliage move into alignment with the wind direction, reducing the crown frontal area (streamlining) and therefore the pressure component of drag. Thus, streamlining depends on the mechanical and aerodynamic properties of stems, branches, and foliage. A number of authors have used eq.1 for calculating critical wind speeds assuming a fixed frontal area, ...” and “with the assumption that 26 m/s is close to the critical wind speed for tree failure and that the rate of reduction in drag coefficient with increasing wind speed is low for wind speeds above 26 m/s”.

Stathers et al. (1994) stated that when “wind speed increases, the canopy tends to bend and deflect and become more streamlined”.

Tree Trunk

Based on the following literature, tree trunks, different from crowns, are not porous and relatively not flexible. Therefore, no reduction in drag is considered and the drag coefficient is assumed to approximate those of a smooth cylinder (1.2).

Johnson et al. (1982) stated that “Wind pressure coefficients for the bole will be assumed to approximate those of a thin smooth cylinder (1.2) even though the bark roughness and high windspeeds would both increase these coefficients (Note, wind forces on the bole are minor relative to those on the canopy).”

Spatz & Bruechert (2000) stated that “Calculating the wind loads on the trunk followed essentially the same route except that the reduction of drag due to the flexibility of the top parts of the crown were found small and were therefore not explicitly taken into account”.

Drag Coefficient from Literature Review

A number of researchers have conducted studies on tree drag. The following tables summarized drag coefficient of tree trunk and tree crown in literature:

Table 7 - Drag Coefficient of Trunk Suggested in Literature

Literature	C_D
Sun et al. (2003)	1.2
Johnson et al. (1982)	1.2

Table 8 - Drag Coefficient of Tree Crown Obtained from Wind Tunnel Test in Literature

Literature	Tree Species	Wind Speed	C _D
Johnson et al. (1982)	Dwarf white pines (松) (dwarf conifers) (assumed for high solidities)	High	0.5 (average)
	Cryptomeria (杉) (dwarf conifers) (assumed for low solidities)	High	0.3
Mayhead (1973)	Lodgepole pine (松)	30 m/s	0.20
	Western hemlock (鐵杉)	30 m/s	0.14
	Lodgepole pine (松)	26 m/s	0.35
Rudnicki et al. (2004)	Redcedar (紅側柏)	20 m/s	0.22
	Lodgepole pine (松)	20 m/s	0.47
	Hemlock (鐵杉)	20 m/s	0.47 ¹
Spatz & Bruechert (2000)	Norway spruce tree (雲杉)	Very low	0.5 ²
Stathers et al. (1994)	Engelmann spruce (雲杉) & subalpine fir (冷杉) (stiff branches and needles)	25 m/s	0.5
		10 m/s	0.8
	Lodgepole pine (松) & Douglas-fir (冷杉) (more flexible branches)	25 m/s	0.3
		10 m/s	0.6
	Western hemlock (鐵杉) (very spindly branches and crowns)	25 m/s	0.2
		10 m/s	0.3
Notes: (1) ¹ 0.4 was recommended in the literature. (2) ² recommended value only, not from wind tunnel test.			

Drag coefficients for tree crown showed in Table 8 were obtained from wind tunnel tests using artificial trees or real trees as the testing samples. Therefore, the porosity of tree crowns, degree of permeability of the crown for air movements has been already taken into account in determining drag coefficient.

Testing Wind Speed

Based on the literature review, the rate of reduction in drag coefficient is low for high wind speeds and the design wind speed during analysis is close to the wind speed for tree failure, the drag coefficient at high wind speed should be considered. Based on critical wind speed (26 m/s) mentioned by Rudnicki et al. (2004), only those drag coefficients in Table 8 with testing wind speed above 26 m/s were considered and the maximum value was found to be 0.5.

Tree Species

All the testing samples in the above literature were conifers. However, the wall tree species found in Hong Kong are not conifers (See Section 2.1.1).

As wind load on wall trees partially depends on the density of tree crown. Leaf area index (LAI), a measurement for plant density and growth, was compared to review the drag coefficient.

Leaf area index (LAI)

Leaf area index (LAI) is the total of single-side leaf surface area in relation to the projection of the crown area onto the ground. It is a measurement of foliage density and growth.

Among the 30 wall tree species in Hong Kong, *Ficus microcarpa* (Chinese Banyan) has the highest leaf area index (LAI), although several species have values close to it, such as *Ficus superba* (Superb Fig) and *Celtis sinensis* (Chinese Hackberry). The dominant wall tree species, Chinese Banyan, is therefore taken as the maximum-value scenario in the calculation of wind load. Drag coefficient of wall trees is thus based on Chinese Banyan trees.

A healthy conifer tree may have an average LAI of around 5:1. The LAI for the optimal case of Chinese Banyan is 8:1. However, this value is for trees growing healthily on the ground, with little obstacle to the spread of its roots and crown. In this report, the trees studied are growing on stone retaining walls. The highly restrictive environment for root penetration and extension, and the stresses on stem (trunk, branches, foliage) development, would curtail growth quite substantially. The LAI could be reduced to about 5:1 for trees on the least stressful wall sites. On the most stressful sites it could be suppressed further. Therefore LAI for wall trees in Hong Kong is similar to that of the species tested.

Recommendation

For tree trunk, as only 1.2 was suggested in the reviewed literature, a drag coefficient of 1.2 is recommended for the tree trunk.

Since no study on the drag coefficient of Chinese Banyan could be found and the LAI is similar for the species in Table 8 and Chinese Banyan trees growing on masonry walls, a drag coefficient of 0.5 is recommended for the tree crown.

3.2.2.6 Frontal Area

The frontal area of tree crown is usually difficult to be determined on site. For simplicity, the frontal area of crown for wall trees in Hong Kong may be assumed to be elliptical in shape.



Figure 14 - Frontal Area of the Crown of Wall Trees in Hong Kong is Similar to an Ellipse

3.2.2.7 Dynamic Effects

The dynamic effects due to resonant motion of tree should also be considered during stability analysis. Reference can be made to the Wind Code.

According to the Wind Code, the wind force allowing for dynamic effect is given by:

$$F = G \sum C_D \bar{q}_z A_z$$

where

- F = the wind force (kN)
- G = the dynamic magnification factor
- C_D = the drag coefficient (dimensionless)
- \bar{q}_z = design hourly mean wind pressure at height z (kPa)
- A_z = the frontal area of that part corresponding to \bar{q}_z (m²)

The derivations of the above parameters are described below:

Drag Coefficient, C_D

The drag coefficient would be the same for the case of static response, that is, $C_D = 1.2$ for tree trunk and $C_D = 0.5$ for tree crown are recommended.

Frontal Area, A_z

The frontal area, A_z , would be the same for the case of static response, as described in Section 3.2.2.3.

Design Hourly Mean Wind Pressure, \bar{q}_z

The design hourly mean wind pressures, \bar{q}_z , is stipulated in the Wind Code and are extracted below:

Table 9 - Design Hourly Wind Pressure Extracted from the Wind Code

Height above Site-ground Level	Design Wind Pressure (kPa)
≤ 5 m	0.77
10 m	0.90
20 m	1.05
30 m	1.15

Dynamic Magnification Factor, G

The dynamic magnification factor, G, is a function of the turbulence intensity and hourly mean velocity at the roof level, the height and breadth of the building, the natural frequency and damping ratio of the fundamental mode of vibration and the other descriptors of the wind energy parameters. Appendix F of the Wind Code provides the equation for calculating the dynamic magnification factor.

Most of the parameters mentioned above are not dependent on the properties of the structure and therefore would equally apply to the estimation of dynamic magnification factor for trees. The parameters that are related to the structural properties are the natural frequency and damping ratio of the structure. Since the Wind Code has not covered the structural properties of trees, literature review has been conducted and recommendations are given below:

- Natural Frequency

Based on Explanatory Material to The Wind Code, the natural frequency of the structure, n_a , can be estimated from the height of the structure, h, by using the an empirical expression: $n_a = 46/h$. However, this empirical expression is not applicable to wall trees. Based on Moore & Maguire (2003), the following equation is recommended for the determination of natural frequency of trees:

$$n_a = 0.0948 + 3.4317 \text{ DBH} / H^2$$

where DBH = diameter at breast height (cm) (See Section 3.2.1.1)
 H = total tree height (m)

Based on the above, the natural frequency of a tree depends on the ratio DBH / H^2 . Therefore, a tree, which is short and has a large trunk diameter, would have a large natural frequency and give a lower dynamic magnification factor.

- Damping Ratio

The dynamic motion of a tree is attenuated by damping which acts to dissipate energy. The damping ratio, ξ , is the ratio of actual damping to critical damping (the minimum damping that will prevent or stop oscillation in the shortest amount of time). According to Explanatory Material to The Wind Code, the damping ratio includes both structural damping and aerodynamic damping.

Based on Moore & Maguire (2003), structural damping of trees is due to the friction of the root-soil connection, movement of branches and the internal friction of wood. Aerodynamic damping is an external damping due to the aerodynamic drag of the crown and also to collisions between crowns of neighbouring trees. Moore & Maguire (2003) stated that it was not usually possible to determine the amount of damping by using physical considerations because the basic energy-loss mechanisms are seldom fully understood and stated that the damping ratios were not related to tree diameter. However, it suggested that the structural damping ratio were typically less than 5%.

The Wind Code recommended 1.5% for steel structures, 2% for reinforced concrete structure and suggested that stocky buildings may have higher damping values. As wall trees are relatively short and with small height/breadth ratio compared with normal structure, a damping ratio of 2% is considered to be acceptable for wall trees.

3.2.2.8 Recommendation

In the assessment of stability of retaining wall with trees, professional judgement should be exercised regarding whether the root anchorage is strong enough to sustain the design wind forces. If not, the effects of wind forces on wall trees could be ignored as far as the consequential effect on masonry walls is concerned.

In the determination of the wind forces, both static and dynamic response should be considered.

The wind force on wall trees, F , may be calculated as follows:

$$\begin{array}{ll} \text{Static response:} & F = \sum C_D q_z A_z \\ \text{Dynamic response:} & F = G \sum C_D \bar{q}_z A_z \end{array}$$

where F = the wind force (kN)
 C_D = the drag coefficient (dimensionless) (0.5 for tree crown & 1.2 for tree trunk)
 A_z = the frontal area of that part corresponding to q_z or \bar{q}_z (m^2)
 q_z = basic wind pressure at height z (kPa) (See Table 6)
 \bar{q}_z = design hourly mean wind pressure at height z (kN) (See Table 9)
 G = the dynamic magnification factor (See Section 3.2.2.4)

G should be determined based on Appendix F of the Wind Code. The damping ratio of wall trees is recommended to be 2% and the following equation is recommended to determine the natural frequency of wall trees:


$$n_a = 0.0948 + 3.4317 \text{ DBH} / H^2$$

where n_a = natural frequency
 DBH = diameter at breast height (cm) (See Section 3.2.1.1)
 H = total tree height (m)


3.2.3 Recommendation

Based on the above discussion, the effects of tree roots may be ignored and the effects of wind load and surcharge of wall trees can be calculated as follows using the final dimensions of wall trees:

Elevation of Wall Tree



Section of Wall Tree



Calculation of Surcharge of Wall Tree

Total dry biomass of wall tree, $b_m = \text{Exp} (-2.0127 + 2.4342 \ln DBH)$

$\text{Ratio}_{(\text{foliage})} = \text{Exp} (-4.0813 + 5.8816 / DBH)$

$\text{Ratio}_{(\text{stem bark})} = \text{Exp} (-2.0129 - 1.6805 / DBH)$

$\text{Ratio}_{(\text{stem wood})} = \text{Exp} (-0.3065 - 5.4240 / DBH)$

$\text{Ratio}_{(\text{branch})} = 1 - \text{Ratio}_{(\text{foliage})} - \text{Ratio}_{(\text{stem bark})} - \text{Ratio}_{(\text{stem wood})}$

$\text{Ratio}_{(\text{crown})} = \text{Ratio}_{(\text{foliage})} + \text{Ratio}_{(\text{branch})}$

$\text{Ratio}_{(\text{trunk})} = \text{Ratio}_{(\text{stem bark})} + \text{Ratio}_{(\text{stem wood})}$

where DBH = Diameter at breast height (measured at 1.3 m above the trunk base)

Surcharge of tree crown on wall per m width, $F_{SC} = b_m \times \text{Ratio}_{(\text{crown})} / s$

Surcharge of tree trunk on wall per m width, $F_{ST} = b_m \times \text{Ratio}_{(\text{trunk})} \times 1.5 / s$

where b_R = root spread (extent of roots that hold firmly on wall face)

$b_{45} = 45^\circ$ spreading from trunk base to wall toe

B = base width of wall

s = spread of loading = greater of $[(b_R + 2B) \text{ or } b_{45}]$

Overturning moment cause by surcharge of tree = $F_{SC} \times L_{SC} + F_{ST} \times L_{ST}$

where L_{SC} = Lever arm of surcharge of tree crown against overturning

L_{ST} = Lever arm of surcharge of tree trunk against overturning

Calculation of Wind Force (if required)

Force on crown per m width, $F_{WC} = 0.5 \times (\sum A_C q_Z) / s$

Force on trunk per m width, $F_{WT} = 1.2 \times (\sum A_T q_Z) / s$

or

Force on crown per m width, $F_{WC} = 0.5 G \times (\sum A_C \bar{q}_Z) / s$

Force on trunk per m width, $F_{WT} = 1.2 G \times (\sum A_T \bar{q}_Z) / s$

whichever F_{WC} and F_{WT} are the greater

where q_Z = Design wind pressures at height z (Table 6)

\bar{q}_Z = design hourly mean wind pressure at height z (See Table 9)

G = the dynamic magnification factor (See Section 3.2.2.4)

A_C = Area of crown frontal area

A_T = Area of trunk frontal area

Overturning moment caused by wind force on tree = $F_{WC} \times L_{WC} + F_{WT} \times L_{WT}$

where L_{WC} = Lever arm of wind load on tree crown against overturning

L_{WT} = Lever arm of wind load on tree trunk against overturning

4. EXAMPLES OF UPGRADING WORKS

When a masonry wall is found to have an inadequate factor of safety, upgrading works should be carried out. Information search was carried out on examples of upgrading works on masonry retaining walls on the following aspects:

- (i) preservation of existing trees on the walls; and
- (ii) preservation of the existing masonry pattern (or façade).

4.1 Search for Examples of Upgrading Works

Letters were sent to professors of some universities in UK, Australia and Italy. However, they did not have any experiences on upgrading the stability of masonry retaining wall by preserving the existing facing and any trees growing on it.

In order to review the existing methods on upgrading masonry walls in Hong Kong, records were collected from the following organisations:

- (i) LPM Division 2, Geotechnical Engineering Office (GEO);
- (ii) CMWAL;
- (iii) other consultants; and
- (iv) Architectural Services Department (ArchSD).

LPM Division 2, Geotechnical Engineering Office (GEO)

A list of project related to the study on masonry wall carried out by LPM Division 2, GEO was received in Dec 2004. (See Appendix D, Page D1) There were 10 features in the list. Two of them were not related to this study. One of them contained a masonry wall of 1.83 m high only and the upgrading works were carried out on the slope above the wall. Upgrading works of four of the features were not completed yet. The remaining three examples on upgrading of masonry walls preserved the existing trees.

CMWAL

Past upgrading works on masonry walls carried out by CMWAL were reviewed. Four examples were found on upgrading of masonry walls with masonry pattern retained. One example was found on both cases with masonry pattern partially retained and with existing trees preserved. No examples on upgrading masonry walls with both masonry pattern retained and existing trees preserved were found.

Other Consultants

Letters were sent to 30 consultants by GEO in Dec 2004 requesting for records of methods on upgrading masonry walls with existing masonry pattern retained and/or existing trees preserved. Out of these 30 consultants, eight consultants replied and five of them provided relevant records. Three examples were found on both cases with masonry pattern retained and partially retained. One example on upgrading masonry walls with both masonry pattern partially retained and existing trees preserved was found. A summary of the replies from the consultants is included in Appendix D, Page D2.

Architectural Services Department

During the meeting for special task in 14 Dec 2004 between GEO and CMWAL, an example of upgrading of masonry wall with existing trees preserved was provided by GEO. Relevant records were collected in Architectural Services Department (ArchSD).

4.2 Preservation of the Existing Masonry Pattern (or Façade)

Past methods of upgrading masonry works with existing masonry pattern retained were mainly using hand-dug caissons, mass concrete backfill and soil nails.

Installation of soil nails normally retained the existing masonry pattern partially. Soil nail heads were noted in all of the examples except Feature No. 11SW-A/R1086. Soil nail heads were hidden behind the masonry blocks in Feature No. 11SW-A/R1086. However, some grout was noted on the wall face.

The method using mass concrete backfill is similar to that using caissons. The main differences are that caissons are circular in plan and concrete rings are used during excavation. It appears that caissons are better in preserving trees because of less contact area to the back of walls.



Figure 15 - Feature No. 11SW-A/R1086 before and after Upgrading Works Using Soil Nails

4.3 Preservation of Existing Trees on the Walls

Past methods of upgrading masonry walls with trees preserved mainly used soil nails or dowel bars together with skin walls with recesses or planters. Feature No. 11SW-C/R38 was upgraded by constructing a mass concrete wall. Feature No. 11SW-A/R346 was upgraded by installation of soil nails only.

Except Feature No. 11SW-A/R346, all the masonry wall facings could not be preserved in these examples. For Feature No. 11SW-A/R346, concrete beams tying up some of the soil nail heads were noted on the wall facing.

The works were carried out one to three years ago. As the trees can usually survive for several years after severe damage, the actual effect of these upgrading works on wall trees cannot be determined as yet.



Figure 16 - Feature No. 11SW-C/R476 Upgraded Using Soil Nails, L-shaped Wall and Planter



Figure 17 - Feature No. 11SW-C/R38 Upgraded Using Mass Concrete Wall and Finished with the Old Granite Blocks



Figure 18 - Feature No. 11SW-A/R346 Upgraded Using Soil Nails

The past examples on methods of upgrading masonry walls are summarized in the following table:

Table 10 - Past Example of Upgrading Works on Masonry Walls with or without Trees Growing on Them (Sheet 1 of 2)

Feature No.	Location	Upgrading Method	Tree Preserved	Wall Facing Preserved	Year of Completion	Designed by	Remark
11SW-A/R22	Fuk On Lane	Soil nails and skin wall	Y	N	2004	GEO	Recesses were provided to protect and preserve the trees.
11SW-C/CR120	Pokfulam Training Centre Complex, Wah Fu, HK Island	Skin wall	Y	N	2004	GEO	Tree preserved by tree rings.
11SW-C/R38	Bethanie, 139 Pokfulam Road	mass concrete wall	Y	N	2003	GEO	Existing masonry wall was removed and a new reinforced concrete wall with a green face was constructed. The exposed surface of the new wall would be finished with the salvaged old granite blocks.
11NW-D/R50 (part)	No. 6 Knutsford Terrace	Caisson	NA	Y	1997	CMW	Active pressure assumed to be taken by the caisson only.
11SW-A/R147	No.2-4B Ying Fai Terrace	Caisson	NA	Y	1999	CMW	Existing wall thickened by caissons.
11SW-A/R634 (part)	No. 109-109B Robinson Road	Caisson	NA	Y	1993	CMW	Existing wall thickened by caissons.
11SW-A/R679	Piccadilly Mansion, Nos. 4-6A, Po Shan Road, Hong Kong	Mass concrete backfill	NA	Y	2003	CMW	
11SW-A/R1086	250 m North West from No. 63 Victoria Road HK	Soil nails	NA	Y	2004	CMW	Soil nail heads hidden behind the masonry wall facing.
11SW-C/R476	The University of Hong Kong, 5-7 Sassoon Road	Soil nails, L-shaped wall and planter	Y	N	2003	CMW	
11SW-A/R298	Merry Terrace, 4A-4P, Seymour Road	Soil nails, skin wall and planter	Y	N	2001	BBV	
11SW-A/R109	North-west of Merry Terrace, Sheung Wan	Dowel bars and skin wall	Y	N	1998	BCL	Recesses were provided to protect and preserve the trees. Granite facing constructed at the wall facing.

Table 10 - Past Example of Upgrading Works on Masonry Walls with or without Trees Growing on Them (Sheet 2 of 2)

Feature No.	Location	Upgrading Method	Tree Preserved	Wall Facing Preserved	Year of Completion	Designed by	Remark
11SW-A/R346	North of Pok Fu Lam Service Reservoir, along Pok Fu Lam Road	Soil nails	Y	P	2003	Fugro	Architectural pattern made by concrete beam tying up part of soil nail heads were constructed on the wall surface.
11SW-A/R374	No. 101 Robinson Road, Hong Kong Lot No. I.L.719 s.C.R.P.	Soil nails	NA	P	2003	James Lau	Continuous concrete beams tying up soil nail heads were constructed.
11SW-A/R802	Masonry Wall Portion, La Clare Mansion, No. 92 Pokfulam Road, Hong Kong	Soil nails	NA	P	2003	James Lau	Some masonry blocks removed and replaced by soil nail head.
11SW-B/R548 (Portion)	No. 15 Bowen Road, Hong Kong	Soil nails	NA	P	2003	James Lau	Continuous concrete beams tying up soil nail heads were constructed.
11SW-A/R563	65A & 65B Bonham Road and 2 Hing Hong Road	Soil nails and skin wall	Y	N	2004	Scott Wilson	Soil nails were offset from tree root locations. The skin wall was span across. Random pattern stone facing finish were constructed at the wall facing.
11SW-A/R466, R467, R469, R470. R471, R472	King George V Memorial Garden	Soil nails and RC skin wall	Y	N	1996	ASD	Dressed block facing constructed on RC skin wall.
Legend:							
BCL	Binnie Consultants Limited				Y	Yes	
BBV	Binnie Black & Veatch Hong Kong Limited				N	No	
CMW	C M Wong & Associates Ltd.				P	Partial	
Fugro	Fugro (Hong Kong) Limited				NA	Not Applicable	
James Lau	James Lau & Associates Ltd.						
Scott Wilson	Scott Wilson (Hong Kong) Ltd.						
GEO	Geotechnical Engineering Office						
ASD	Architectural Service Department						

5. PROPOSED METHODS OF UPGRADING MASONRY WALLS

Various geotechnical methods could be used to stabilize masonry retaining walls. There is a need to preserve the integrity of the stone façade and the wall trees, especially for walls with high heritage value and wall trees of high amenity and landscape value. In this study, the following aspects were taken into account in reviewing the methods of upgrading masonry walls:

- (i) preservation of existing trees on the walls; and
- (ii) preservation of the existing masonry pattern (or façade).

Based on the examples in Section 4, methods on upgrading masonry walls with trees using soil nails and caissons may preserve both existing trees and existing masonry pattern. The method using buttresses is also recommended.

5.1 Soil Nails

Soil nail consists of a tensile reinforcing element (usually steel bar) and grout. It is constructed by drilling into the slope or wall followed by the installation of tensile reinforcing element and grouting. In order to upgrade masonry walls, soil nails are installed on the facing of the walls.



Masonry pattern can be retained using soil nails. However, soil nail heads are usually seen on masonry wall faces. If masonry blocks are temporarily removable, soil nail heads can be hidden behind masonry blocks. No soil nails will be seen on facing, but special measures should be carried out to ensure the original pointing retained.


Wall trees are usually adversely affected by grout which leaks out to the surrounding soil during the installation of soil nails. The threats of grout to tree growth are as follows:

- (i) the chemical damage to roots due to high alkalinity;
- (ii) the disruption in the balance of nutrient supply due to the decreased solubility of some trace elements leading to nutrient deficiency symptoms; and
- (iii) the physical filling of soil pores thus reducing the ability of the soil to drain excess water and to store plant-available water.

However, wall trees are usually located within the free length of soil nails designed, as

they are located close to the wall faces. Therefore, left-in casing could be used within the free length of soil nails to seal-off the grout and reduce the threats.

Behind masonry walls, there should be enough area within boundary for the construction of soil nails.



5.2 Buttresses

5.2.1 Conventional Buttresses

Buttress is a structure, usually brick, stone or concrete, built against a wall for support or reinforcement. In order to upgrade masonry walls with trees, buttresses are built with spacing adjusted to minimize impacts on wall trees.

Since buttresses are built in front of walls, soil and tree roots behind the walls are not disturbed or damaged. The bulk of the masonry wall facing can be retained.

For conventional buttresses, there should be enough area in front of the walls for construction. This area will be occupied by buttresses and thus cannot be used for other purposes. The masonry facing will be slightly modified, as part of it will be blocked by the buttresses.





Figure 19 - Conventional Buttresses in the University of Hong Kong



5.2.2 Flying Buttresses

Besides conventional buttresses, flying buttresses can also be used. Flying buttresses may be in the form of as half or semi-arches. The elevated end of the arch supports the wall and the lower end of the arch is mounted on foundations, or on pillars or other flying buttresses. If necessary, beams could be built as extensions from the flying buttresses to provide additional support to the wall.

Flying buttresses have the same advantages as conventional buttresses. However, flying buttresses have fewer disadvantages than conventional buttresses.

Construction of flying buttresses requires area in front of the walls. However, as flying buttresses stand apart from masonry walls and connect to them in semi-arch shape, the area between the toe of walls and flying buttresses will not be occupied. This area can be used for other purposes (e.g. footpath). The masonry facing will still be slightly modified using flying buttresses.





Figure 20 - A Flying Buttress in the University of Hong Kong




5.3 Hand-dug Caissons

Caisson is an earth-retaining structure, or part thereof, the construction of which includes the excavation of a shaft in the ground by means of digging carried out by any person inside the shaft with or without the aid of machine tools. In order to upgrade masonry walls with trees, caissons are built behind the walls. The spacing between caissons should be adjusted as far as practicable to minimize damaging tree roots.

As caissons are built behind masonry walls, masonry pattern can thus be fully retained. Caissons are excavated by hands. The disturbance to the surrounding soil and damages to masonry blocks are small. Cutting of large tree roots could also be avoided.

According to ETWB Circular No. 09/1994, the use of hand-dug caissons requires approval from the Director of CEDD. For private project, under the jurisdiction of the Buildings Ordinance, hand-dug caisson of depth greater than 3 m would not be approved unless there is no alternative. Therefore, for caisson proposed to be more than 3 m depth, it must be demonstrated that there is no other practical alternative in preserving the masonry facing and the trees thereon.

Caisson proposal is not effective to upgrade walls with large wall trees having an extensive spread of roots, as the spacing between caissons cannot be too large. Area should also be available behind the walls for the construction of caissons.



The following table summarized the comparisons between the above methods:

Table 11 - Advantages and Disadvantages / Limitations of Upgrading Methods on Masonry Walls with Tree

Method	Advantages	Disadvantages / Limitations
Soil Nail	1. Masonry pattern largely retained.	1. To reduce potential adverse effect on wall trees due to grouting, left-in casing need to be provided. 2. Masonry wall facings slightly modified. 3. Boundary constraint behind walls.
Conventional buttress	1. Soil and tree roots behind walls are not disturbed or damaged. 2. Masonry pattern largely retained.	1. Masonry wall facings slightly modified. 2. Area in front of walls required. 3. Area occupied by buttresses cannot be used for other purposes.
Flying buttress	1. Soil and tree roots behind walls are not disturbed or damaged. 2. Masonry pattern largely retained.	1. Masonry wall facings slightly modified. 2. Area in front of walls required.
Caisson	1. Masonry pattern can be fully retained. 2. Damage to masonry block and large tree roots and disturbance to surrounding soil are small. 3. No leakage of grout to soil.	1. Spacing between caissons cannot be too large. 2. Special approval from relevant authority required. 3. Boundary constraint behind walls.

5.4 Recommendation

In conclusion, in order to upgrade masonry walls with trees preserved and masonry pattern retained, installation of soil nails, construction of conventional buttresses, flying buttresses and caissons are recommended and the selection of upgrading method to be used should be based on the actual site conditions.

6. SPECIAL MEASURES ON UPGRADING MASONRY WALLS WITH TREES

For the walls designated for special protection, specific precautionary measures could be adopted in the course of upgrading works and wall maintenance to ensure that the wall façade is not unduly modified, and the wall trees are not damaged.

The guiding principles are discussed in Section 6.1. Details of the preservation

principles are discussed in Sections 6.2 - 6.4. The pertinent issues and their recommended precautionary measures for the proposed upgrading methods are included in Appendix E.

6.1 Guiding Principles

It is pertinent to protect not only the visible tree parts, namely the stems and wall-surface roots, but also the hidden tree roots that have grown into the soil situated behind the wall and below the ground at the wall base. The overarching principles of wall protection in relation to stabilization works are:

- (i) The integrity and appearance of the stone façade, including the masonry blocks and associated mortar and pointing, are preserved.
- (ii) The tree stems (branches and foliage) and roots, including aerial roots, on the wall face are not unduly damaged.
- (iii) The tree roots that have penetrated into the soil behind the stone wall are not unduly damaged.
- (iv) The tree roots that have entered the soil situated on the slope adjacent to the top of the wall are not unduly damaged.
- (v) The tree roots that have penetrated into the soil below the ground at or near the wall base are not unduly damaged.
- (vi) The stabilized wall will continue to support the growth of existing trees.

Details of the preservation of existing masonry pattern (or façade), the protection of tree roots from damage and the continued growth of existing trees are discussed in the following sections.

6.2 Preserving the Existing Masonry Pattern (or Façade)

Walls to be preserved should have their façade kept intact and the pointing should not be modified. Any cement mix used in re-pointing, if deemed absolutely necessary, should match as far as possible the original material in terms of composition, colour and workmanship. Dry walls should remain undisturbed, and their joints should not be filled with mortar. Walls without original pointing should not be given new pointing, or above all they should not have the joints buttered over by cement. Any stones that need to be temporarily removed for soil nailing work and other maintenance tasks should be very carefully extracted so as not to damage them, and they should be replaced with due respect to the full restoration of the façade appearance. The use of plaster to emulate the stone in covering up the soil-nail opening should not be accepted. To ensure full restoration of the façade, photographs of the façade can be taken, and number or reference can be marked on every masonry stones before their removal for any works.

6.3 Protecting Tree Roots and Stems From Damage

6.3.1 Importance of Protecting Tree Roots from Damage

Trees have developed through evolution two different strategies to support its aboveground masses and to react to mechanical forces that may disturb its balance and stability. Mechanical stresses on trees could be imposed by wind or tilting (gravity). Coniferous trees develop new compression wood on the downwind or falling side to support or push up the tree against failure. On the contrary, broadleaf trees react by developing new tension wood on the upwind or opposite side to pull up the tree against failure. Whether pushing (compression) or pulling (tension), the effect is an attempt to correct the imbalance by shifting the tree towards the upright or equilibrium position.

Banyan is a broadleaf tree that adopts the pulling or tension wood strategy. A wall tree has an inherently unstable perch. Its stem attempts to grow largely vertically upwards in response to negative geotropism. In doing so, it must develop adequate anchorage to support itself against gravity pull. Additional reserve strength must be made available to cater to the exigencies of the

Perch

A perch is a branch that serves as a resting place for birds, or an attachment surface for epiphytes (plants that grow on the surface of other plants).

pressure imposed by strong wind. The trunk and roots of a wall tree would have to develop tension wood to pull the tree weight like ropes to counteract the force of collapse. The larger the root, the more role it plays in securing the tree on the vertical habitat. Any attempt to damage or cut the roots, especially the main roots, may bring serious consequences on tree stability. The weakened tree may collapse without warning on pedestrians, vehicles or properties. It will induce the formation of hazard trees in our compact city, and substantially trim the life span and ecological value of the damaged tree. Some examples of root severance of wall trees in recent years had resulted in loss of poise and tree collapse.

6.3.2 Tree Root Pruning

Where stones are shifted at the wall ends to such an extent that a potential hazard of stone fall or wall destabilization may be induced, only the specific roots in question could be pruned to stop the displacement. Detailed field assessment could judge whether appropriate management intervention is necessary to abate the hazard. There is little field evidence to support the need for pre-emptive pruning of tree roots to prevent stone displacement. Where root pruning is found necessary, an overall evaluation of wall-tree relationship is recommended to judge the extent position and method of root pruning. The cardinal principle is to minimize the amount of root removal so as to forestall tree decline and possible tree destabilization.

The following general principles of pruning the roots of wall trees are recommended:

- (i) Prune only if it is absolutely necessary, that is to prune only if non-action will permit the wall instability problem to aggravate such that it may degenerate into a hazard;
- (ii) Root pruning should bear in mind that it could destabilize the tree and hence in solving one “perceived” problem,

another problem (hazard) and a long-term management worry and burden could be generated; and

- (iii) Prune the minimal amount of roots that is sufficient to alleviate the wall instability hazard, and take care not to remove roots unnecessarily.

Concerning the specifics, the actual location, amount and method of root removal have to rely on expert judgment in the field, to be assessed on an individual-tree basis.

6.3.3 Trimming of Branches, Leaves or Roots of Wall Trees

Trimming a tree's foliage and branches could reduce its capability to produce food and hence weaken the tree and make it susceptible to attack by pests and pathogens. Therefore, wall trees should only be pruned if it is absolutely necessary. When the following conditions are found, pruning may be found necessary:

- (i) there is unequivocal evidence that they have damaged a wall by displacing masonry blocks;
- (ii) they have a very high probability of destabilizing wall;
- (iii) they obstruct vehicular traffic; and
- (iv) they have been weakened by wind, pest or pathogens and as a result have become potentially hazardous.

If pruning is found to be necessary, it should be confined to the abatement of the specific problem in question to minimize the amount of tissue removal. As different trees and different problem cases require different pruning approaches, the actual pruning extent has to be decided on the basis of individual trees in the field and the pruning should be carried out only by knowledgeable and experienced landscape contractors using clean and sharp tools. Care should be taken on the position and angle of cuts in the case of branch removal to minimize the chance of wound invasion by wood-decay fungi.

6.4 Continued Growth of Existing Trees

As it is the case for normal ground-growing trees, some roots may decline or die due to various reasons, such as disease, pest, injury, decay, drought, waterlogging, soil contamination, sealing and compaction. For a healthy tree, new roots would continually be formed to expand the root catchment and to compensate for the loss roots. Wall growth conditions must remain continually suitable for root growth in order that the wall tree can continue to thrive. Keeping joints of masonry walls unsealed, which is usually ignored, is one of the important measures for the continued growth of existing wall trees.

6.4.1 Keeping Joints Unsealed

The tendency of aerial roots of Banyans to grow into the crevices between stones is tied to their natural negative phototropism. In other words, they tend to grow away from light and into the dark joints. It is largely the presence of joints in the older generation of walls that has permitted the unique ecological phenomenon of stone wall trees to flourish in Hong Kong.

Recently, some old stone walls with trees have been too assiduously maintained, resulting in extensive sealing and even buttering over of joints with new cement mixtures. Some walls have virtually all the joints effectively sealed by cement. The sealing is so thorough that even living roots in the joints were embedded in cement. Such sealing will deprive the wall trees of a pertinent *raison d'être* for their survival. New roots will no longer be able to enter the joints to obtain sustenance in the soil lying behind the wall. Existing roots will suffer from inadequate aeration as the joints are essential in allowing the entry of air into the soil and carbon dioxide from root respiration to dissipate through the joints. Where the cement covers the existing roots, their continued growth which requires secondary thickening will be curtailed. Any root thickening would result in self-girdling damage that could lead to root decay and possible root death. The long-term effect of such overzealous wall maintenance is to suppress tree growth, induce decline and eventually leading to premature tree death.

In order to let the wall growth conditions continually suitable for root growth, any unsealed joints of masonry walls should be kept unsealed. For deteriorated mortar joints, the mortar may be removed and replaced by new one and no significant alteration should be made on the wall condition.

The pertinent issues and their recommended precautionary measures for the proposed upgrading methods are included in Appendix E.

6.5 Conclusion

In conclusion, any measure that could impose injuries or harms on trees should be reviewed and modified to make them tree friendly. Contractors should be coached about the reasons for adopting the new wall maintenance techniques, and their performance should be monitored to prevent overzealous work. Significant historical walls and trees should receive special attention, and any maintenance work should be custom-designed based on scientific and filed study of the real-world situation.

7. SAFETY STANDARD FOR CHECKING MASONRY RETAINING WALLS WITH TREES

Based on the above study, stability of masonry walls with trees can be assessed and the existing and upgraded conditions of the walls should be checked against safety standards. GEO (1984) (hereinafter referred to as “Geotechnical Manual for Slopes”), GEO (1982) (hereinafter referred to as “GEOGUIDE 1 (1982)”) and GEO (1993) (hereinafter referred to as “GEOGUIDE 1 (1993)”) are the current guides used in Hong Kong providing standards of

practice that should be adopted for the design, construction and maintenance of masonry walls.

In the following sections, the approaches for checking the stability of masonry walls, the current safety standards for masonry walls and the recommended safety standards for masonry walls with trees are discussed.

7.1 Approaches

There are two approaches for checking the stability of retaining walls in Hong Kong:

- (i) limit state approach; and
- (ii) factor of safety approach.

Geotechnical Manual for Slopes and GEOGUIDE 1 (1982) used factor of safety approach. The latest Geoguide, GEOGUIDE 1 (1993), recommended limit state approach. However, the geotechnical standards set out in the latest Geoguide are for new permanent earth retaining walls on land. Assessments of existing retaining walls are beyond its scope. As masonry walls with trees are existing retaining walls, the geotechnical standards set out in Geotechnical Manual for Slopes and GEOGUIDE 1 (1982) should be followed. Therefore the factor of safety approach is recommended for masonry walls with trees.

7.2 Existing Walls, New Walls and Remedial Works

Geotechnical Manual for Slopes recommended minimum values on factor of safety for the following two separate cases:

- (i) the design of a new wall where design parameters are derived from geological and geotechnical investigation; and
- (ii) the analysis of an existing wall and for the design of remedial and preventive works.

According to the Geotechnical Manual for Slopes, when analysing an existing gravity retaining wall to determine the extent of any remedial or preventive works required, the factors of safety for case (ii) may be used as long as rigorous structural, geological and geotechnical investigation are conducted (which include a thorough examination of wall maintenance history, groundwater records, rainfall records and any wall monitoring records) and the loading remain substantially the same as those of the existing wall.

In checking the stability of masonry wall with trees, if the generalized parameters in the preceding sections are adopted and without specific test being conducted, then such analysis cannot satisfy the criteria for rigorous structural investigation, not to mention whether the geological and geotechnical investigation are considered rigorous or not. Therefore, the recommended minimum factors of safety for the design of a new wall, i.e. case (i), should be used for both the stability analysis and the design of upgrading works for masonry wall with trees.

7.3 Factor of Safety for Masonry Walls

According to Geotechnical Manual for Slopes, a retaining wall can fail by sliding, by rotation or as a result of bearing capacity failure. Failure can also result from the structural failure of the wall itself particularly in the case of masonry wall. The minimum factors of safety against these failures for normal masonry walls are discussed in the following sections.

7.3.1 Structural Failure

There are major uncertainties in structural stability assessment, and it is difficult to carry out reliable calculations for walls without tie members. GEO (2003) - GEO Circular No. 33 suggested that it would be more practicable to make an engineering appraisal of the wall condition through visual inspection. According to Morgenstern & GEO (1994), slender walls, with a slenderness ratio greater than 5 are liable to fail in a brittle manner. The absence of prior warning makes the failure of slender walls particularly dangerous. Definition of a slender wall is included in GEO Circular No. 33.

7.3.2 Sliding, Overturning and Bearing Capacity

The minimum factors of safety for new walls against sliding, overturning and bearing capacity recommended by Geotechnical Manual for Slopes are summarized in the following table:

Table 12 - Recommended Factors of Safety for Masonry Retaining Walls for a Ten-year Return Period Rainfall

Mode of Failure	New Walls
Sliding	1.5
Overturning	2.0
	(For a masonry wall, the resultant force should lie within the middle-third)
Bearing	3.0

These minimum factors of safety are the same as those recommended by GEOGUIDE 1 (1982).

7.4 Recommended Factor of Safety for Walls with Trees

When checking the stability of masonry walls with trees against failures, surcharge from trees on masonry walls and wind load on trees should be considered.

Geotechnical Manual for Slopes and GEOGUIDE 1 (1982), however, did not mention

the wind effect when recommending safety standards. Reference has therefore been made to the Building (Construction) Regulations and BD (2004c) (hereinafter referred to as “Code of Practice for Foundations”) to study the minimum factor of safety if the increased in disturbing force is solely due to wind.

7.4.1 Structural Failure

As discussed in Section 3, tree roots do not have adverse effect on the structural integrity of masonry walls and it is difficult to carry out reliable stability analysis on the structural integrity. Therefore, the usual practice may be followed and an engineering appraisal of structural integrity of masonry walls with trees may be made. A detailed study on the structural stability of masonry retaining walls is available in Chan (1996).

7.4.2 Sliding, Overturning and Bearing Capacity

7.4.2.1 Sliding

Building (Construction) Regulations and Code of Practice for Foundations both recommended a minimum factor of 1.5 on sliding force due to loads with and without wind loads:

- (i) Building (Construction) Regulations stated that “the resistance to the sliding force acting thereon shall be not less than 1.5 times the sliding force due to any loads”.
- (ii) Code of Practice for Foundations stated that “the sliding resistance shall be at least 1.5 times the sliding force due to any loads.”

Therefore, the minimum factor on sliding force for masonry walls with trees is recommended to be the same as the normal one (1.5 due to wind load and other loads for the design of new wall).

7.4.2.2 Overturning

In checking the stability against overturning, Building (Construction) Regulations and Code of Practice for Foundations both recommended factors of 1.5 and 2 on overturning moment due to wind loads and loads other than wind loads respectively:

- (iii) Building (Construction) Regulations stated that “the resistance to the overturning moment acting thereon shall be not less than 1.5 times the overturning moment due to wind loads and 2 times the overturning moment due to loads other than wind loads.”
- (iv) Code of Practice for Foundations stated that “the overturning moment resistance shall be at least 1.5 times

the overturning moment due to wind loads” and “2 times the overturning moment due to loads other than wind loads and floatation, with the overturning moment resistance taken as the sum of the stabilizing moment due to the minimum dead loads plus that due to any permitted anchoring resistance.”

The above recommended factor of 2 on overturning moment due to loads other than wind loads is the same as the required factor of safety against overturning for the design of new walls as stated in Geotechnical Manual for Slopes and GEOGUIDE 1 (1982). Therefore, a factor of 1.5 is recommended on overturning moment due to wind loads for the design of new walls.

7.4.2.3 Bearing

Building (Construction) Regulations and Code of Practice for Foundations both recommended that the bearing capacity might be increased by 25% when such an increase is solely due to wind effects:

- (i) Building (Construction) Regulations stated that “the allowable capacity of foundations for bearing, bond or friction resisting the combined effects of dead, imposed and wind loads may be increased by not more than 25% where such increase is solely due to wind loads.”
- (ii) Code of Practice for Foundations stated that “the allowable capacity of the soil/rock under working loads where any foundation is founded “may be increased by 25% when such increase is solely due to wind effects.”

Based on the Building (Construction) Regulations and Code of Practice for Foundations, a factor of 2.4 ($= 3 / 1.25$) is recommended on bearing force due to combined effects of dead, imposed and wind loads for the design of new walls.

7.5 Conclusion

A retaining wall with trees can fail by structural failure, sliding, overturning and bearing failure. Surcharge from trees on masonry walls and wind loads on trees should be considered.

For structural integrity of masonry walls with trees, an engineering appraisal may be made. A detailed study on the structural stability of masonry retaining walls is available in Chan (1996).

In checking the stability of masonry walls with trees against sliding and overturning failures, factor of safety approach with local factors of safety is recommended. The total forces or moments resisting failure should not be less than the total forces or moments

causing failure with factors of safety applied. That is,

$$R \geq \gamma_1 F_{\text{loads other than wind}} + \gamma_2 F_{\text{wind load only}}$$

where R = resistance force or moment

$F_{\text{loads other than wind}}$ = forces or moments causing failure due to loads other than wind

$F_{\text{wind load only}}$ = forces or moments causing failure due to wind load only

γ_1 = factor of safety applied on $F_{\text{loads other than wind}}$ (See Table 13)

γ_2 = factor of safety applied on $F_{\text{wind load only}}$ (See Table 13)

The resistance should be taken as the sum of the stabilizing force or moment due to the minimum dead loads plus that due to any permitted anchoring resistance.

In checking the bearing, factor of safety approach with global factors of safety is recommended. That is,

$$q_c \geq \tau_1 q_{\text{loads other than wind}}$$

$$q_c \geq \tau_2 q_{\text{combined effects}}$$

where q_c = bearing capacity

$q_{\text{loads other than wind}}$ = bearing due to loads other than wind

$q_{\text{combined effects}}$ = bearing due to combined effects of dead, imposed and wind loads

τ_1 = factor of safety applied on $q_{\text{loads other than wind}}$ (See Table 14)

τ_2 = factor of safety applied on $q_{\text{combined effects}}$ (See Table 14)

Since the criteria discussed in Section 7.2 cannot be satisfied for a wall with trees, the recommended factors of safety for new walls should be adopted for the analysis of existing masonry walls and the design of upgrading works. The factors of safety applied to the loads causing failure are recommended and summarized in Tables 13 and 14.

Table 13 - The Recommended Factors of Safety Applied to Loads Causing Failure for Masonry Walls with Trees

Type of Loads	Recommended Factors of Safety	
	Loads Other Than Wind (Earth Pressure) (γ_1)	Wind Load Only (γ_2)
Sliding	1.5	1.5
Overturning	2	1.5
	(For a masonry wall, the resultant force should lie within the middle-third)	

Table 14 - The Recommended Factors of Safety for Bearing

Type of Loads	Recommended Factors of Safety	
	Loads Other Than Wind (Earth Pressure) (τ_1)	Combined Effects of Dead, Imposed and Wind Loads (τ_2)
Bearing	3	2.4

An example of stability checking of a masonry wall is included in Appendix F.

8. CONCLUSION

Tree Root Effect

In conclusion, tree roots generally have potential beneficial effect on the stability of masonry walls. Due to the possible significant variability of the potential beneficial effect and the extreme difficulty in fully characterizing the tree roots and quantifying the effects of tree roots, it may be conservatively ignored during stability analysis of masonry walls with trees. However, attention should still be paid to possible decay of large tree roots, if any, during inspections to ascertain that the strength of the soil vulnerability to water ingress is not affected, and masonry block displacement, if any, to ascertain that such displacement is not due to tree roots.

Effects of Tree Stem

Surcharge of wall trees and wind load on trees were found to have adverse effect on the stability of masonry walls and may be calculated as follows:

- Surcharge of Trees on Masonry Walls

The dry biomass of wall tree, $b_m = \text{Exp} (-2.0127 + 2.4342 \ln DBH)$

where b_m = total aboveground biomass (kg)
 DBH = diameter at breast height (cm)

The biomass ratio equation is calculated as: $\text{ratio} = \text{Exp} (\beta_0 + \beta_1 / DBH)$

where ratio = ratio of component to total aboveground biomass for trees
 β_0, β_1 = coefficients (refer to hardwood of Table 4)

The total dry biomass of tree trunk should be increased by 50% to allow for the moisture content of wall trees.

- Wind Effect on Trees and Thus on Masonry Walls

In the assessment of stability of retaining wall with trees, professional judgement should be exercised regarding whether the root anchorage is strong enough to sustain the design wind forces. If not, the effects of wind forces on wall trees could be ignored as far as the consequential effect on masonry walls is concerned.

The wind force induced on trees,

$$\begin{aligned} \text{Static response:} \quad & F = \sum C_D A_Z q_Z \\ \text{or Dynamic response:} \quad & F = G \sum C_D \bar{q}_Z A_Z \quad \text{whichever is greater} \end{aligned}$$

where F = the wind force (kN)
 C_D = the drag coefficient
= 0.5 for tree crown and 1.2 for tree trunk
 A_Z = the frontal area of that part corresponding to q_Z or \bar{q}_Z (m²)
 q_Z = design wind pressure at height z (kPa) (refer to Table 6)
 \bar{q}_Z = design hourly mean wind pressure at height z (kN) (See Table 9)
 G = the dynamic magnification factor (See Section 3.2.2.4)

Proposed Methods of Upgrading Masonry Walls

In order to upgrade masonry walls with the existing trees preserved and the existing masonry pattern retained, installation of soil nails, construction of caissons, flying buttresses or a combination of the methods are recommended for different site conditions.

Special Measures on Upgrading Masonry Walls with Trees

Special measures should be implemented during upgrading of masonry walls which deserve preservation of existing trees and existing masonry pattern. Any measures that could impose injuries or harm on trees should be reviewed and modified to make them tree-friendly. The joints between masonry blocks should not be sealed. Besides masonry blocks, pointing should not be modified.

Safety Standard for Checking Masonry Retaining Walls with Trees

A retaining wall with trees can fail by structural failure, sliding, overturning and bearing failure. Surcharge from trees on masonry walls and wind loads on trees should be considered.

For structural integrity of masonry walls with trees, an engineering appraisal may be made. A detailed study on the structural stability of masonry retaining walls is available in Chan (1996). In checking the stability of masonry walls with trees against sliding, overturning and bearing failures, the resistance should not be less than the forces or moments causing failure with factors of safety applied. The factors of safety applied to the forces or moments causing failure are recommended in Table 13. The factors of safety for bearing are recommended in Table 14.

9. REFERENCES

- AFCD (2003). Measurement of Diameter at Breast Height (DBH). Nature Conservation Practice Note No. 02/2003. Agriculture, Fisheries and Conservation Department, The Government of the Hong Kong Special Administrative Region.
- BD (2004a). Code of Practice on Wind Effects in Hong Kong 2004. Buildings Department, Hong Kong Special Administrative Region.
- BD (2004b). Explanatory Material to The Code of Practice on Wind Effects in Hong Kong 2004. Buildings Department, Hong Kong Special Administrative Region.
- BD (2004c). Code of Practice for Foundations. Buildings Department, Hong Kong Special Administrative Region.
- Building (Construction) Regulations. The Government of the Hong Kong Special Administrative Region.
- Chan, Y.C. (1996). Study of Old Masonry Retaining Walls in Hong Kong. GEO Report No. 31, Geotechnical Engineering Office, Civil Engineering Department, The Government of the Hong Kong Special Administrative Region.
- Cucchi, Veronique, Meredieu, Celine & Stokes, Alexia (2004). Root anchorage of inner and edge trees in stands of Maritime pine (*Pinus pinaster*Ait.) growing in different podzolic soil conditions. Trees, 18: 460-466.
- Gray, Donald H. & Sotir, Robbin B. (1995). Biotechnical and Soil Bioengineering Slope Stabilization: a practical guide for erosion control.
- Greenway, D.R. (1987). Vegetation and Slope Stability. Slope Stability: Geotechnical Engineering and Geomorphology. Edited by M.G. Anderson and K.S. Richards, Chichester [West Sussex]: Wiley.
- GEO (1982). Guide to Retaining Wall Design. Geoguide 1, Geotechnical Engineering Office, Civil Engineering Department, The Government of the Hong Kong Special Administrative Region.
- GEO (1984). Geotechnical Manual for Slopes (2nd Edition). Geotechnical Engineering Office, Civil Engineering Department, The Government of the Hong Kong Special Administrative Region.
- GEO (1993). Guide to Retaining Wall Design (2nd Edition). Geoguide 1, Geotechnical Engineering Office, Civil Engineering Department, The Government of the Hong Kong Special Administrative Region.
- GEO (2003). Guidelines for Assessment of Old Masonry Walls in Geotechnical Studies and for Action to be Taken on Private Walls. GEO Circular No. 33, Geotechnical Engineering Office, Civil Engineering Department, The Government of the Hong Kong Special Administrative Region.

- Jenkins, Jennifer C., Chojnacky, David C., Heath, Linda S. & Birdsey, Richard A. (2003). National-Scale Biomass Estimators for United States Tree Species. Forest Science, 49(1): 12-35.
- Jim, C.Y. (1988). Preservation of a Large Chinese Banyan on a Construction Site. Journal of Arboriculture, 14(7): 176-180.
- Jim, C.Y. (1998). Old stone walls as an ecological habitat for urban trees in Hong Kong. Landscape and Urban Planning (Amsterdam), 42(1): 29-43.
- Johnson, R.C. JR., Ramey, G.E. & O'Hagan, D. S. (1982). Wind Induced Forces on Trees. Journal of Fluids Engineering, 104: 25-30.
- Lee, Ivan W.Y. (1985). A review of vegetative slope stabilisation. HKIE Geotechnical Group paper For publication only, pp 9-21.
- Lei, Y.C., Zhang, S.Y. & Zehui Jiang (2005). Models for predicting lumber bending MOR and MOE based on tree and stand characteristics in black spruce. Wood Sci Technol, 39: 37-47.
- Mayhead, G.J. (1973). Drag Coefficients for British Forest Trees Derived from Wind Tunnel Studies. Agricultural Meteorology, 12: 123-130.
- Moore, John R. (2000). Differences in maximum resistive bending moments of *Pinus radiata* trees grown on a range of soil types. Forest Ecology and Management, 135: 63-71.
- Moore, John R. & Maguire, Douglas A. (2003). Natural sway frequencies and damping ratios of trees: concepts, review and synthesis of previous studies. Trees, 18: 195-203.
- Morgenstern, N.R. & GEO (1994). Report on the Kwun Lung Lau Landslide of 23 July 1994. GEO Report No. 103, Geotechnical Engineering Office, Civil Engineering Department, The Government of the Hong Kong Special Administrative Region.
- Peltola, Heli, Kellomaki, Seppo, Hassinen, Alpo & Granander, Markku (2000). Mechanical stability of Scots pine, Norway spruce and birch: an analysis of tree-pulling experiments in Finland. Forest Ecology and Management, 135: 143-153.
- P.G. Biddle (1998). Tree Root Damage to Buildings, Volume 1, Causes, Diagnosis and Remedy.
- Rudnicki, Mark, Mitchell, Stephen J. & Novak, Michael D. (2004). Wind tunnel measurements of crown streamlining and drag relationships for three conifer species. Canadian Journal of Forest Research, 34(3): 666-676.
- Spatz, Hanns-Christof & Bruechert, Franka (2000). Basic biomechanics of self-supporting plants: wind loads and gravitational loads on a Norway spruce tree. Forest Ecology and Management, 135: 33-44.

- Stathers, R.J., Rollerson, T.P. & Mitchell, S.J. (1994). Windthrow Handbook for British Columbia Forests. Research Program Working Paper 9401, Ministry Forests Research Program.
- Sun, Meng, Jepson, Allan D. & Fiume, Eugene (2003). Video Input Driven Animation (VIDA). Proceedings of the IEEE International Conference on Computer Vision, vol. 1, pp 96-103.
- USDA (1999). Wood Handbook - Wood as an Engineering Material. Forest Products Laboratory, Forest Service, United States Department of Agriculture.
- Wang, Song-Yung, Lin, Cheng-Jung & Chiu, Chih-Ming (2005). Dynamic modulus of elasticity and bending properties of young Taiwania trees grown with different thinning and pruning treatments. The Japan Wood Research Society, 51: 1-6.
- WBTC (1999). Geotechnical Manual for Slopes, Guidance on Interpretation and Updating. WBTC No. 13/99, The Government of the Hong Kong Special Administrative Region.

APPENDIX A

Chinese Name of the 30 Species of Trees Growing on Masonry Walls in Hong Kong

Scientific Name	Common Name		Family	
<i>Ficus microcarpa</i>	Chinese banyan	榕樹 (細葉榕)	Moraceae	桑科
<i>Ficus superba</i>	Superb fig	筆管榕	Moraceae	桑科
<i>Ficus hispida</i>	Rough-leaf stem fig	對葉榕 (牛乳樹)	Moraceae	桑科
<i>Ficus virens</i>	Big-leaved fig	黃葛樹 (大葉榕)	Moraceae	桑科
<i>Celtis sinensis</i>	Chinese hackberry	朴樹	Ulmaceae	榆科
<i>Broussonetia papyrifera</i>	Paper mulberry	構樹	Moraceae	桑科
<i>Ficus variegata</i>	Red-stem fig	青果榕	Moraceae	桑科
<i>Ligustrum sinense</i>	Chinese privet	山指甲	Oleaceae	木犀科
<i>Maesa perlarius</i>	(nil)	鯽魚膽	Myrsinaceae	紫金牛科
<i>Ficus religiosa</i>	Peepul tree	菩提樹	Moraceae	桑科
<i>Bridelia monoica</i>	Pop-gun seed	土蜜樹 (逼迫仔)	Euphorbiaceae	大戟科
<i>Litsea glutinosa</i>	Pond spice	潺槁樹	Lauraceae	樟科
<i>Macaranga tanarius</i>	Elephant's ear	血桐	Euphorbiaceae	大戟科
<i>Cassia surattensis</i>	Sunshine tree	黃槐決明 (黃槐)	Caesalpiniaceae	蘇木科
<i>Mallotus paniculatus</i>	Turn-in-the-wind	白楸	Euphorbiaceae	大戟科
<i>Cratoxylum ligustrinum</i>	Yellow-cow wood	黃牛木	Hypericaceae	山竹子科
<i>Dalbergia balansae</i>	South China rosewood	南嶺黃檀	Papilionaceae	蝶形花科
<i>Alangium chinense</i>	Chinese alangium	八角楓	Alangiaceae	八角楓科
<i>Delonix regia</i>	Flame of the forest	鳳凰木	Caesalpiniaceae	蘇木科
<i>Albizia lebeck</i>	Lebeck tree	大葉合歡	Mimosaceae	含羞草科
<i>Aporosa chinensis</i>	Aporosa	銀柴 (大沙葉)	Euphorbiaceae	大戟科
<i>Bauhinia blakeana</i>	Hong Kong orchid tree	洋紫荊	Caesalpiniaceae	蘇木科
<i>Carica papaya</i>	Papaya	番木瓜	Cariaceae	番木瓜科
<i>Liquidambar formosana</i>	Sweet gum	楓香	Hamelidaceae	金縷梅科
<i>Litsea monopetala</i>	Persimmon-leaf litsea	假柿木薑子 (假柿樹)	Lauraceae	樟科
<i>Nerium indicum</i>	Oleander	夾竹桃	Apocynaceae	夾竹桃科
<i>Punica granatum</i>	Pomegranate	安石榴	Punicaceae	安石榴科
<i>Sapium sebiferum</i>	Tallow tree	烏柏	Euphorbiaceae	大戟科
<i>Schefflera octophylla</i>	Ivy tree	鴨腳木	Araliaceae	五加科
<i>Thevetia peruviana</i>	Yellow oleander	黃花夾竹桃	Apocynaceae	夾竹桃科

APPENDIX B

Status of reply from LCSD

District	Reply
Central and Western District	Two records of incident case (Clarence Terrace Children's Playground and Ka Wai Man Road Garden)
Eastern District	No records
Islands District	Not yet received
Kowloon City District	No records
Kwai Tsing District	No records
Kwun Tong District	No records
North District	Not yet received
Sai Kung District	No records
Sha Tin District	Not yet received
Sham Shui Po District	One records of incident case (Lei Cheng Uk Swimming Pool)
Southern District	No records
Tai Po District	No records
Tsuen Wan District	Not yet received
Tuen Mun District	No records
Wan Chai District	No records
Wong Tai Sin District	Not yet received
Yau Tsim Mong District	No records
Yuen Long District	No records

11SW-A/FR24

URGENT BY HAND

11SW-A/FR24

Amended Mar., 97

GEO INCIDENT REPORT

To: ☒ CGE/ I*/ME*/MW* (See also section 16)
☒ PM/LIC (Fax : 2827 8352)

19 MAY 1997

(to be filled in by District Division)


File No. GCI 2/E2/1997
 Incident No. HK 97/512
 Feature No. 11SW-A/FR24

FILL IN OR TICK OR DELETE (FOR ITEM MARKED BY AS APPROPRIATE)

- Incident Reported: Date 09.05.1997 Time 03:25 hrs
☐ thro' Pager No. 4554*/6780* ☒ from ETC Mr. K.L. S. L. (Team 10A) (ETC Incident No. 29)
☐ from Mr/Mrs/Ms Tel. No.
 of ☐ Arch SD ☐ DLO/..... ☐ BD ☐ DO/..... ☐ HD
☐ HyD/..... ☐ Police ☐ FSD ☐ WSD
- Location of Failure T2 Hill Road, Hong Kong
 Co-ordinates of centre of failure 115° 15' 30" E 22° 19' 45" N
 (Attach a 1:1000 survey plan to show location of failure, and Slope Reference Number if possible)
- Date of Inspection 09.05.1997 Inspection by F. Fok
 with Mr/Mrs/Ms Terry Wan of ED Tel. No. 28261354 Time arrived on site 10:40 hrs
 Mr/Mrs/Ms of Tel. No. Time left site 11:50 hrs
 Mr/Mrs/Ms of Tel. No.
 Mr/Mrs/Ms of Tel. No.
- Time and Date of Failure About 2:00 a.m. 09.05.1997 Weather Condition at time of inspection cloudy
 (It is important to give exact time if possible; ask residents or others)
- Type of Failure ☐ Significant sign of distress with no failure mass ☐ Washout
☐ Landslide ☐ Boulder fall from natural slope ☐ Retaining wall failure ☐ Rock fall
☒ Non landslide case (tree fall/ building collapse*) masonry block fall ☐
 (Circle ☐ to indicate principal type of failure if more than one type is involved)
- Feature Type ☐ Natural slope ☐ Rock slope ☒ RC Retaining wall ☒ Masonry wall
☒ Fill slope ☐ Soil cut slope ☐ Soil/rock cut slope ☐ Others
 (Circle ☐ to indicate principal feature type if more than one type is involved)
- Material and Mass Description of the Feature (The Geoguide 3 classification system should be adopted)
☒ Fill ☐ Colluvium ☐ Residual Soil
☐ Partially Weathered Rock (PW 0/30, PW 30/50, PW 50/90, PW 90/100, unclear)
☐ Others
 (Circle ☐ to indicate dominant material if more than one material is involved)
- Scale of Failure m³ (Volume of slip scar*/debris*)
 For boulder fall from natural slope (Approx. trajectory to be shown in Item 15) masonry block
 Number of boulders involved Two Dimension and shape of boulders 0.3 m x 0.3 m
- Feature Condition
 Evidence of poor state of maintenance: ☐ Damaged chunam/shotcrete/stone-pitching*, location
☐ Bare slope surface (poorly maintained vegetation), location
☐ Blocked/broken drains, location ☐ Others location
 Capacity of surface drainage system ☒ adequate ☐ inadequate ☐ not present ☐ not known
 Coverage of hard protection surface against infiltration ☒ adequate ☐ inadequate ☐ not present
 Surface Protection Material chunam
 Field evidence of past instability at or adjoining the failure location ☐ yes ☒ no
 Groundwater seepage observed at the failure location ☐ yes (location to be shown in item 15) ☒ no
- Possible Contributing Causes of Failure (tick one or more) ☐ Infiltration ☐ wash-out
☐ seepage behind an impermeable surface ☐ groundwater (main/perched/unclassified)* ☐ rupture of watermain
☐ Insufficient maintenance contributed to failure ☒ Others tree fall
 (Circle ☐ to indicate primary cause if more than one cause is involved)
- Consequence of Failure ☐ person(s) killed ☐ person(s) injured ☐ Squatter huts affected ☒ Carparks affected
☐ lane(s) of road blocked ☐ Building lot affected ☐ Construction site affected ☐ Pedestrian pavement affected
☐ Country park affected ☐ Open space affected ☐ Building access affected ☐ A car was damaged

12. Immediate Advice Given To: Mr/Ms/Ms Terry Wan of BD
- ☐ Squatter huts permanently evacuated Hut No(s)
- ☐ Squatter huts temporarily evacuated Hut No(s)
- ☐ Flats evacuated/Closure Order Recommended.
Building/Flat No.
- ☐ Close lane(s) of road
- ☐ Close pedestrian pavement
- ☐ Divert surface runoff from reaching failure area
- ☒ Cover failure scar with tarpaulin properly secured against wind
- ☒ Fence off area in danger
- ☐ Trim back failure surface
- ☐ Provide surface protection (with weepholes) to trimmed failure surface
- ☐ Provide/reconstruct drainage system
- ☐ Isolate water-carrying services
- ☐ Check land status
- ☐ Buttrressing
- ☒ Warn nearby occupants of possible danger during heavy rainstorm
- ☒ Remove loose masonry blocks and cover the affected area with chinam
- ☐ Yes ☒ No
13. Is Further Inspection by District GE Required?
if Yes, Reason
14. Is Landslip Record Card Required: ☐ Yes (for debris vol. > 50 m³ or involving death)

15. Details of Failure (location plan & section with approx. dimensions of slope height, gradients, depth of failure, debris run out etc.)



Inspection Officer's Signature

ELTON FOR GE/ISW
NAME IN BLOCK LETTER, POST

09.05.97
DATE

16. District Action Required (to be filled in by District Division)

16.1 Feature to be registered (GEO Circular 8/96)?

☐ Yes ☒ No (Decision to be made by District GE)

16.2 Feature previously studied, upgraded or checked by GEO

☒ Yes ☐ No (TO to carry out file search)

If Yes, state action taken in file DH Order Recommended to BD on 31.12.96

Additional Remarks

Inspection Officer's Signature
District GE's Signature

ELTON FOR
NAME IN BLOCK LETTER

09.05.97
Date

W. Wan
District SGE's Signature

MON KA PAI
NAME IN BLOCK LETTER

9/5/97
Date

- C.C. ☒ CGE/SP (with photo) thro' GGE I/A, PGGE
- ☒ CGE/LI (with photo) IV
- ☐ CGE/SS (for boulder fall from natural slope only)
- ☐ CBS/DB (for private site only)

→ { SSGRI 2m
F/LI 7 2/8

- 1/. One incident report should be filled in for each incident. Report to be continued on supplementary sheets if necessary.
- 2/. Section 1 to 15 to be filled in by Inspecting GE. On returning to the office, the copy should be despatched to CGE/District and PM/LIC asap. The remaining sections (Top box & Section 16) to be completed by District GE and despatched accordingly.
- 3/. Useful observation which supplement information given in the Incident Report to be made on separate sheets.
- GCDIST 31 (3/97)

PHOTOGRAPHS


File Ref. No. GCI 2/E2/1187

Location: No. 72, Hill Road

Taken by: M. G. MA on: 9/5/97

Neg. No: 297/212/0.1

11SW-A / FR 24



GEOTECHNICAL ENGINEERING OFFICE

ISLAND DIVISION

GCDIST FORM 45



BASIC INFORMATION	Feature Ref. No. : 11SW-A/FR 24
--------------------------	--

Location: Behind Hillview Garden, Hill Road, Pokfulam.

Approximate Coordinates **Northing** 816190 **Easting** 831961

SLOPE PART

Max. Height (m) : 9 **Length (m) :** 70 **Avg. Angle (deg) :** 55

WALL PART

Max. Height (m) : 9 **Length (m) :** 70

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest : Flyover

Distance of Facility from Crest (m) : 0

Facility at Toe : Residential

Distance of Facility from Toe (m) : 4

Consequence-to-life Category : 1

Sift Class : B2

Maintenance Responsibility :

Sub Div. No : 1

Main. Parties : Lands D

Sub Div. No : 2

Main. Parties : IL7578

Sub Div. No : 3

Main. Parties : Arch SD

Slope / Wall Detail Data	Feature Ref. No. : 11SW-A/FR 24
--------------------------	---------------------------------

SLOPE PART

Material Description : Material Type: Soil Geology:

Dimensions : Max. Height (m): 9 Length (m): 70

 Average Angle (deg): 55

 No. of Berms: 1 Min. Berm Width (m): .5

Surface Protection : % Bare: 0 % Shotcrete: 0

 % Vegetated: 0 % Other Cover: 0

 % Chunam: 100

Weepholes : Size (mm): 65 Spacing (m): 2.2

Drainage : Type Size (mm)

 Crest 201

 Berm 151

 Toe 201

 On slope 325

WALL PART

Wall ID : 1

Type of Wall : Wall Material: Wall Location:

Dimensions : Max. Height (m): 9 Length (m): 70 Face Angle (deg): 85

 No. of Berms: 0 Min. Berm Width (m): 0

Weepholes : Size (mm): 65 Spacing (m): 1.2

Drainage : Size (mm) Type

 Crest 225

SERVICES


<u>Utilities Type</u>	<u>Size</u>	<u>Location</u>	<u>Remark</u>
NULL	NULL	NULL	NULL

Photo Record Sheet

Printed on 01-NOV-04 10:39:15

11SW-A/FR 24

Date Taken



11SW-A/F 24

10 Feb 2000


Photo 1 : General View Right

Photo Record Sheet

Printed on 01-NOV-04 10:39:15

11SW-A/FR 24


Date Taken



11SW-A/F 24

10 Feb 2000

Photo 2 : General View Left



Geotechnical Engineering Office

Slope Location Plan

Slope No: 11SW-A/FR 24
Easting: 831961

Date Print: 01/11/2004
Northing: 816190

Scale: 1: 1000

SIFT No: 11SW-7C/S64 GEO Reg. No: 11SW-A/FR24 Grid Ref.: 816190 N 832065 E
 Location: slope to the south of the Hillside Garden (No. 72 Hill Rd)

1. Registration Criteria from GEO circular 7/93:

- ☐ retaining wall greater than 3m high. ☒ fill slope or FR greater than 5m high.
☐ fill slope or FR less than 5m high which pose a direct risk to life in the event of failure.
☐ cut slope or CR greater than 3m high. Aerial Photograph Year and Number _____
☐ does not meet GEO slope registration criteria _____

2. SIFT Classification of Fill features:

- ☐ Class A Fill feature considered to have similar circumstances to the Baguio landslide site.
Class B Fill feature considered to meet GEO criteria for slope registration but does not meet criteria A.
☐ B(i) Unregistered or Misregistered, formed pre-1978 or illegal tipped fill and may not have been checked by GEO.
☐ B(ii) Registered and not studied to Stage II equivalent.
☐ B(iii) Unregistered or Misregistered, formed post-1977.
☒ Class C All other features.

3. Modified B & P Risk Assessment: for A, B(i), B(ii) only. See Section 6 on page 2 for details.

- ☐ Low ☐ Low to moderate ☐ Moderate ☐ Moderate to High ☐ High ☐ Very High


4. Remarks: Stage 2 study completed and advising letter served


5. Photograph: Mandatory for A, B(i) only

Negative Number

11SW-A/R120

414
Photos Taken on 24.8.2003
at Kow Wai Man Rd. Garden.





Photos Taken on 3.9.03

at Kai Wai Man Rd Garden





Incident Report for Incident

Printed on 24-FEB-05 14:36:51

HK99/8/3

URGENT BY HAND

GEO INCIDENT REPORT

To: ☒ CGE/1*/ME*/MW*

Amended May, 1999

(to be filled in by District Division)

File No. GCE 2/E2/1999

Incident No. HK 1999/ P. 1. 3

Feature No. 11 SW - A/R 120

FILL IN OR TICK OR DELETE (FOR ITEM MARKED *) AS APPROPRIATE

1. Incident Reported: Date 22/1/8/1999 Time 17:15 hrs
☒ thro' Pager No. 4554*/6780* ☒ from ETC Mr. U. H. Cho: (ETC Incident No.)
☐ from Mr/Mrs/Ms Tel. No.
of ☐ Arch/SD ☐ DLO/ ☐ BD ☐ DO/ ☐ HD
☐ HyD/ ☐ Police ☐ FSD ☐ WSD ☐
2. Location of Failure Slope behind USD Park at Ka Wai Wan Road, Kennedy Town, HK
Co-ordinates of center of failure
(Attach a 1:1000 survey plan to show location of failure, and Slope Reference Number if possible)
3. Date of Inspection 22/1/8/1999 Inspection by Roger C. H. Ting
with Mr/Mrs/Ms C. D. Wong of HyD Tel. No. 9822 5939 Time arrived on site 18:11 hrs
Mr/Mrs/Ms S. J. A. of Police Tel. No. Time left site 19:39 hrs
Mr/Mrs/Ms of Tel. No.
Mr/Mrs/Ms of Tel. No.
4. Time and Date of Failure 22/1/8/1999 Weather Condition at time of inspection Raining
(It is important to give exact time if possible; ask residents or others)
5. Type of Failure ☐ Significant sign of distress with no failure mass ☐ Washout
☐ Landslide ☐ Boulder fall from natural slope ☐ Retaining wall failure ☐ Rock fall
☒ Non landslide case (tree fall/building collapse/ uprooted with 6m x 6m x 1m soil mass on slope)
(Circle the principal type of failure if more than one type is involved)
6. Feature Type ☐ Natural slope ☐ Rock slope ☐ RC Retaining wall ☐ Masonry wall
☐ Fill slope ☒ Soil cut slope ☐ Soil/rock cut slope ☐ Others
(Circle the principal feature type if more than one type is involved)
7. Material and Mass Description of the Feature (The Geoguide 3-classification system should be adopted)
☐ Fill ☐ Colluvium ☒ Residual Soil / CDG
☐ Partially Weathered Rock (PW 0/30, PW 30/50, PW 50/90, PW 90/100, unclear)
☐ Others
(Circle the dominant material if more than one material is involved)
8. Scale of Failure 24 m³ (Volume of slip scar/debris)
For boulder fall from natural slope (Approx. trajectory to be shown in item 15)
Number of boulders involved Dimension and shape of boulders
9. Feature Condition
Evidence of poor state of maintenance: ☐ Damaged chunam/shootcrete/stone-pitching*, location
☐ Bare slope surface (poorly maintained vegetation), location
☐ Blocked/broken drains, location ☐ Others location
Capacity of surface drainage system ☐ adequate ☐ inadequate ☐ not present ☒ not known
Coverage of hard protection surface against infiltration ☒ adequate ☐ inadequate ☐ not present
Surface Protection Material chunam
Field evidence of past instability at or adjoining the failure location ☐ yes ☒ no (Too dark to see)
Groundwater seepage observed at the failure location ☐ yes (location to be shown in item 15) ☐ no
10. Possible Contributing Causes of Failure (tick one or more) ☐ Infiltration ☐ wash-out
☐ seepage behind an impermeable surface ☐ groundwater (main/perched/unclassified)* ☐ rupture of watermain
☐ Insufficient maintenance contributed to failure ☒ Others tree uprooted and typhoon
(Circle the primary cause if more than one cause is involved)
11. Consequence of Failure ☐ person(s) killed ☐ person(s) injured ☐ Squatter huts affected ☐ Carparks affected
☐ lane(s) of road blocked ☐ Building lot affected ☐ Construction site affected ☐ Pedestrian pavement affected
☐ Country park affected ☐ Open space affected ☐ Building access affected ☒ USD Park affected

GEO ECC-7 (5/1999)

- 1 -


Geotechnical Engineering Office - Civil Engineering Department

Incident Report for Incident

Printed on 24-FEB-05 14:36:51

HK99/8/3

- Sergeant 159 A Police Amended May, 1999
of Housing Dept.
12. Immediate Advice Given To: Mr/Mrs/Ms A. Leung
- | | |
|---|--|
| <input type="checkbox"/> Squatter huts permanently evacuated (Hut No(s) | <input type="checkbox"/> Divert surface runoff from seaching failure area |
| <input type="checkbox"/> Squatter huts temporarily evacuated (Hut No(s) | <input checked="" type="checkbox"/> Cover failure scar with tarpaulin properly secured against wind |
| <input type="checkbox"/> Flats evacuated/Closure Order Recommended.
Building/Flat No. | <input checked="" type="checkbox"/> Fence off area in danger (USD Park & Footpath leading to the affected basin) |
| <input type="checkbox"/> Close lane(s) of road | <input type="checkbox"/> Trim back failure surface |
| <input type="checkbox"/> Close pedestrian pavement | <input type="checkbox"/> Provide surface protection (with weepholes) to trimmed failure surface |
| | <input type="checkbox"/> Provide/reconstruct drainage system |
| | <input type="checkbox"/> Isolate water-carrying services |
| | <input type="checkbox"/> Check land status |
| | <input type="checkbox"/> Buttressing |
| | <input type="checkbox"/> Warn nearby occupants of possible danger during heavy rainstorm |
13. Is Further Action by District GE Required? ☒ Yes ☐ No
If Yes, Reason Give advice to USD on slope stability under continuous washout overnight and re-open the park if appropriate.
14. Is Landslip Record Card Required? ☐ Yes (for debris vol. > 50 m³ or involving death) ☒ No
15. Details of Failure (location plan & section with approx. dimensions of slope height, gradients, depth of failure, debris run out etc.)



Roger Tink
Inspection Officer's Signature

Roger C.M. Ting
NAME IN BLOCK LETTER, POST

23 / 8 / 99
DATE

---> GR thro' District SGE
District GE

Cheng Wai Man (Atty. SGE/ISW)
Cheng Wai Man (GE/ISW)

c.c. STO(G)/
PM/LIC - please prepare checklist (GCDIST 44) 3-2
CGE/LI (Fax : 2894 5780)
CBS/SS, BD* (Fax : 2624 4135)
(For cases affecting private buildings)

Note:

- One incident report should be filled in for each incident. Report to be continued on supplementary sheets if necessary.
- Section 1 to 15 to be filled in by Inspecting GE. On returning to the office, the Incident Report should be despatched to CGE/District asap. Top box to be completed by District GE and the Incident Report distributed accordingly.
- Useful observation which supplement information given in the Incident Report to be made on separate sheets.

* Delete as appropriate
GEO ECC-7 (5/1999)

- 2 -


Geotechnical Engineering Office - Civil Engineering Department

Incident Report for Incident

Printed on

24-FEB-05 14:36:51

HK99/8/3



Geotechnical Engineering Office - Civil Engineering Department

Photo for Incident

Printed on

24-FEB-05 14:37:19

HK99/8/3

Incident No. HK1999/8/3

PHOTOGRAPHS	File Ref. No. <i>GCE 2/22/1999</i>	Neg. No. : <i>E99/387/09 & 18</i>
Date Taken : <i>23-8-1999</i>	Location : <i>Ka whi Man Road West Garden Hill-A/1220</i>	



(Where appropriate, please attach a location plan showing
direction of shooting and provide caption to the photographs)

Geotechnical Engineering Office

District Division



GCDIST 45 (Apr 98)

Geotechnical Engineering Office - Civil Engineering Department

BASIC INFORMATION

Feature Ref. No. : 11SW-A/R 120

Location: Ka Wai man Road Open Space, Kennedy Town

Approximate Coordinates **Northing** 815855 **Easting** 830950

SLOPE PART

Max. Height (m) : **Length (m) :** **Avg. Angle (deg) :**

WALL PART

Max. Height (m) : 7 **Length (m) :** 50

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest : Road with low traffic

Distance of Facility from Crest (m) : 1

Facility at Toe : Others occupied buildings

Distance of Facility from Toe (m) : 5

Consequence-to-life Category : 1

Sift Class : B1

Maintenance Responsibility : **Sub Div. No :** 0 **Main. Parties :** Arch SD

Slope / Wall Detail Data	Feature Ref. No. : 11SW-A/R 120
--------------------------	---------------------------------

SLOPE PART

NULL

WALL PART

Wall ID : 1

Type of Wall : Wall Material: Square rubble Wall Location:

Dimensions : Max. Height (m): 7 Length (m): 50 Face Angle (deg): 80

No. of Berms: 0 Min. Berm Width (m): 0

Weepholes : Size (mm): Spacing (m):

SERVICES


<u>Utilities Type</u>	<u>Size</u>	<u>Location</u>	<u>Remark</u>
NULL	NULL	NULL	NULL

Photo Record Sheet

Printed on 24-FEB-05 14:34:15

11SW-A/R 120

Date Taken




11SW-A/R 120 WESTERN PART OF FEATURE F7

Photo Record Sheet

Printed on 24-FEB-05 14:34:15

11SW-A/R 120

Date Taken



11SW-A/R 120

EASTERN PART OF FEATURE

F6

PHASE 2 SYSTEMATIC INSPECTION OF FEATURES IN THE TERRITORY (SIFT 2 Version 4.3)

Amended 7.12.94

SIFT No: 11SW-6D/S 116 GEO Reg. No: 11SW-A/R120 Grid Ref.: 815855 N 830948 E
 Location: 15 M NORTHWEST OF NORTH TERRACE, SAI WAN ESTATE

1. Registration Criteria from GEO Circular 7/93:

☒ greater than 3m high. F or FR greater than 5m high.

F or FR less than 5m high which pose a direct risk to life in the event of failure.

} Part of Larger
 } Fill Body

(Y/N)

C or CR greater than 3m high.

WIP work in progress, registerable features may be present

NR does not meet GEO slope registration criteria NE no longer exists

2. SIFT Classification: from Guidelines for Phase 2 SIFT Version 3

Aerial Photograph Year and Number 1963-7200/1

☐ **Class A** Fill feature considered to have similar circumstances to the Baguio landslide site.

Class B Fill feature considered to meet GEO criteria for slope registration but does not meet criteria A.

☒ **B1** Assumed not to have been checked by GEO (assumed formed pre-1978 or illegally tipped fill).

☐ **B2** Assumed to have been checked by GEO (assumed formed post 1977) or Housing Department or studied to Stage 2 or equivalent.

Class C Cut feature considered to meet GEO criteria for slope registration.

☐ **C1** Assumed formed pre-1978 or illegally formed.

☐ **C2** Assumed formed post 1977.

3. Degree of Risk: (Modified B&P Assessment of Risk for A, B1 only. See Section 6 on page 2 for details.)

☐ Low ☐ Low to moderate ☒ Moderate ☐ Moderate to High ☐ High ☐ Very High


4. Remarks: Squared rubble, mortar packed, retaining wall, 6 m high.

Although wall is not clearly visible in air photos, it appears to have
been constructed prior to 1945. Feature is obscured by overhanging trees
in available photo post 1963

5. Photograph: Mandatory

Negative Number

TE 95142/1



Compiled by N. ABRAHAM API CONSULTANT/9 dated 9/6 1995


6. Modified B&P Assessment of Risk : (For Class A, B1 only)

SIFT No. 11SW-6D/S 1/6 Version 4.3 (7.12.94)

6.1 Feature Dimensions

Estimated Slope Height m. Estimated Slope Length 53 m. Estimated Slope Gradient °.
 Estimated Retaining Wall Height 6 m. Estimated Max. Fill Width 3 m. Estimated Fill Thickness 2.5 m.
 Total Height of Feature 6 m. Part of Larger Fill Body ? (Y / N)
 Volume Calculation $6 \times 53 \times 3 / 2$ Estimated Fill Volume 477 m³.

6.2 Estimated critical section profile: circle the appropriate model below or draw others as appropriate.



6.3 Topographic Situation

Adjacent / Traversed : Drainage Line / Topographic Depression or Spurline / Planar Slope

Catchment area : (1=<100m², 2=100-500m², 3=500-1000m², 4=1000-10000m², 5=>10000m²)

To Fill Body 4 To Drainage Line (if At Risk Structure located downstream)

Intervening Ground, feature to facility: Platform / Slope / Drainage Line . Natural / Cut / Fill . Vegetation (Y / N)

Debris Trail : Channelisation ; Spread ; Erosion and Entrainment ; Assumed to occur along debris trail

6.4 Facilities

Facility(ies) below feature.

Bus Shelter (Y / N)

Facility Ka Wai Man Road Sitting ; Distance, Plan 2 m, Vertical m, Angle Level °

Facility Out-Area ; Distance, Plan m, Vertical m, Angle °

Facility(ies) on slope/platform of feature: road / building / other Foot path - low pedestrian access

6.5 Consequences of Slope Failure :

Spread of debris onto sitting out area.

7. Aerial Photograph Interpretation / Site Observations : (For Class A and Class B1 with VH, H, and MH risk classes only)

7.1 Site History

Year of initial fill placement: Years of subsequent major filling:

Modification / history:

Years and numbers of significant aerial photos used:

7.2 Instability

Past landslips: (Y / N) details:

Signs of distress: (Y / N) details:

7.3 Hydrology

Surface cover: Slope Platform

Estimated area of fill body: m² Estimate permeable infiltration area : m² Cover

Surface drainage channels observed: (Y / N) Potential for toe erosion loose material / undercutting

Evidence for groundwater seepage :


Location : NORTH TERRACE, SAI WAN ESTATE

SIFT No.:

Date : 9/6/95

by N. ABRAHAM API9

113W-6D/S116



Legend :

- Assumed Debris Trail $\Rightarrow \Rightarrow$ Assumed Channelisation $\Rightarrow \Rightarrow$ Assumed Entrainment $\Rightarrow \Rightarrow$
- Fill Body \bigcirc At Risk Facility XXX Assumed Spread SS
- Retaining Wall --- Catchment Boundary --- Note : Delete boundary lines if spread is unconfined

Phase II SIFT Study

FEATURE LOCATION PLAN

Scale 1:1000

11SW-A/R751

Incident Report for Incident

Printed on 01-NOV-04 16:12:08

HK99/8/4

URGENT BY HAND

GEO INCIDENT REPORT

Amended May, 1999

To: ☒ CGE/1/AME/1/1/1/1

(to be filled in by District Division)

File No. GCI 2/E2/1999

Incident No. HK 1999/8/4

Feature No. 11SW-A/R751

FILL IN OR TICK OR DELETE (FOR ITEM MARKED *) AS APPROPRIATE

- Incident Reported Date: 23/8/1999 Time: 08:30 hrs
☐ from Pager No. 455476780 ☒ from ETC Mr. Alan Chan (ETC Incident No.)
☐ from Mr/Ms/Ms of ☐ Arch-SD ☐ DLO ☐ BD ☐ DO ☐ HD
☐ HyD ☐ Police ☐ FSD ☐ WSD
- Location of Failure: 18 Clarendon Terrace, Sai Wan
 Co-ordinates of center of failure:
 (Attach a 1:1000 survey plan to show location of failure, and Slope Reference Number if possible)
- Date of Inspection: 23/8/1999 Inspection by: James Kwok
 with Mr/Ms/Ms of Tel. No. 2312 1121 Time arrived on site: 9:15 hrs
 Mr/Ms/Ms of Tel. No. 2312 1121 Time left site: 10:00 hrs
 Mr/Ms/Ms of Tel. No.
 Mr/Ms/Ms of Tel. No.
- Time and Date of Failure: 13/8/1999 Weather Condition at time of inspection: Heavy Rain
 (It is important to give exact time if possible; ask residents or others)
- Type of Failure: ☒ Significant sign of distress with no failure mass ☐ Washout
☐ Landslide ☐ Boulder fall from natural slope ☒ Retaining wall failure ☐ Rock fall
☐ Non landslide case (tree fall/building collapse) ☒ Retaining wall hit by fallen tree
 (Circle the principal type of failure if more than one type is involved)
- Feature Type: ☐ Natural slope ☐ Rock slope ☐ RC Retaining wall ☒ Masonry wall
☒ Fill slope ☐ Soil cut slope ☐ Soil/rock cut slope ☐ Others
 (Circle the principal feature type if more than one type is involved)
- Material and Mass Description of the Feature: (The Geological Classification system should be adopted)
☐ Fill ☐ Colluvium ☐ Residual Soil
☐ Partially Weathered Rock (PW 0/30 PW 30/50 PW 50/90 PW 90/100 unclear)
☐ Others N/A
 (Circle the dominant material if more than one material is involved)
- Scale of Failure: N/A m³ (Volume of slip scar/debris)
 For boulder fall from natural slope (Approx. trajectory to be shown in item 15)
 Number of boulders involved: Dimension and shape of boulder:
- Feature Condition
 Evidence of poor state of maintenance: ☐ Damaged chain/shotcrete/stone-pitching, location:
☐ Bare slope surface (poorly maintained vegetation), location:
☒ Blocked/broken drains, location: N/A ☐ Others: N/A location:
 Capacity of surface drainage system: ☒ inadequate ☐ inadequate ☐ not present ☐ not known
 Coverage of hard protection surface against infiltration: ☒ adequate ☐ inadequate ☐ not present
 Surface Protection Material:
 Field evidence of past instability at or adjoining the failure location: ☐ yes ☒ no
 Groundwater seepage observed at the failure location: ☐ yes (location to be shown in item 15) ☒ no
- Possible Contributing Causes of Failure (tick one or more)
☐ seepage behind an impermeable surface ☐ groundwater (main/perched/unclassified)
☐ insufficient maintenance contributed to failure ☐ Others: N/A
 (Circle the primary cause if more than one cause is involved)
- Consequence of Failure
☐ person(s) killed ☒ person(s) injured ☐ Squatter huts affected ☐ Carparks affected
☐ lane(s) of road blocked ☐ Building lot affected ☐ Construction site affected ☐ Pedestrian pavement affected
☐ Country park affected ☒ Open space affected ☒ Building access affected ☒ Handrails of Sai Wan 2nd opp. to feature were broken by tree fall

Geotechnical Engineering Office - Civil Engineering Department

Incident Report for Incident

Printed on 01-NOV-04 16:12:08

HK99/8/4

- Amended May, 1999
12. Immediate Advice Given To: Mr/Ms/Ms of (Kowloon Tong Estate Station)
- ☐ Squatter huts permanently evacuated Hut No(s)
- ☐ Squatter huts temporarily evacuated Hut No(s)
- ☐ Flats evacuated/Closure Order Recommended, Building/Hut No.
- ☐ Close lane(s) of road
- ☐ Close pedestrian pavement
- ☐ Divert surface runoff from reaching failure area
- ☐ Cover failure scar with tarpaulin properly secured against wind
- ☒ Fence off area in danger
- ☐ Trim back failure surface
- ☐ Provide surface protection (with woodpoles) to undermined failure surface
- ☐ Provide/reconstruct drainage system
- ☐ Isolate water-carrying services
- ☐ Check land status
- ☐ Buttressing
- ☐ Warn nearby occupants of possible danger during heavy rain/storm
- ☒ Other Action Taken

13. Is Further Action by District GE Required?
If Yes, Reason


☒ Yes ☐ No

14. Is Landslip Record Card Required?

☐ Yes (for debris vol. > 50 m³ or involving death)

☒ No

15. Details of Failure (location plan & section with approx. dimensions of slope height, gradients, depth of failure, debris run out etc.)



Inspection Officer's Signature

NAME IN BLOCK LETTER, POST

23, 8, 99
DATE

GR thro' District SGE Cheng Wai Man (Atty. G&S/ISW)
District GE Cheng Wai Man (G&S/ISW)

c.c. STOC/ISW - please prepare checklist (GCDIST 44) in 24h
PM/LIC (Fax: 2894 5780)
CGE/LI (Fax: 2624 4135)
CBS/SS/BD* (For cases affecting private buildings)

Note:

- One incident report should be filled in for each incident. Report to be continued on supplementary sheets if necessary.
- Section 1 to 15 to be filled in by inspecting GE. On returning to the office, the Incident Report should be despatched to CGE/District asap. Top box to be completed by District GE and the Incident Report distributed accordingly.
- Useful observation which supplement information given in the Incident Report to be made on separate sheets.


* Delete as appropriate

Geotechnical Engineering Office - Civil Engineering Department

Incident Report for Incident

Printed on 01-NOV-04 16:12:08

HK99/8/4



Geotechnical Engineering Office - Civil Engineering Department

BASIC INFORMATION	Feature Ref. No. : 11SW-A/R 751
--------------------------	--

Location: SOUTH OF 450-456,QUEEN'S ROAD WEST,HONG KONG

Approximate Coordinates **Northing** 816257 **Easting** 832106

SLOPE PART

Max. Height (m) : **Length (m) :** **Avg. Angle (deg) :**

WALL PART

Max. Height (m) : 6 **Length (m) :** 65

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest : Road with low traffic

Distance of Facility from Crest (m) : 1

Facility at Toe : Residential

Distance of Facility from Toe (m) : 2.5

Consequence-to-life Category : 1

Sift Class : B2

Maintenance Responsibility : **Sub Div. No :** 0 **Main. Parties :** IL834

Slope / Wall Detail Data	Feature Ref. No. : 11SW-A/R 751
--------------------------	---------------------------------

SLOPE PART

NULL

WALL PART

Wall ID : 1

Type of Wall : Wall Material: Square rubble Wall Location: Retaining wall with level platform

Dimensions : Max. Height (m): 6 Length (m): 65 Face Angle (deg): 85

No. of Berms: 0 Min. Berm Width (m): 0

Weepholes : Size (mm): Spacing (m):

Drainage :	<u>Size (mm)</u>	<u>Type</u>
	Toe	275

SERVICES

<u>Utilities Type</u>	<u>Size</u>	<u>Location</u>	<u>Remark</u>
NULL	NULL	NULL	NULL

Photo Record Sheet

Printed on 01-NOV-04 10:28:20

11SW-A/R 751

Date Taken



11SW-A/R751

GENERAL VIEW

720

PHASE II SYSTEMATIC INSPECTION OF FEATURES IN THE TERRITORY (SIFT II Version 3.8)

SIFT No: 11SW-7A/S 56 GEO Reg. No: 11SW-A/R51 Grid Ref.: 816259 N 832100 E
Location: BEHIND Nos 450-456 QUEENS ROAD WEST.

1. Registration Criteria from GEO circular 7/93:

- ☒ retaining wall greater than 3m high. ☐ fill slope or FR greater than 5m high.
☐ fill slope or FR less than 5m high which pose a direct risk to life in the event of failure.
☐ cut slope or CR greater than 3m high. Aerial Photograph Year and Number _____
☐ does not meet GEO slope registration criteria _____

2. SIFT Classification of Fill features:

- ☐ Class A Fill feature considered to have similar circumstances to the Baguio landslide site.
Class B Fill feature considered to meet GEO criteria for slope registration but does not meet criteria A.
☐ B(i) Unregistered or Misregistered, formed pre-1978 or illegal tipped fill and may not have been checked by GEO.
☐ B(ii) Registered and not studied to Stage II equivalent.
☐ B(iii) Unregistered or Misregistered, formed post-1977.
☒ Class C All other features.

3. Modified B & P Risk Assessment: for A, B(i), B(ii) only. See Section 6 on page 2 for details.

- ☐ Low ☐ Low to moderate ☐ Moderate ☐ Moderate to High ☐ High ☐ Very High

4. Remarks : STAGE II REPORT S2R 19/91, 15/4/91.

5. Photograph : Mandatory for A, B(i) only

Negative Number

Alex Cheung
DDL(M(C&W)2
for DLM(C&W)



The trees immediately adjacent to the collapsed tree are in danger of falling.

photos taken at Clarence Terrace Children's Playground



11SE-A/C897

URGENT BY HAND

Amended May 2003

GEO INCIDENT REPORT

To: ☒ CGE/I*/ME*/MW*

(to be filled in by District Division)

File No. GCI 2/E2/2003Incident No. 2003.1.9.10180Feature No. 11 SE-A/R51

FILL IN OR TICK OR DELETE (FOR ITEM MARKED *) AS APPROPRIATE

1. Incident Reported: Date 4.1.9 /2003 Time 12:04 hrs
☐ thro' Pager No. 4554*/6780* ☐ from ETC Mr (ETC Incident No.)
☒ from Mr/Mrs/Ms Lau Tel. No. 6259 2481 ICC referred the case (no. 1-28562796) to LandsD copied to GEO.
of ☐ Arch SD ☐ DLO/..... ☐ BD ☐ DO/..... ☐ HD
☐ HyD/..... ☐ Police ☐ FSD ☐ WSD ☒ FEHD
2. Location of Failure Lai Sing Court 13-15 Tai Hang Road, HK
Co-ordinates of center of failure 828134E 815333N (Attach a 1:1000 survey plan to show location of failure)
3. Date of Inspection 4.1.9 /2003 Inspection by K. M. Heung
with Mr/Mrs/Ms Y. Y. Ong of SMS/LandsD Tel. No. 2231 3082
Mr/Mrs/Ms Zoe L.S. Lam of BD Tel. No. 2135 2473 Time arrived on site 15:00 hrs
Mr/Mrs/Ms of Tel. No. Time left site 16:00 hrs
Mr/Mrs/Ms of Tel. No.
Mr/Mrs/Ms of Tel. No.
4. Classification of incident: Serious / Significant / Minor*
5. Time and Date of Failure 10:20 p.m. 2.1.9 /2003 Weather Condition at time of inspection Cloudy
(It is important to give exact time if possible; ask residents or others)
6. Type of Failure ☐ Significant sign of distress with no failure mass ☐ Washout
☐ Landslide ☐ Boulder fall from natural slope ☐ Retaining wall failure ☐ Rock fall
☒ Non landslip case (tree fall/ building collapse*/ adjacent stone pitching blocks) ☐
(Circle the principal type of failure if more than one type is involved) on wall pulled down
7. Feature Type ☐ Natural slope ☐ Rock slope ☐ RC Retaining wall ☒ Masonry wall
☐ Fill slope ☐ Soil cut slope ☐ Soil/rock cut slope ☐ Others
(Circle the principal feature type if more than one type is involved)
8. Material and Mass Description of the Feature (The Geoguide 3 classification system should be adopted)
☐ Fill ☐ Colluvium ☒ Residual Soil
☐ Partially Weathered Rock (PW 0/30, PW 30/50, PW 50/90, PW 90/100, unclear)
☐ Others
(Circle the dominant material if more than one material is involved)
9. Scale of Failure approx. 1 m³ (Volume of slip scar*/debris*)
For boulder fall from natural slope (Approx. trajectory to be shown in Item 16)
Number of boulders involved Dimension and shape of boulders
10. Feature Condition
Evidence of poor state of maintenance: ☐ Damaged chunam/shotcrete/stone-pitching*, location
☐ Bare slope surface (poorly maintained vegetation), location
☐ Blocked/broken drains, location ☐ Others location
Capacity of surface drainage system ☒ adequate ☐ inadequate ☐ not present ☐ not known
Coverage of hard protection surface against infiltration ☒ adequate ☐ inadequate ☐ not present
Surface Protection Material stone pitching
Field evidence of past instability at or adjoining the failure location ☐ yes ☒ no
Groundwater seepage observed at the failure location ☐ yes (location to be shown in Item 16) ☒ no
11. Possible Contributing Causes of Failure (tick one or more) ☐ Infiltration ☐ wash-out
☐ seepage behind an impermeable surface ☐ groundwater (main/perched/unclassified)* ☐ rupture of water mains
☐ Insufficient maintenance contributed to failure ☒ Others Tree uprooted by strong wind pull down the adjacent stone pitching block near the crest of wall
(Circle the primary cause if more than one cause is involved)
12. Consequence of Failure ☐ person(s) killed ☐ person(s) injured ☐ Squatter huts affected ☐ Car parks affected
☐ lane(s) of road blocked ☐ Building lot affected ☐ Construction site affected ☒ Pedestrian pavement affected
☐ Country park affected ☐ Open space affected ☐ Building access affected ☐

Amended May, 2003

13. Immediate Advice Given To: Mr/Mrs/Ms Zoe L S Lam of CBS/SS, BD

- | | |
|---|--|
| <input type="checkbox"/> Squatter huts permanently evacuated Hut No(s) | <input checked="" type="checkbox"/> Divert surface runoff from reaching failure area |
| <input type="checkbox"/> Squatter huts temporarily evacuated Hut No(s) | <input checked="" type="checkbox"/> Cover failure scar with tarpaulin properly secured against wind |
| <input type="checkbox"/> Flats evacuated/Closure Order Recommended.
Building/Flat No. | <input checked="" type="checkbox"/> Fence off area in danger |
| <input type="checkbox"/> Close lane(s) of road | <input type="checkbox"/> Trim back failure surface |
| <input checked="" type="checkbox"/> Close pedestrian pavement | <input checked="" type="checkbox"/> Provide surface protection (with weepholes) to trimmed failure surface |
| | <input type="checkbox"/> Provide/reconstruct drainage system |
| | <input type="checkbox"/> Isolate water-carrying services |
| | <input type="checkbox"/> Check land status |
| | <input type="checkbox"/> Buttrressing |
| | <input checked="" type="checkbox"/> Warn nearby occupants of possible danger during heavy rainstorm |
| | <input checked="" type="checkbox"/> <u>remove loose debris/blocks and tree roots on slip surface</u> |

14. Is Further Action by District GE Required?


☐ Yes ☒ No

if Yes, Reason

15. Is Landslip Record Card Required:

☐ Yes (for debris vol. > 50 m³ or involving death) ☒ No

16. Details of Failure (location plan & section with approx. dimensions of slope height, gradients, depth of failure, debris run out etc.)



Inspection Officer's Signature

K.M. HEUNG (GE/IE1)

NAME IN BLOCK LETTER, POST

5/9/2003

DATE

GR thro' District SGE/IE

(Signature) S. H. KWAN

(Name) S. J. 2003 (Date)

District GE/IG K.M. HEUNG

(Signature) K.M. HEUNG

(Name) 5/9/2003 (Date)

c.c. STO(G)/IE

PM/LIC(HKI & OI)*

PM/LIC(K & NT)*

CGE/LI

CBS/SS, BD*

CGE/SM, LandsD*

CGE/MW*(Attn:SGE/SO)

- please prepare checklist (GCDIST 44)

(Fax : 2894 5780)

(Fax : 2736 2856)

(Fax : 2624 4135)

(For cases requiring BD's follow-up action only)

(For cases requiring CGE/SM, LandsD's follow-up action only)

(For cases affecting squatters)

FAXED
6.9.03

Note:

1/ One incident report should be filled in for each incident. Report to be continued on supplementary sheets if necessary.

2/ Section 1 to 16 to be filled in by Inspecting GE. On returning to the office, the Incident Report should be despatched to CGE/District asap. Top box to be completed by District GE and the Incident Report distributed accordingly.

3/ Useful observation which supplement information given in the Incident Report to be made on separate sheets.

o Incident no. is assigned through the Integrated Landslip Information System.

* Delete as appropriate

GEO ECC-7 (5/2003)


PHOTOGRAPHS

File Ref. No. : GC1 2/E2/2003
Incident No. : 2003/9/0180

File No. : 2003-09-ISDF-113, 114

Date Taken : 04.09.2003

Location : Lai Sing Court, Tai Hang Road, H.K. (11SE-A/R51)



(Where appropriate, please attach a location plan showing
direction of shooting and provide caption to the photographs)

Geotechnical Engineering Office

District Division



GCDIST 45 (Apr 98)






Photo for Incident

Printed on

24-FEB-05 14:43:29

HK99/8/4

Incident No. HK 1999/8/4

PHOTOGRAPHS	File Ref. No: GCI 2/E2/1999	Neg. No.: 171/300/00, 05
Date Taken: 23-8-1999	Location: No 18 Clarence Terrace (Bm-A/RJK)	
		
(Where appropriate, please indicate direction of shooting and camera position)	Division	

GCDIST 45 (Apr 98)

Geotechnical Engineering Office - Civil Engineering Department

BASIC INFORMATION	Feature Ref. No. : 11SE-A/C 897
--------------------------	--

Location: FRONT OF LAI SING COURT, TAI HANG ROAD, TAI HANG

Approximate Coordinates **Northing** 815313 **Easting** 838155

SLOPE PART

Max. Height (m) : 5.5 **Length (m) :** 48 **Avg. Angle (deg) :** 75

WALL PART

Max. Height (m) : **Length (m) :**

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest : Open carpark

Distance of Facility from Crest (m) : 1

Facility at Toe : Road with heavy traffic

Distance of Facility from Toe (m) : 2

Consequence-to-life Category : 2

Sift Class : C1

Maintenance Responsibility : **Sub Div. No :** 1 **Main. Parties :** IL7903&EXT

Sub Div. No : 2 **Main. Parties :** IL8200RP

Slope / Wall Detail Data	Feature Ref. No. : 11SE-A/C 897
---------------------------------	--

SLOPE PART

Material Description : **Material Type:** Soil & Rock **Geology:** Decomposed granite
Dimensions : **Max. Height (m):** 5.5 **Length (m):** 48
Average Angle (deg): 75
No. of Berms: **Min. Berm Width (m):**
Surface Protection : **% Bare:** **% Shotcrete:**
% Vegetated: **% Other Cover:** 100
% Chunam:
Weepholes : **Size (mm):** 65 **Spacing (m):** 1.2
Drainage : **Type** **Size (mm)**
Crest 300
Toe 175

WALL PART

NULL

SERVICES

<u>Utilities Type</u>	<u>Size</u>	<u>Location</u>	<u>Remark</u>
NULL	NULL	NULL	NULL

Photo Record Sheet

Printed on

23-DEC-04 10:08:55

11SE-A/C 897


Date Taken



11SE-A/R51

GENERAL VIEW

C8



Geotechnical Engineering Office

Slope Location Plan

Slope No: 11SE-A/C 897

Date Print: 23/12/2004

Scale: 1: 1000

Easting: 838148

Northing: 815325

11NW-B/C321

致：深水埗公園游泳池經理


有關李鄭屋游泳池斜坡樹木倒塌事件報告

於 17.9.2004 上午 8 時 05 分左右，忽然有一棵大樹從跳水池對上的山邊斜坡倒塌下來。本人即時到跳水池查看，發現一顆約高 30 多呎，直徑濶 3 呎半左右的金鳳樹從跳水池對上的斜坡倒塌下來橫臥在跳水池範圍內，它的其中一條枝幹卡在跳板上，當時跳水池是開放的，幸好沒有泳客正在使用，所以沒有引至任何受傷事件發生。

今日天氣晴朗沒有下雨，而早上有少許風及比較乾燥，我觀察這棵已倒塌的金鳳樹，是正在生長中而非枯萎，亦沒有被蟲蛀的跡象，可能它生長得太過茂盛，及支條很多和樹齡多年，而該處斜坡非常傾斜，可能樹根承受不起樹幹和樹枝的重量而連根拔起地倒塌下來。

現場並沒有任何設施嚴重損毀，祇有幾塊池面磚損毀，而斜坡上的約有 3 米長的鐵網、4 條石屎柱及上斜坡鐵梯亦被大樹壓毀，跳池的彈板被樹幹的枝條壓着引致輕微移位。

另外九龍樹隊於上午 10 時 30 分左右，到達本池協助清理倒塌下來的大樹，他們將樹幹鋸成分段及收剪支條。最後九龍樹隊於下午 3 時 30 半左右，完成所有工作及離去。而我亦吩咐清潔工人儘快清走池面之樹幹枝葉。(希望有關組別能在本泳池今年之冬季工程期間，修輯所有具危險性存在的斜坡樹木。現附上多張有關塌樹現場的照片，以供參考)。



Tree felling accident on 17.9.2004
Venue: Lei Cheng Uk Swimming Pool





BASIC INFORMATION	Feature Ref. No. : 11NW-B/C 321
--------------------------	--

Location: Lei Cheng Uk Swimming Pool

Approximate Coordinates **Northing** 822210 **Easting** 834770

SLOPE PART

Max. Height (m) : 12 **Length (m) :** 120 **Avg. Angle (deg) :** 55

WALL PART

Max. Height (m) : **Length (m) :**

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest : Undeveloped green belt

Distance of Facility from Crest (m) : 0

Facility at Toe : Heavily used playground

Distance of Facility from Toe (m) : 0

Consequence-to-life Category : 2

Sift Class : C1

Maintenance Responsibility : **Sub Div. No :** 0 **Main. Parties :** Arch SD

Slope / Wall Detail Data	Feature Ref. No. : 11NW-B/C 321
--------------------------	---------------------------------

SLOPE PART

Material Description : Material Type: Soil Geology:

Dimensions : Max. Height (m): 12 Length (m): 120

Average Angle (deg): 55

No. of Berms: Min. Berm Width (m):

Surface Protection : % Bare: 0 % Shotcrete: 0

% Vegetated: 100 % Other Cover: 0

% Chunam: 0

Weepholes : Size (mm): Spacing (m):

Drainage : Type Size (mm)

NULL NULL

WALL PART

NULL

SERVICES

<u>Utilities Type</u>	<u>Size</u>	<u>Location</u>	<u>Remark</u>
NULL	NULL	NULL	NULL


Photo Record Sheet

Printed on

24-FEB-05 14:27:33

11NW-B/C 321

Date Taken



WESTERN SIDE BY LARGE
SWIMMING POOL

CRITICAL
SECTION


07C

Photo Record Sheet

Printed on 24-FEB-05 14:27:33


11NW-B/C 321

Date Taken



EASTERN END.

08C



Geotechnical Engineering Office

Slope Location Plan

Slope No: 11NW-B/C 321
Easting: 834770

Date Print: 24/ 2/2005
Northing: 822210

Scale: 1: 1000


APPENDIX C

Chinese name of the species group classified in Jenkins et al., 2003

Species class	Species group	Chinese Name
Hardwood	Aspen / alder / cottonwood / willow	白楊樹 / 赤楊 / 三角葉楊 / 柳樹
	Soft maple / birch	"軟"楓樹 / 白樺
	Mixed hardwood	--
	Hard maple / oak/ hickory / beech	"硬"楓樹 / 橡樹 / 山核桃樹 / 山毛櫸
Softwood	Cedar / larch	雪松類 / 落葉松
	Douglas-fir	道格拉斯冷杉
	True fir / hemlock	冷杉 / 鐵杉
	Pine	松
	Spruce	雲杉
Woodland	Juniper / oak / mesquite	杜松 / 橡樹 / 牧豆樹

Comparison of aboveground biomass for different species group and different DBH

Species group	DBH (cm)	b _m (kg)	DBH (cm)	b _m (kg)	DBH (cm)	b _m (kg)	DBH (cm)	b _m (kg)	DBH (cm)	b _m (kg)
Aspen / alder / cottonwood / willow	20	140	40	731	60	1925	80	3824	100	6514
Soft maple / birch	20	176	40	909	60	2371	80	4683	100	7938
Mixed hardwood	20	143	40	797	60	2183	80	4459	100	7762
Hard maple / oak / hickory / beech	20	196	40	1061	60	2846	80	5733	100	9870
Cedar / larch	20	114	40	545	60	1362	80	2608	100	4317
Douglas-fir	20	162	40	883	60	2378	80	4803	100	8286
True fir / hemlock	20	134	40	746	60	2041	80	4168	100	7251
Pine	20	117	40	630	60	1692	80	3409	100	5870
Spruce	20	136	40	683	60	1758	80	3439	100	5787
Juniper / oak / mesquite	20	80	40	262	60	522	80	851	100	1245



APPENDIX D

Study on Masonry Wall (Past Project by LPM 2 Division)

Feature No.	Location	Soil Nail Method		Other Method			Remark
		Retained		Retained			
		Pattern	Tree	Pattern	Tree	Tree	
11SW-A/R22	Wa Ning Lane	No	Yes	N/A			-
11SW-C/CR120	Pokfulam Training Centre	N/A		No	Yes		-
11SW-C/R38	Pokfulam Road	N/A		No	Yes		-
11SW-A/CR306	Mount Davis Road	Yes	N/A	N/A			Works not yet completed
11SW-B/FR55	Bowen Road	Yes	Yes	N/A			Works not yet completed
11SW-B/R521	Bowen Road	N/A		No	N/A		Not related to this study
11SW-C/CR81	Queen Mary Hospital	N/A		Yes	N/A		Masonry wall of 1.83m high only
11SE-B/FR111	Chai Wan Road	Yes	N/A	N/A			Works not yet completed
11SW-B/R625	Sik On Street	N/A		No	N/A		Not related to this study
11SW-B/C6	Albany Road	Yes	N/A	N/A			Works not yet completed

A summary of replies from 30 consultants on method of upgrading masonry walls

List No.	Consultant	Result
1	Atkins China Ltd.	No reply
2	Au Posford Consultants Ltd.	No reply
3	Babtie Asia Ltd.	No relevant records
4	BCL Geotechnics Ltd.	(1) 11SW-A/R109 (2) 11SW-A/R298
5	Black & Veatch Hong Kong Ltd.	
6	BMMK, Ratcliffe, Hoare & Co. Ltd.	No reply
7	ESA Consulting Engineers Ltd.	No reply
8	Fugro (Hong Kong) Ltd.	(1) 11SW-A/R346
9	Greg Wong & Associates Ltd.	No reply
10	Halcrow China Ltd.	No reply
11	Ho Tin & Associates Consulting Engineers Ltd.	No reply
12	Hyder Consulting Ltd.	No reply
13	James Lau & Associates Ltd.	(1) 11SW-A/R374 & 375 (2) 11SW-B/R548 (Portion) (3) 11SW-A/R802
14	LMM Consulting Engineers Ltd.	No reply
15	Maunsell Geotechnical Services Ltd.	No reply
16	Maurice Lee and Associates Ltd.	No relevant records
17	Meinhardt (C&S) Ltd.	No reply
18	Mott Connell Ltd.	No relevant records
19	Ove Arup & Partners HK Ltd.	No reply
20	Parsons Brinckerhoff (Asia) Ltd	No reply
21	Pypun Engineering Consultants Ltd.	No reply
22	Roger Sze & Associates Ltd.	No reply
23	Scott Wilson Ltd.	(1) 11SW-A/R563
24	Siu Yin Wai & Associates Ltd.	No reply
25	SMEC Asia Ltd.	No reply
26	Victor Li & Associates Ltd.	No reply
27	W T Chan & Associates Ltd.	No reply
28	Wong & Cheng Consulting Engineers Ltd.	No reply
29	Wong Pak Lam & Associates Consulting Engineers & Architects Ltd.	No reply
30	WSP Hong Kong Ltd.	No reply

APPENDIX E

E.1 SOIL NAIL METHOD

The preferred method is to hide the soil nail heads behind masonry blocks, and hence it is necessary to extract selected blocks, install the soil nails, and then reinstate the blocks such that little evidence of disturbance is left. The following precautionary measures are proposed to minimize impacts on walls and trees:

(i) Physical breakage of masonry blocks

- Avoid breaking the block in prying it;
- Avoid dropping the extracted block;
- Avoid physical impact on the wall by construction vehicles and machinery;

(ii) Chipping corners off masonry blocks

- Avoid chipping the block corners in prying it;
- Avoid dropping the extracted block;

(iii) Cracking masonry blocks

- Avoid cracking the block in prying it;
- Avoid dropping the extracted block;
- Avoid physical impact on the wall by construction vehicles and machinery;

(iv) Staining masonry blocks with cement

- Do not permit piling of construction materials against the wall;
- Avoid staining the wall face by wet cement;
- Shield both the target and adjacent blocks to avoid staining by cement;
- Trials could be attempted to coat or spray the wall face with a protective non-penetrating liquid, plastic, foam or wax that could be easily removed after the completion of stabilization works;

(v) Excessive cleaning of masonry blocks stained by cement

- Avoid rigorous washing of stained blocks that could change its colour and render it discordant with existing blocks;
- If staining occurs, the cement should be washed off immediately with clean water without any additives, detergents or abrasive materials;
- Do not allow cement stain to dry and cure on masonry blocks;

(vi) Temporary storage of extracted masonry blocks

- All extracted masonry blocks should be properly numbered and temporarily stored in a compartment sheltered from the elements and from construction activities and materials;
- Avoid staining or physically damage the stored blocks;

(vii) Replacement masonry blocks of a different stone type

- If the extracted block is unfortunately damaged, the replacement block should as far as possible be of the same stone type in terms of mineral composition and texture, and be of a comparable degree of weathering and surface finishing;
- Consideration should be given to the stockpiling of masonry blocks from demolished old stone walls to be used for replacement purpose, and this is especially important for volcanic (dark-coloured) stone blocks as quarrying for this stone type is now very rare;

(viii) Use of plaster to imitate the extracted masonry block

- Avoid using plaster to imitate the extracted masonry blocks, as the material and workmanship cannot reproduce the colour, texture and finishing of the original stone;

(ix) New mortar of a different colour, texture and configuration

- Prepare a mortar with a composition, colour and texture that is similar to the existing one;
- Apply the mortar in such a way that it emulates the original design and workmanship;

(x) New pointing of a different colour and texture

- Prepare a pointing mixture with a composition, colour and texture that is similar to the existing one;
- Apply the pointing material in such a way that it emulates the original design and workmanship;
- The original pointing design should be faithfully followed, namely whether it is recessed, flushed or ribbon, and whether the surface is concave-V, concave-U, concave-flat, convex-V, convex-U or convex-flat;

(xi) Placement of soil nail heads

- Instead of a uniform pattern of soil nails, their location and spacing could be modified to minimize impacts on tree roots;
- The centre of a soil nail on the wall surface should be situated at not less than 1000 mm from the edge of a surface root with a diameter larger than 25 mm to reduce the chance of damaging roots situated on and behind the wall face

(xii) Displacement of masonry blocks

- In the course of extracting the masonry blocks, take care not to displace the adjacent blocks;
- Where necessary, temporary supports may be needed to avoid displacement of adjacent blocks in the course of drilling and grouting;

(xiii) Injury to tree branches and foliage

- Do not damage or cut any branches or roots, including aerial roots, of wall trees;
- Do not damage or remove any foliage of wall trees;
- Do not permit drilling and other machines and construction vehicles to damage the branches, foliage and roots of wall trees;
- Do not permit the piling of construction materials against wall trees;
- Do not permit any parts of wall trees to be used as a temporary support for scaffolding and other structures;
- Do not hang anything on wall trees;
- Do not tie strings or ropes or cables on wall trees;
- Do not put up signs on wall trees;
- Do not permit covering the crowns of wall trees by plastic sheets or other materials;
- Do not permit wet cement and grouting fluid to spill on wall trees;
- Do not permit cement dust to accumulate on wall trees;
- Do not permit hot air from machines to drift into the crowns of wall trees;
- Do not permit exhaust fume or smoke from machines to drift into the crowns of wall trees;
- Do not light a fire or burn materials under the crowns and within 10 m from the crown perimeter of wall trees;
- Do not permit heavy materials to be lifted and to sail above wall trees;

(xiv) Injury to tree roots in the soil behind the wall and below the footpath

- Avoid spreading of grouting fluid from the drill hole to the surrounding soil where tree roots occur;
- Use left-in casings for the free length of soil nails;
- Where tree roots have penetrated into the soil beneath the paving at the wall base, take care to avoid disturbing the soil and damaging the roots growing in it;
- Where tree roots have penetrated into the soil beneath the paving at the wall base, avoid spilling cement-laden water into the soil.
- Avoid spilling of petrol oil, bitumen or other materials likely to be injurious to the trees or cause soil pH change.
- Where tree roots have penetrated into the soil beneath the paving at the wall base, no stockpiling of soil, materials, equipment, machinery and no passage or parking of vehicles, which cause compaction to the soil;

E.2 CONVENTIONAL AND FLYING BUTTRESS

The buttress method has the advantage of keeping the masonry work intact and avoiding disturbing the soil and tree roots situated behind the stone wall. The contact area between buttresses and walls is relatively small, and hence the chance of the buttresses damaging the wall faces and wall trees is correspondingly reduced. To reduce the aesthetic impact, the finishing of the buttress should be designed to be blended with the preserved wall façade as far as possible. The buttress method is considered a much less intrusive stabilization technique than soil nail. Its impacts on walls and wall trees could be minimize by observing the following precautionary measures:

(i) Physical breakage of masonry blocks

- Avoid damaging masonry blocks in constructing the buttresses;
- Avoid physical impact on the wall by construction vehicles and machinery;

(ii) Staining masonry blocks with cement

- Do not permit piling of construction materials against the wall;
- Avoid staining the wall face by wet cement or concrete;
- Shield both the target and adjacent blocks to avoid staining by cement;
- Trials could be attempted to coat or spray the wall face with a protective non-penetrating liquid, plastic, foam or wax that could be easily removed after the completion of stabilization works;

(iii) Placement of buttresses

- Where conditions permit, flying buttress is better than conventional buttress because of a smaller contact area between buttress and wall face;
- Place the buttresses in a flexible manner to avoid damaging tree roots growing on the wall face;
- Instead of a uniform distribution of buttresses, their spacing could be modified to minimize impacts on tree roots;

(iv) Injury to tree branches and foliage

- Do not damage or cut any branches or roots, including aerial roots, of wall trees;
- Do not damage or remove any foliage of wall trees;
- Do not permit machines or construction vehicles to damage the branches, foliage and roots of wall trees;
- Do not permit the piling of construction materials against wall trees;
- Do not permit any parts of wall trees to be used as a temporary support for scaffolding and other structures;
- Do not hang anything on wall trees;
- Do not tie strings or ropes or cables on wall trees;
- Do not put up signs on wall trees;
- Do not permit covering the crowns of wall trees by plastic sheets or other materials;
- Do not permit wet cement or concrete to spill on wall trees;
- Do not permit cement dust to accumulate on wall trees;
- Do not permit hot air from machines to drift into the crowns of wall trees;
- Do not permit exhaust fume or smoke from machines to drift into the crowns of wall trees;
- Do not light a fire or burn materials under the crowns and within 10 m from the crown perimeter of wall trees;
- Do not permit heavy materials to be lifted and to sail above wall trees;

(v) Injury to tree roots in the soil behind the wall and below the footpath

- Where tree roots have penetrated into the soil beneath the paving at the wall base, in installing the buttress foundation take care to minimize disturbing the soil and damaging the roots growing in it;
- Where tree roots have penetrated into the soil beneath the paving at the wall base, avoid spilling cement-laden water into the soil.
- Avoid spilling of petrol oil, bitumen or other materials likely to be injurious to the trees or cause soil pH change.
- Where tree roots have penetrated into the soil beneath the paving at the wall base, no stockpiling of soil, materials, equipment, machinery and no passage or parking of vehicles, which cause compaction to the soil;

E.3 HAND-DUG CAISSON

The caissons are to be installed behind the wall and hence they will impose little impact on the stone face and roots growing on it. The disturbance to soil and roots, however, will occur behind the stone wall. The hand-digging approach will facilitate preservation of relatively large roots. The spacing of caissons could avoid damaging the major root concentrations and leave gaps for future root growth. The following precautionary measures could be adopted to reduce impacts on walls and wall trees:

(i) Physical breakage of masonry blocks

- Avoid damaging masonry blocks in the course of constructing the caissons;
- Avoid physical impact on the wall by construction vehicles and machinery;

(ii) Staining masonry blocks with cement

- Do not permit piling of construction materials against the wall;
- Avoid staining the wall face by wet cement or concrete;
- Shield both the target and adjacent blocks to avoid staining by cement;
- Trials could be attempted to coat or spray the wall face with a protective non-penetrating liquid, plastic, foam or wax that could be easily removed after the completion of stabilization works;

(iii) Placement of caissons

- Place the caissons in a flexible manner to minimize damaging tree roots growing on and behind the wall face;
- Instead of a uniform spread of caissons, their spacing could be modified to minimize impacts on tree roots growing behind the wall;

(iv) Injury to tree branches and foliage


- Do not damage or cut any branches or roots, including aerial roots, of wall trees;
- Do not damage or remove any foliage of wall trees;
- Do not permit machines or construction vehicles to damage the branches, foliage and roots of wall trees;
- Do not permit the piling of construction materials against wall trees;
- Do not permit any parts of wall trees to be used as a temporary support for scaffolding and other structures;
- Do not hang anything on wall trees;
- Do not tie strings or ropes or cables on wall trees;
- Do not put up signs on wall trees;
- Do not permit covering the crowns of wall trees by plastic sheets or other materials;
- Do not permit wet cement or concrete to spill on wall trees;
- Do not permit cement dust to accumulate on wall trees;
- Do not permit hot air from machines to drift into the crowns of wall trees;
- Do not permit exhaust fume or smoke from machines to drift into the crowns of wall trees;
- Do not light a fire or burn materials under the crowns and within 10 m from the crown perimeter of wall trees;
- Do not permit heavy materials to be lifted and to sail above wall trees;

(v) Injury to tree roots in the soil behind the wall and below the footpath

- Where tree roots have penetrated into the soil beneath the paving at the wall base, in installing the caissons take care to minimize unnecessary disturbance of the soil and damaging the roots growing in it;
- Study the root distribution pattern on the wall face including the penetration of roots through the joints between masonry blocks, make an educated assessment of possible root concentrations behind the wall, and avoid placing caissons at such locations;
- After taking the above precaution, where roots with a diameter over 20 mm are encountered in opening the caisson shaft, they should not be cut and should be wrapped around by expanded vermiculite mineral particles to be contained in a tube-like and water-proof protective sheath with a diameter at least three times that of the root's;
- Do not place two adjacent caissons without leaving a gap of at least 2000 mm in between to permit future root growth into the soil behind the wall;
- Where tree roots have penetrated into the soil beneath the paving at the wall base, avoid spilling cement-laden water into the soil.
- Avoid spilling of petrol oil, bitumen or other materials likely to be injurious to the trees or cause soil pH change.
- Where tree roots have penetrated into the soil beneath the paving at the wall base, no stockpiling of soil, materials, equipment, machinery and no passage or parking of vehicles, which cause compaction to the soil;

APPENDIX F



Feature No. 11SW-A/R684



STABILITY CHECKING OF MASONRY WALL WITH TREES

Feature No.
Location

11SW-A/R684
Po Shan Road



(A) DIMENSION AND PARAMETERS

Wall Dimensions

H = Height of masonry wall	7	m
B = Base width at toe	1.1	m
B _F	0.61	m
B _B	0.00	m
φ _F = wall face angle	85	deg
φ _B = wall back angle	90	deg

*Base width obtained by weephole probing only

Tree Dimensions

DBH*	70	cm
h = Overall height of tree	9	m
h _C = Height of tree canopy	5	m
h _T = Height of tree trunk	5	m
h _A = Height of trunk base above wall toe	6.5	m
b _C = Crown spread	12	m
b _R = root spread	7	m
θ = Tilting angle of trees	30	deg

(* DBH= Diameter at breast height and shall be measured at 1.3m above the trunk base and measurement shall follow the guidance provided in AFCD (2003) - Nature Conservation Practice Note No. 02/2003)

$$\begin{aligned}
 b_{45} &= 45^\circ \text{ spreading from trunk base to wall toe} = 2 \times h_A = 13 \text{ m} \\
 s &= \text{spread of loading} = 3.5 + \text{greater } (b_R + 2B \text{ or } b_{45})/2 = 10.5 \text{ m} \\
 &\hspace{15em} (\text{one side constrained by wall end})
 \end{aligned}$$

Design Parameters

Masonry unit wt.	22	kN/m ³
Soil unit wt.	19	kN/m ³
Water unit wt.	9.81	kN/m ³
Ø' of soil behind wall	Unfactored	°
c' of soil behind wall	35	°
δ, friction angle	0	kPa
K _a (base on Coulomb Theory)	23.3	°
	0.32	
Ø' of base soil	35	°
c' of base soil	7	kPa
δ _b , wall base friction angle	23.3	°
wall base cohesion, c _b	0.0	kPa

Geometry

Back slope angle (β)	20	°
Front slope angle (α)	0	°
Height of groundwater table	2.3	m
Surcharge	0	kPa

Forces

P ₁ , P ₂ , P ₃	= Active force on wall from soil behind wall
	= Active force on wall from groundwater behind wall
P _s	= Active force on wall due to surcharge beyond wall crest
P _u	= Uplift force on wall due to groundwater below wall
W ₁ , W ₂ , W ₃	= Weight of wall
F _{WC}	= Wind force on tree crown
F _{WT}	= Wind force on tree trunk
F _{SC}	= Surcharge from tree crown
F _{ST}	= Surcharge from tree trunk

(B) CHECKING THE STABILITY AGAINST SLIDING

(I) FORCE FROM SOIL AND WATER PRESSURE

Type									Force (kN/m)	F _{OH} (kN/m)	F _{OV} (kN/m)
P ₁ =	0.5	x	0.32	x	4.67 ²	x	19.00	=	66.20	60.79	26.22
P ₂ =	0.32	x	4.67	x	2.33	x	19.00	=	66.20	60.79	26.22
P ₃ =	0.5	x	0.32	x	2.33 ²	x	9.19	=	8.01	7.35	3.17
P _s =	0.32	x	0.00	x	7.00			=	0.00	0.00	0.00
P _w =	0.5	x	2.33 ²	x	9.81			=	26.71	26.71	0.00
Total									155.64	55.62	

(II) WIND FORCE

C_{DC} = drag coefficient of tree crown

= 0.5

C_{DT} = drag coefficient of tree trunk

= 1.2

Static

Wind force = C_D q A

q = wind pressure (1 in 50 years)

= 2.23 kPa

Assume the projected frontal area of crown is elliptical in shape

Projected frontal area of crown, A_C = b_C h_C x π/4

= 47.12 m²

Projected frontal area of trunk, A_T = DBH h_T

= 3.5 m²

Type									Force (kN)	Force (kN/m)
F _{WC} =	0.5	x	2.23	x	47.12	=	52.5	=	5.00	
F _{WT} =	1.2	x	2.23	x	3.5	=	9.4	=	0.89	
F _W									5.90	

Dynamic

Wind force = G C_D q_z A_z

q_z = design hourly-mean wind pressure (1 in 50 years)

= 1.05 kPa

natural frequency, n_a = 0.0948 + 3.4317 DBH / h²

= 2.39 Hz

effective turbulence length scale, L_h = 1000 (h/10)^{0.25}

= 974.00

design hourly-mean wind speed at height h, V_h

= 41.7 m/s

effect reduced frequency, N = n_a L_h / V_h

= 55.81

turbulence intensity at the tope of structure, I_h = 0.1055 (h / 90)^{-0.11}

= 0.14

peak facotr for background response, g_v

= 3.7

peak facotr for resonance response, g_r = √(2 log_e(3600n_a))

= 4.26

background factor, B = 1 / [1 + (36h² + 64b_c²) / L_h²]

= 0.90

size factor, S = 1 / [1 + (3.5n_ah / V_h) [1 + (4n_ab_c / V_h)]]

= 0.10

wind energy spectrum, E = 0.47N / (2 + N²)^{5/6}

= 0.03

damping ratio, ξ

= 0.02

dynamic magnification factor, G = 1 + 2I_h √(g_v²B + (g_r²SE) / ξ)

= 2.06

Type									Force (kN)	Force (kN/m)
F _{WC} =	2.06	x	0.5	x	1.05	x	47.12	=	50.8	4.84
F _{WT} =	2.06	x	1.2	x	1.05	x	3.5	=	9.1	0.86
F _W									5.71	

F_{WC} = 5.00 kN/m (greater of static & dynamic)

F_{WT} = 0.89 kN/m (greater of static & dynamic)

Total = 5.90 kN/m

(III) VERTICAL FORCE

Surcharge from Wall Tree

According to Jenkins et al. (2003)*,

b_m = total aboveground biomass (kg) for trees 2.4cm DBH and larger = $\text{Exp}(\alpha_0 + \alpha_1 \ln \text{DBH})$

ratio = $\text{Exp}(\beta_0 + \beta_1 / \text{DBH})$

*Jenkins, Jennifer C.; Chojnacky, David C.; Heath, Linda S.; Birdsey, Richard A. (2003). National-Scale Biomass Estimators for United States Tree Species. Forest Science, v 49, n 1, February, 2003, p 12-35

b_m	$(\alpha_0 = -2.0127, \alpha_1 = 2.4342)$	=	4142	kg
		=	40.64	kN
Ratio (foliage)	$(\beta_0 = -4.0813, \beta_1 = 5.8816)$	=	0.018	
Ratio (stem bark)	$(\beta_0 = -2.0129, \beta_1 = -1.6805)$	=	0.130	
Ratio (stem wood)	$(\beta_0 = -0.3065, \beta_1 = -5.4240)$	=	0.681	
Ratio (branches)	= $1 - 0.018 - 0.13 - 0.681$	=	0.170	

Weight of wood should be increased by 50% to allow for water content

Type					Force (kN)		Force (kN/m)
$F_{SC} =$	40.64	x (0.018	+ 0.170)	=	7.7
$F_{ST} =$	40.64	x (0.130	+ 0.681	x 1.5)	=	46.8
					F_s	=	5.19

Self Weight & Uplift Pressure

Type								FORCE (kN/m)
$W1 =$	7.00	x	0.49	x	22.00	=		75.46
$W2 =$	0.50	x	7.00	x	0.61	x	22.00	46.97
$W3 =$	0.50	x	7.00	x	0.00	x	22.00	0.00
$Pu =$	-0.50	x	2.33	x	1.10	x	9.81	-12.59
					F_N	=		109.84

(IV) CHECKING

Factor of Safety for Other Loads = 1.5

Factor of Safety for Wind Loads = 1.5

Without Wall Tree

Total Vertical Force (N)	=	$F_{OV} + F_N$	=	165.46	kN/m
Frictional Force (F_R)	=	$N \times \tan \delta_b + c' \times \text{wall base}$	=	71.37	kN/m
Sliding Force	=	$1.50 F_{OH}$	=	233.45	kN/m

Frictional Force < Sliding Force **NOT OK**

With Wall Tree

Total Vertical Force (N)	=	$F_{OV} + F_s + F_N$	=	170.64	kN/m
Frictional Force (F_R)	=	$N \times \tan \delta_b + c' \times \text{wall base}$	=	73.61	kN/m
Sliding Force	=	$1.5 \times F_{OH} + 1.5 \times F_w$	=	242.30	kN/m

Frictional Force < Sliding Force **NOT OK**

(C) CHECKING THE STABILITY AGAINST OVERTURNING**(I) OVERTURNING MOMENT FROM SOIL AND WATER PRESSURE (about pt. O)**

Type	Force (kN/m)	Lever Arm (m)	Moment (kNm/m)
P ₁ (HORIZONTAL COMPONENT)	60.79	3.89	236.41
P ₂ (HORIZONTAL COMPONENT)	60.79	1.17	70.92
P ₃ (HORIZONTAL COMPONENT)	7.35	0.78	5.72
P _s (HORIZONTAL COMPONENT)	0.00	3.50	0.00
P _w (HORIZONTAL COMPONENT)	26.71	0.78	20.77
P _u	12.59	0.73	9.23
- P ₁ (VERTICAL COMPONENT)	26.22	1.10	-28.84
- P ₂ (VERTICAL COMPONENT)	26.22	1.10	-28.84
- P ₃ (VERTICAL COMPONENT)	3.17	1.10	-3.49
- P _s (VERTICAL COMPONENT)	0.00	1.10	0.00
- P _w (VERTICAL COMPONENT)	0.00	1.10	0.00
M_O			= 281.87

(II) OVERTURNING MOMENT FROM SURCHARGE OF WALL TREE (about pt. O)

Type	Force (kN/m)	Lever Arm (m)	Moment (kNm/m)
F _{sc}	0.73	$h_T \times \tan \theta = 2.89$	2.11
F _{st}	4.46	$h_T \times \tan \theta / 2 = 1.44$	6.44
M_S			= 8.54

(III) OVERTURNING MOMENT FROM WIND LOAD ON WALL TREE (about pt. O)

Type	Force (kN/m)	Lever Arm (m)	Moment (kNm/m)
F _{wc}	5.00	$h + H - h_C / 2 = 13.00$	65.05
F _{wt}	0.89	$h + h_T / 2 = 9.00$	8.03
M_W			= 73.08

(IV) RESTORING MOMENT (about pt. O)

Type	Force (kN/m)	Lever Arm (m)	Moment (kNm/m)
W1	75.46	0.86	64.52
W2	46.97	0.41	19.10
W3	0.00	1.10	0.00
M_R			= 83.62

(V) CHECKING

Factor of Safety for Other Loads	=	2
Factor of Safety for Wind Loads	=	1.5

Without Wall Tree

Overturning Moment	=	2 x Mo	=	563.74	kNm/m
Restoring Moment			=	83.62	kNm/m

Restoring Moment < Overturning Moment **NOT OK**

With Wall Tree

Overturning Moment	=	2 x (Mo + Ms) + 1.5 x Mw	=	690.44	kNm/m
Restoring Moment			=	83.62	kNm/m

Restoring Moment < Overturning Moment **NOT OK**

GEO PUBLICATIONS AND ORDERING INFORMATION

土力工程處刊物及訂購資料

A selected list of major GEO publications is given in the next page. An up-to-date full list of GEO publications can be found at the CEDD Website <http://www.cedd.gov.hk> on the Internet under "Publications". Abstracts for the documents can also be found at the same website. Technical Guidance Notes are published on the CEDD Website from time to time to provide updates to GEO publications prior to their next revision.

Copies of GEO publications (except geological maps and other publications which are free of charge) can be purchased either by:

Writing to

Publications Sales Section,
Information Services Department,
Room 402, 4th Floor, Murray Building,
Garden Road, Central, Hong Kong.
Fax: (852) 2598 7482

or

- Calling the Publications Sales Section of Information Services Department (ISD) at (852) 2537 1910
- Visiting the online Government Bookstore at <http://www.bookstore.gov.hk>
- Downloading the order form from the ISD website at <http://www.isd.gov.hk> and submitting the order online or by fax to (852) 2523 7195
- Placing order with ISD by e-mail at puborder@isd.gov.hk

1:100 000, 1:20 000 and 1:5 000 geological maps can be purchased from:

Map Publications Centre/HK,
Survey & Mapping Office, Lands Department,
23th Floor, North Point Government Offices,
333 Java Road, North Point, Hong Kong.
Tel: (852) 2231 3187
Fax: (852) 2116 0774

Requests for copies of Geological Survey Sheet Reports and other publications which are free of charge should be directed to:

For Geological Survey Sheet Reports which are free of charge:

Chief Geotechnical Engineer/Planning,
(Attn: Hong Kong Geological Survey Section)
Geotechnical Engineering Office,
Civil Engineering and Development Department,
Civil Engineering and Development Building,
101 Princess Margaret Road,
Homantin, Kowloon, Hong Kong.
Tel: (852) 2762 5380
Fax: (852) 2714 0247
E-mail: jsewell@cedd.gov.hk

For other publications which are free of charge:

Chief Geotechnical Engineer/Standards and Testing,
Geotechnical Engineering Office,
Civil Engineering and Development Department,
Civil Engineering and Development Building,
101 Princess Margaret Road,
Homantin, Kowloon, Hong Kong.
Tel: (852) 2762 5346
Fax: (852) 2714 0275
E-mail: thomashui@cedd.gov.hk

部份土力工程處的主要刊物目錄刊載於下頁。而詳盡及最新的土力工程處刊物目錄，則登載於土木工程拓展署的互聯網網頁 <http://www.cedd.gov.hk> 的“刊物”版面之內。刊物的摘要及更新刊物內容的工程技術指引，亦可在這個網址找到。

讀者可採用以下方法購買土力工程處刊物(地質圖及免費刊物除外):

書面訂購

香港中環花園道
美利大廈4樓402室
政府新聞處
刊物銷售組
傳真: (852) 2598 7482

或

- 致電政府新聞處刊物銷售小組訂購 (電話: (852) 2537 1910)
- 進入網上「政府書店」選購，網址為 <http://www.bookstore.gov.hk>
- 透過政府新聞處的網站 (<http://www.isd.gov.hk>) 於網上遞交訂購表格，或將表格傳真至刊物銷售小組 (傳真: (852) 2523 7195)
- 以電郵方式訂購 (電郵地址: puborder@isd.gov.hk)

讀者可於下列地點購買1:100 000、1:20 000及1:5 000地質圖：

香港北角渣華道333號
北角政府合署23樓
地政總署測繪處
電話: (852) 2231 3187
傳真: (852) 2116 0774

如欲索取地質調查報告及其他免費刊物，請致函：

免費地質調查報告:

香港九龍何文田公主道101號
土木工程拓展署大樓
土木工程拓展署
土力工程處
規劃部總土力工程師
(請交:香港地質調查組)
電話: (852) 2762 5380
傳真: (852) 2714 0247
電子郵件: jsewell@cedd.gov.hk

其他免費刊物:

香港九龍何文田公主道101號
土木工程拓展署大樓
土木工程拓展署
土力工程處
標準及測試部總土力工程師
電話: (852) 2762 5346
傳真: (852) 2714 0275
電子郵件: thomashui@cedd.gov.hk

MAJOR GEOTECHNICAL ENGINEERING OFFICE PUBLICATIONS

土力工程處之主要刊物

GEOTECHNICAL MANUALS

Geotechnical Manual for Slopes, 2nd Edition (1984), 300 p. (English Version), (Reprinted, 2000).

斜坡岩土工程手冊(1998)，308頁(1984年英文版的中文譯本)。

Highway Slope Manual (2000), 114 p.

GEOGUIDES

Geoguide 1 Guide to Retaining Wall Design, 2nd Edition (1993), 258 p. (Reprinted, 2007).

Geoguide 2 Guide to Site Investigation (1987), 359 p. (Reprinted, 2000).

Geoguide 3 Guide to Rock and Soil Descriptions (1988), 186 p. (Reprinted, 2000).

Geoguide 4 Guide to Cavern Engineering (1992), 148 p. (Reprinted, 1998).

Geoguide 5 Guide to Slope Maintenance, 3rd Edition (2003), 132 p. (English Version).

岩土指南第五冊 斜坡維修指南，第三版(2003)，120頁(中文版)。

Geoguide 6 Guide to Reinforced Fill Structure and Slope Design (2002), 236 p.

Geoguide 7 Guide to Soil Nail Design and Construction (2008), 97 p.

GEOSPECS

Geospec 1 Model Specification for Prestressed Ground Anchors, 2nd Edition (1989), 164 p. (Reprinted, 1997).

Geospec 3 Model Specification for Soil Testing (2001), 340 p.

GEO PUBLICATIONS

GCO Publication No. 1/90 Review of Design Methods for Excavations (1990), 187 p. (Reprinted, 2002).

GEO Publication No. 1/93 Review of Granular and Geotextile Filters (1993), 141 p.

GEO Publication No. 1/2000 Technical Guidelines on Landscape Treatment and Bio-engineering for Man-made Slopes and Retaining Walls (2000), 146 p.

GEO Publication No. 1/2006 Foundation Design and Construction (2006), 376 p.

GEO Publication No. 1/2007 Engineering Geological Practice in Hong Kong (2007), 278 p.

GEO Publication No. 1/2009 Prescriptive Measures for Man-Made Slopes and Retaining Walls (2009), 76 p.

GEOLOGICAL PUBLICATIONS

The Quaternary Geology of Hong Kong, by J.A. Fyfe, R. Shaw, S.D.G. Campbell, K.W. Lai & P.A. Kirk (2000), 210 p. plus 6 maps.

The Pre-Quaternary Geology of Hong Kong, by R.J. Sewell, S.D.G. Campbell, C.J.N. Fletcher, K.W. Lai & P.A. Kirk (2000), 181 p. plus 4 maps.

TECHNICAL GUIDANCE NOTES

TGN 1 Technical Guidance Documents