

# **Review of Landslides in 2010**

**GEO Report No. 305**

**A.C.O. Li, J.C.W. Leung & H.W.K. Lam**

**Geotechnical Engineering Office  
Civil Engineering and Development Department  
The Government of the Hong Kong  
Special Administrative Region**

# **Review of Landslides in 2010**

**GEO Report No. 305**

**A.C.O. Li, J.C.W. Leung & H.W.K. Lam**

**This report was originally produced in February 2012  
as Landslide Study Report No. LSR 1/2012**

© The Government of the Hong Kong Special Administrative Region

First published, December 2014

Prepared by:

Geotechnical Engineering Office,  
Civil Engineering and Development Department,  
Civil Engineering and Development Building,  
101 Princess Margaret Road,  
Homantin, Kowloon,  
Hong Kong.

## Preface

In keeping with our policy of releasing information which may be of general interest to the geotechnical profession and the public, we make available selected internal reports in a series of publications termed the GEO Report series. The GEO Reports can be downloaded from the website of the Civil Engineering and Development Department (<http://www.cedd.gov.hk>) on the Internet. Printed copies are also available for some GEO Reports. For printed copies, a charge is made to cover the cost of printing.

The Geotechnical Engineering Office also produces documents specifically for publication in print. These include guidance documents and results of comprehensive reviews. They can also be downloaded from the above website.

These publications and the printed GEO Reports may be obtained from the Government's Information Services Department. Information on how to purchase these documents is given on the second last page of this report.



H.N. Wong  
Head, Geotechnical Engineering Office  
December 2014

## Foreword

This report presents the findings of a detailed diagnosis of landslides in 2010 that were reported to the Government. It serves to review the performance of the Government's slope safety system and identify areas for improvement, as well as to further enhance the slope engineering practice in Hong Kong.

The review was carried out by Dr A.C.O. Li, Mr H.W.K. Lam and Ms J.C.W. Leung of Landslip Preventive Measures Division 1 under the supervision of Mr W.K. Pun initially and later Mr Y.S. Au-Yeung. Assistance was provided by the landslide investigation consultants engaged by the Geotechnical Engineering Office, namely Fugro Scott Wilson Joint Venture and AECOM Asia Company Limited respectively. Technical support provided by Mr K.W. Cheung, Mr T.F.O. Luk and Mr K.H.K. Yiu is gratefully acknowledged.



Y.C. Chan  
Head of the Geotechnical Engineering Office

## **Abstract**

This report presents the findings of a diagnostic review of the landslides in 2010 that were reported to the Government. The review forms part of the GEO's systematic landslide investigation programme, which is an integral component of the Government's slope safety system. The aims of this report are to review the performance of the Government's slope safety system and identify areas for improvement, as well as to further enhance the slope engineering practice in Hong Kong.

Altogether 206 genuine landslides were reported to the Government in 2010. There were 15 major landslides (viz. failure volume of 50 m<sup>3</sup> or more), and none of them involved engineered man-made slopes that have been accepted under the slope safety system. Seven minor landslides (viz. failure volume of less than 50 m<sup>3</sup>) occurred on engineered man-made slopes. The corresponding annual failure rate is about 0.027% on a slope number basis (i.e. number of landslides relative to the total number of engineered slopes).

Overall, 99.97% of the engineered man-made slopes performed satisfactorily without occurrence of landslides in 2010.

Recommendations for further improvement of the slope safety system and slope engineering practice in Hong Kong are also given in this report.

## Contents

	Page No.
Title Page	1
Preface	3
Foreword	4
Abstract	5
Contents	6
List of Tables	8
List of Figures	9
1 Introduction	10
2 Rainfall and Landslides in 2010	10
3 Severity of Rainstorms as Reflected by Landslide Potential Index	15
4 Overall Diagnostic Review of Landslides	15
4.1 General	15
4.2 Coverage of the Catalogue of Slopes	15
4.2.1 General	15
4.2.2 Diagnosis	17
4.3 Performance of Registered Man-made Slopes	17
4.3.1 General	17
4.3.2 Landslides on Engineered Slopes	19
4.3.3 Landslides on Non-engineered Slopes	21
4.3.4 Annual Failure Rates	21
4.4 Natural Terrain Landslides	22
4.5 Landslides with Inadequate Slope Maintenance Diagnosed as a Key Contributory Factor to Failure	22
4.6 Major Landslides Involving Consequence-to-life Category 1 Slope Features	27
5 Proposed Improvement Initiative	27

	Page No.
6 Conclusions	27
7 References	28
Appendix A: Landslide Incidents Involving Slopes Processed under the Slope Safety System	29
Appendix B: List of 2010 Landslide Incidents Involving Unregistered Man-made Slopes but Registerable at the Time of Failure	34
Appendix C: Progress of Follow-up Actions on the Improvement Measures Recommended in the Review of 2009 Landslides	36



## List of Tables

Table No.		Page No.
2.1	Breakdown of Landslides by Type of Slope Failure	11
2.2	Breakdown of Landslides by Type of Affected Facility	12
2.3	Breakdown of Landslide Consequences by Type of Slope Failure	13
2.4	Breakdown of Facility Groups Affected by Major Landslides	14
2.5	Breakdown of Scale of Failures by Type of Slope	14
4.1	Breakdown of Landslides on Engineered Slopes	19
4.2	Breakdown of Landslides on Slopes Previously Treated under the LPM Programme	20
4.3	Annual Failure Rates of Registered Man-made Slopes in 2010	23
4.4	Breakdown of Annual Failure Rates of Registered Man-made Slopes	24
4.5	Annual Success Rates of Engineered Slopes from 1997 to 2010	25

## List of Figures

Figure No.		Page No.
3.1	Landslide Potential Index for Rainstorms that Resulted in the Issue of Landslip Warning from 1984 to 2010	16
4.1	Breakdown of Landslides on Unregistered Slopes in 2010	18
4.2	Annual Success Rates of Engineered Slopes from 1997 to 2010	26

## 1 Introduction

This report presents the findings of a diagnostic review of the landslides in 2010 that were reported to the Geotechnical Engineering Office (GEO) of the Civil Engineering and Development Department (CEDD) and other government departments. The review forms part of GEO's systematic landslide investigation (LI) programme, which is an integral component of the Government's slope safety system. The LI programme has the following two principal objectives:

- (a) to identify, through studies of landslides, slopes that are affected by inherent instability problems so that appropriate follow-up actions can be taken for integrated slope assessment and upgrading works, and
- (b) to review the performance of Government's slope safety system and identify areas for improvement in slope engineering practice.

The present diagnostic review considers all the available landslide data in 2010. The review has been carried out by the Landslip Preventive Measures Division 1 (LPM1) of the GEO, with assistance provided by GEO's LI consultants, namely Fugro Scott Wilson Joint Venture (FSWJV) and AECOM Asia Company Limited (AECOM).

## 2 Rainfall and Landslides in 2010

The factual information, together with the relevant statistics on rainfall and reported landslides in 2010, was documented by Leung et al (2011).

In 2010, the annual rainfall recorded at the Principal Raingauge of the Hong Kong Observatory (HKO) in Tsim Sha Tsui was 2,372 mm, close to the mean annual rainfall of 2,383 mm recorded between 1971 and 2000. Three Landslip Warnings were issued on 22 July, 28 July and 21 September 2010. Two Black Rainstorm Warnings were issued on 22 July and 28 July 2010; seven Red Rainstorm Warnings were issued between 22 July and 21 September 2010; and 17 Amber Rainstorm Warnings were issued between 7 May and 21 September 2010.

Reported landslides are classified as follows:

- (a) minor failure (i.e. failure volume  $< 50 \text{ m}^3$ ), and
- (b) major failure (i.e. failure volume  $\geq 50 \text{ m}^3$  or where a fatality has occurred).

In the present context, failure volume refers to the total sum of the volume of detached material and the volume of any deformed material that remains on the slope that may, or may not, have displaced significantly.

Of a total of 210 reported incidents in 2010, 206 were genuine landslides, discounting the non-landslide incidents (e.g. tree falls). There were 15 major failures, corresponding to about 7% of the number of genuine landslides.

The distribution of landslides, as classified by the type of slope failure, is given in Table 2.1. The range of facilities affected by the landslides is summarised in Table 2.2. The consequences of the landslides in relation to the type of slope failure are summarised in Table 2.3. The distribution of the different facility groups affected by major landslides is presented in Table 2.4. The distribution of the scale of failures, as classified by the type of slope involved, is given in Table 2.5.

**Table 2.1 Breakdown of Landslides by Type of Slope Failure**

Type of Slope Failure		Number	Percentage (%)
Fill Slopes		10 (2)	4.9
Cut Slopes	Soil	103 (5)	50.0
	Soil/Rock	23 (1)	11.1
	Rock	4 (0)	1.9
Retaining Walls		15 (0)	7.3
Natural Hillside		41 (7)	19.9
Registered Disturbed Terrain		10 (0)	4.9
Total		206 (15)	100

Legend:

23 (1) Twenty-three landslides, one of which was major failure (i.e. failure volume  $\geq 50 \text{ m}^3$ )

Notes: (1) Where a landslide involved more than one type of failure, the predominant type of failure has been considered in the above classification.  
(2) Incidents that were not genuine landslides have been excluded.

**Table 2.2 Breakdown of Landslides by Type of Affected Facility**

Type of Affected Facility	Hong Kong Island	Kowloon	New Territories and Outlying Islands	All
Buildings (including village houses)	3 (0)	0 (0)	19 (0)	22 (0)
Registered Squatter Dwellings	0 (0)	0 (0)	33 (2)	33 (2)
Roads	5 (0)	1 (1)	13 (0)	19 (1)
Transportation Facilities (e.g. railways, tramways, etc.)	0 (0)	0 (0)	0 (0)	0 (0)
Pedestrian Pavements/Footways	0 (0)	0 (0)	0 (0)	0 (0)
Minor Footpaths/Access Paths/Access Roads	6 (0)	2 (1)	68 (9)	76 (10)
Construction Sites	2 (0)	1 (1)	2 (0)	5 (1)
Open Areas	6 (0)	0 (0)	22 (1)	28 (1)
Catchwaters	0 (0)	0 (0)	2 (0)	2 (0)
Others (e.g. carparks, parks, playgrounds, gardens, backyards, etc.)	5 (1)	0 (0)	21 (1)	26 (2)
Nil Consequence	1 (0)	0 (0)	4 (0)	5 (0)
Total	28 (1)	4 (3)	184 (13)	216 (17)

Legend:

4 (3) Four landslides of which three were major failures (i.e. failure volume  $\geq 50 \text{ m}^3$ )

Notes:

- (1) A given landslide may affect more than one type of facility.
- (2) Incidents that were not genuine landslides have been excluded.
- (3) Nil consequence refers to incidents where the landslide debris came to rest on areas with no proper access for the public (e.g. natural hillside, slope berm, disused quarry surrounded by fence, etc.).

**Table 2.3 Breakdown of Landslide Consequences by Type of Slope Failure**

Type of Slope Failure		Number of Squatter Dwellings <sup>(1)</sup> Evacuated		Number of Floors, Houses or Flats Evacuated or Partially Closed	Number of Closure			Deaths	Injuries reported to GEO
		Permanent	Temporary		Roads	Pedestrian Pavements	Footpaths, Alleyways or Access Paths		
Fill Slopes		0 (0)	1 (2)	0	2	0	1	0	0
Cut Slopes	Soil	1 (2)	2 (5)	0	4	0	3	0	0
	Soil/Rock	0 (0)	0 (0)	0	0	0	0	0	0
	Rock	0 (0)	0 (0)	0	0	0	0	0	0
Retaining Walls		0 (0)	3 (9)	0	0	0	3	0	0
Natural Hillside		0 (0)	0 (0)	0	1	0	5	0	0
Registered Disturbed Terrain		0 (0)	0 (0)	0	0	0	0	0	0
Total		1 (2)	6 (16)	0	7	0	12	0	0

Legend:

1 (1) Number of squatter dwellings evacuated, with the number of tolerated squatter structures evacuated shown in brackets

Notes: (1) A squatter dwelling is defined as a place of residence that contains one or more tolerated squatter structures, i.e. structures built for domestic purposes or non-domestic purposes and registered in 1982 Housing Department's Squatter Structure Survey (GEO, 2010b).

(2) A failure may give rise to more than one type of consequence.

**Table 2.4 Breakdown of Facility Groups Affected by Major Landslides**

Type of Major Landslide	Facilities Group Affected by Major Landslides (Group No.)						
	1a	1b	2a	2b	3	4	5
All Major Landslides	0	2	0	1	1	9	4
Major Landslides on Man-made Slopes	0	2	0	1	1	4	2
Major Landslides on Registered Disturbed Terrain	0	0	0	0	0	0	0
Major Landslides on Natural Hillside	0	0	0	0	0	5	2

Notes: (1) Facility groups are classified in accordance with the GEO Technical Guidance Note No. 15 (GEO, 2007).  
 (2) A given landslide may affect more than one type of facility.

**Table 2.5 Breakdown of Scale of Failures by Type of Slope**

Type of Slope	Number of Minor Failures  ( $< 50 \text{ m}^3$ )	Number of Major Failures		Total
		( $50 \text{ m}^3$ to $< 500 \text{ m}^3$ )	( $\geq 500 \text{ m}^3$ )	
Registered Man-made Slopes	108	8	0	116
Registered Disturbed Terrain	10	0	0	10
Unregisterable Man-made Slopes	34	0	0	34
Registerable Man-made Slopes Not Yet Registered at Time of Failure	5	0	0	5
Natural Hillside	34	7	0	41
Total	191	15	0	206

### **3 Severity of Rainstorms as Reflected by Landslide Potential Index**

Experience has shown that the annual rainfall alone is not a good measure of the severity of the individual rainstorms in terms of their potential to trigger landslides. A more direct measure of the severity of the individual rainstorms in the context of landslides is given by the Landslide Potential Index (LPI), as promulgated by the GEO (2009a). The LPI is calculated for rainstorms that result in the issue of Landslip Warning and used to depict the relative severity of the rainstorm with respect to its potential to cause landslides. The LPI, which is not a predictive index, is based on the 24-hour rainfall of a rainstorm. The LPI for rainstorms that resulted in the issue of Landslip Warning from 1984 to 2010 is presented in Figure 3.1.

In 2010, three Landslip Warnings were issued on 22 July, 28 July and 21 September 2010. The LPI for these rainstorm events was assessed to be 1. In terms of its potential to cause landslides, the rainstorms of 22 July, 28 July and 21 September 2010 were one-tenth of the severity of the rainstorms of 23 July 1994 and 20 August 2005, both of which had an LPI of 10 and had triggered landslides resulting in fatalities (viz. the 23 July 1994 landslide at Kwun Lung Lau and the 20 August 2005 landslide at Fu Yung Shan Tsuen).

## **4 Overall Diagnostic Review of Landslides**

### **4.1 General**

An overall diagnostic review of the available 2010 landslide data has been carried out to appraise the slope performance, and facilitate the identification of areas in the slope safety system for further improvement.

The diagnostic review has mainly focused on the following aspects:


- (a) coverage of the Catalogue of Slopes,
- (b) performance of registered man-made slopes,
- (c) observations from natural terrain landslides, and
- (d) other areas of technical interest.

### **4.2 Coverage of the Catalogue of Slopes**

#### **4.2.1 General**

Sizeable man-made slopes and retaining walls, including those compiled under the GEO's project entitled "Systematic Identification and Registration of Slopes in the Territory" (SIRST) that was completed in September 1998, together with newly formed or identified slope features after 1998, are registered in the Catalogue of Slopes. Potentially registerable man-made slopes would also be identified during slope maintenance inspections, landslide investigations and other geotechnical inspections or studies (GEO, 2010a).





**Figure 3.1 Landslide Potential Index for Rainstorms that Resulted in the Issue of Landslip Warning from 1984 to 2010**

### 4.2.2 Diagnosis

Of the 206 genuine landslides, 126 occurred on registered slope features (comprising 116 on registered man-made slopes and ten on registered disturbed terrain (DT) features) and 80 occurred on slopes not registered in the Catalogue of Slopes (Table 2.5).

Among the above 80 landslides, 41 occurred on natural hillside, 34 occurred on small man-made slope features that do not meet the slope registration criteria (GEO, 2004). The remaining five landslides involved slope features that satisfied the slope registration criteria but were not registered in the Catalogue of Slopes at the time of failure, which was 2.4% of the number of genuine landslides in 2010. A breakdown of these 80 landslides is given in Figure 4.1.

The landslide incidents involving the five registerable slopes were all minor failures with a failure volume  $\leq 5 \text{ m}^3$ . Amongst these five failures, one resulted in temporary closure of a road and the remaining four incidents did not cause any significant impact on the community (Appendix B). Following the landslides, arrangements have been made to register the concerned man-made slope features in the Catalogue of Slopes.

The 34 landslides involving unregisterable man-made slope features were all minor failures with a failure volume  $\leq 12 \text{ m}^3$ .


## 4.3 Performance of Registered Man-made Slopes

### 4.3.1 General

The man-made slopes registered in the Catalogue of Slopes can be broadly classified into engineered slopes and non-engineered slopes. The performance of the registered man-made slopes is reviewed in terms of their annual failure rates.

Engineered slopes include the following:

- (a) slopes formed after 1977 (i.e. after the Geotechnical Control Office (renamed GEO in 1991) was established) that were designed, checked and accepted under the slope safety system as being up to the required geotechnical standards,
- (b) slopes formed before 1977 that were subsequently assessed, checked and accepted under the slope safety system as being up to the required geotechnical standards,
- (c) slopes formed before 1977 that were subsequently upgraded, checked and accepted under the slope safety system as being up to the required geotechnical standards, and



**Figure 4.1 Breakdown of Landslides on Unregistered Slopes in 2010**

- (d) slopes upgraded to the required geotechnical standards using Type 3 prescriptive measures (GEO, 2009b) under an adequate quality system satisfying the requirements of Environment, Transport and Works Bureau (ETWB) Technical Circular (Works) No. 13/2005 (ETWB, 2005) whereby checking of the design by the GEO has been waived.

For the present diagnosis, slopes that were not accepted under the slope safety system (e.g. no geotechnical submissions made to the GEO for checking, or submissions with outstanding GEO comments) are considered as non-engineered slopes.

Of the 206 genuine landslides in 2010, a total of 116 landslides (about 56%) occurred on registered man-made slopes (Table 2.5). Of these 116 landslides, seven (about 6%) occurred on engineered slopes, all of which were minor failures. Of the remaining 109 landslide incidents that occurred on non-engineered slopes, eight incidents were major and the remaining were minor. Further details on the landslides in 2010 involving engineered slopes are given in Appendix A. Detailed assessment of the engineered and non-engineered slopes is described in the sections below.

#### 4.3.2 Landslides on Engineered Slopes

Brief description of the engineered slope failures in 2010 are given in Appendix A. A breakdown of these seven landslides in terms of feature type is given in Table 4.1.

**Table 4.1 Breakdown of Landslides on Engineered Slopes**

Scale of Failure (m <sup>3</sup> )	Fill Slopes	Cut Slopes			Retaining Walls	Total
		Soil	Soil/Rock	Rock		
> 500 m <sup>3</sup>	0	0 (0)	0 (0)	0	0	0
50 m <sup>3</sup> to 500 m <sup>3</sup>	0	0 (0)	0 (0)	0	0	0
> 5 m <sup>3</sup> to < 50 m <sup>3</sup>	0	2 (0)	0 (0)	0	0	2
≤ 5 m <sup>3</sup>	0	2 (1)	3 (0)	0	0	5
Total	0	4 (1)	3 (0)	0	0	7

Legend:

- 2 (1) Of the two landslides, one occurred within or adjacent to the soil-nailed portion of the slope

Three of these seven engineered slope failures involved minor rockfalls, with a failure volume less than  $0.6 \text{ m}^3$ . These incidents occurred on the rock portion of soil/rock cut slopes without any surface protective measures. The incidents indicated that minor rockfalls may be difficult to guard against in the design of rock slopes. Provision of surface protective measures such as rock mesh netting could be a pragmatic solution.

One minor failure involved a soil-nailed cut slope (No. 13NE-A/C102), which was located at South Lantau Road, Lantau (Incident No. 2010/06/0942). The failure was associated with small-scale detachment ( $1 \text{ m}^3$ ) from the near-surface groundmass in between soil nail heads. This failure was shallow ( $\sim 0.3 \text{ m}$  deep) and had negligible consequence.

The other three incidents (Incident Nos. 2010/06/0947, 2010/08/1027 and 2010/05/0939) occurred on unsupported soil cut slopes. They were checked and accepted by the GEO between 1989 and 2001. The landslides involved a failure volume ranging from  $2.5 \text{ m}^3$  to  $40 \text{ m}^3$ , with negligible consequences.

Among the seven engineered slope failures, three involved slopes that have been previously treated under the Landslip Preventive Measures (LPM) Programme (see Table 4.2).

**Table 4.2 Breakdown of Landslides on Slopes Previously Treated under the LPM Programme**

Scale of Failure ( $\text{m}^3$ )	Fill Slopes	Cut Slopes			Retaining Walls	Total
		Soil	Soil/Rock	Rock		
$> 500 \text{ m}^3$	0	0	0	0	0	0
$50 \text{ m}^3$ to $500 \text{ m}^3$	0	0	0	0	0	0
$> 5 \text{ m}^3$ to $< 50 \text{ m}^3$	0	0	0	0	0	0
$\leq 5 \text{ m}^3$	0	1 (1)	2 (0)	0	0	3
Total	0	1 (1)	2 (0)	0	0	3

Legend:

2 (0) Of the two landslides involved, none occurred within or adjacent to the soil-nailed portion of the slope

### 4.3.3 Landslides on Non-engineered Slopes

There were 109 failures on non-engineered slopes in 2010, among which 101 failures were minor and eight were major.

Of the eight major failures, the largest one occurred on Slope No. 11NW-B/FR5 below Pak Wan Street ( $150 \text{ m}^3$ ), which resulted in temporary closure of the road (see also Section 4.6). Two other major failures (Incident Nos. 2010/07/0976 and 2010/07/0982) affected squatter dwellings. The rest of the major landslides did not have any notable consequence.

Of the 101 minor landslides, 60 were relatively small in scale with a failure volume less than  $5 \text{ m}^3$  and the rest had a failure volume ranging from  $5 \text{ m}^3$  to  $40 \text{ m}^3$ . Four incidents resulted in temporary road closure. Another resulted in damage of a car parked at the toe of the slope that failed. The rest did not have any notable consequence.

### 4.3.4 Annual Failure Rates

The annual failure rates of registered man-made slopes under different categories are presented in Tables 4.3 and 4.4. The annual failure rates have been assessed in terms of:

- (a) the number of landslides divided by the total number of slopes under a given category (e.g. slope type),
- (b) the surface area of landslides divided by the total surface area of slopes under a given category, and
- (c) the number of landslides divided by the total surface area of slopes under a given category.

By relating the failure rate to the surface area of slopes as in (b) above, it would have taken into account that a large slope is more susceptible to having 'defects' than a small slope. It is however noteworthy that the annual failure rates could be influenced by other factors, such as the rainfall characteristics, prevailing slope maintenance condition, etc.

The annual failure rates for all genuine landslides on registered man-made slopes in 2010 (excluding registered DT features) correspond to about 0.2% (number of landslides divided by number of registered man-made slopes), 0.005% (total surface area of landslides divided by total surface area of registered man-made slopes), and about  $2 \times 10^{-6}$  (number of landslides divided by total surface area of registered man-made slopes in  $\text{m}^2$ ) respectively. Further details are summarised in Table 4.4.

Based on the landslide data in 2010 (Table 4.4), the annual failure rates of engineered slopes are lower than that of non-engineered slopes by a factor of about 13 on a slope number basis, and about 88 on a slope surface area basis. In terms of the number of landslides per total slope surface area, the corresponding failure rate of engineered slopes is about 37 times lower than that of non-engineered slopes.

In addition, the annual failure rates of slopes previously treated under the LPM Programme correspond to 0.073% (number of landslides divided by number of registered man-made slopes treated under the LPM Programme), 0.0001% (total surface area of landslides divided by total surface area of registered man-made slopes treated under the LPM Programme), and about  $4 \times 10^{-7}$  (number of landslides divided by total surface area of registered man-made slopes treated under the LPM Programme in m<sup>2</sup>) respectively, as summarised in Table 4.4. The annual failure rate of slopes previously treated under the LPM Programme is lower than that of non-engineered slopes by a factor ranging from about 5 to 150, comparable to that of other engineered slopes.

GEO's target annual success rates (where success rate = 1 – failure rate) for engineered slopes are 99.8% and 99.5% against major and minor failures respectively, on the basis of the number of landslides per total number of slopes. In 2010, the corresponding annual success rates were 100% and 99.97% respectively. Hence, the targets were satisfactorily achieved. The trend of the annual success rates of engineered slopes against major and minor failures respectively for the period from 1997 to 2010 is shown in Table 4.5 and Figure 4.2.

#### **4.4 Natural Terrain Landslides**

A total of 41 natural terrain landslides were reported in 2010, seven of which were major failures. Three landslides resulted in temporary closure of a road, slight damage of a canopy structure of a building and flooding of a backyard and a car park of a residential building. The other natural terrain landslides did not have any notable consequence. Among these reported natural terrain landslides, seven failures (all minor) were located at or within 50 m from existing Historical Landslide Catchments.

#### **4.5 Landslides with Inadequate Slope Maintenance Diagnosed as a Key Contributory Factor to Failure**

All the 116 landslides on registered man-made slopes were reviewed to assess whether inadequate slope maintenance was likely to have been a key contributory factor to the failures. Reference has been made to the records of emergency inspections by the GEO or other government departments, inspections or follow-up studies by the LI consultants.

Inadequate slope maintenance was assessed to be a key contributory factor to 27 of the 116 landslides (i.e. about 23%), of which two incidents were major failures. Amongst these 27 landslides, three occurred on engineered slopes.

Of these 27 landslides involving inadequate slope maintenance, 16 affected Government slopes and five affected private slopes. The remaining six incidents affected slope features of mixed maintenance responsibility of Government/private, based on the information from the Slope Maintenance Responsibility Information System (SMRIS) maintained by the Lands Department. Of these six incidents involving slope features of mixed maintenance responsibility, four occurred on the Government portion and two were on the private portion.

**Table 4.3 Annual Failure Rates of Registered Man-made Slopes in 2010**

Annual Failure Rates		Non-Engineered Slopes			Engineered Slopes		
		Fill/Retaining Wall	Soil/Rock Cut	Overall	Fill/Retaining Wall	Soil/Rock Cut	Overall
Slopes Involved in Landslides in 2010	Number of Slopes	14	95	109	0	7	7
	Surface Area of Landslides (m <sup>2</sup> )	450	2,082	2,532	0	66	66
Slopes Involved in Major Landslides in 2010	Number of Slopes	2	6	8	0	0	0
	Surface Area of Landslides (m <sup>2</sup> )	261	548	809	0	0	0
Slopes Involved in Minor Landslides in 2010	Number of Slopes	12	89	101	0	7	7
	Surface Area of Landslides (m <sup>2</sup> )	189	1,534	1,723	0	66	66
Total Number of Registered Slopes		11,160	20,090	31,250	11,840	14,210	26,050
Total Surface Area of Registered Slopes (m <sup>2</sup> )		6,181,000	10,415,600	16,596,600	13,274,200	26,133,100	39,407,300
Annual Failure Rates (All Landslides)	On Slope Number Basis	0.125%	0.473%	0.349%	0%	0.049%	0.027%
	On Slope Surface Area Basis	0.007%	0.020%	0.015%	0%	0.00025%	0.00017%
	Number of Landslides Divided by Slope Surface Area (no./m <sup>2</sup> )	2.265 x 10 <sup>-6</sup>	9.121 x 10 <sup>-6</sup>	6.568 x 10 <sup>-6</sup>	0	2.679 x 10 <sup>-7</sup>	1.776 x 10 <sup>-7</sup>
Annual Failure Rates (Major Landslides)	On Slope Number Basis	0.018%	0.030%	0.026%	0%	0%	0%
	On Slope Surface Area Basis	0.004%	0.005%	0.005%	0%	0%	0%
	Number of Landslides Divided by Slope Surface Area (no./m <sup>2</sup> )	3.236 x 10 <sup>-7</sup>	5.761 x 10 <sup>-7</sup>	4.820 x 10 <sup>-7</sup>	0	0	0

Note: Landslides on registered disturbed terrain features have been excluded from this calculation.



**Table 4.4 Breakdown of Annual Failure Rates of Registered Man-made Slopes**

Category of Slope		Failure Rate on Slope Number Basis (i.e. number of landslides divided by total number of slopes)	Failure Rate on Slope Surface Area Basis (i.e. surface area of landslides divided by total surface area of slopes)	Failure Rate in Terms of Number of Landslides Divided by Total Surface Area of Slopes (no./m <sup>2</sup> )
Registered Man-made Slopes	All Landslides	0.202%	0.005%	$2.071 \times 10^{-6}$
	Major Landslides	0.014%	0.001%	$1.428 \times 10^{-7}$
	Minor Landslides	0.188%	0.003%	$1.928 \times 10^{-6}$
Engineered Slopes	All Landslides	0.027% (0.073%)	0.00017% (0.00010%)	$1.776 \times 10^{-7}$ ( $4.336 \times 10^{-7}$ )
	Major Landslides	0 (0)	0 (0)	0 (0)
	Minor Landslides	0.027% (0.073%)	0.00017 % (0.00010%)	$1.776 \times 10^{-7}$ ( $4.336 \times 10^{-7}$ )
Non-engineered Slopes	All Landslides	0.349% [12.9/4.8]	0.015% [88.2/150.0]	$6.568 \times 10^{-6}$ [37.0/15.1]
	Major Landslides	0.026%	0.005%	$4.820 \times 10^{-7}$
	Minor Landslides	0.323%	0.010%	$6.086 \times 10^{-6}$

Legend:


0.027%  
(0.073%) Annual failure rate of engineered slopes (considering all landslides) is 0.027% and that for slopes previously treated under the LPM Programme is 0.073%

0.349%  
[12.9/4.8] Annual failure rate of non-engineered slopes (considering all landslides) is 0.349%, which is about 12.9 times and 4.8 times higher than those of engineered slopes and slopes previously treated under the LPM Programme respectively

**Table 4.5 Annual Success Rates of Engineered Slopes from 1997 to 2010**

Scale of Failure	Annual Success Rate on Slope Number Basis (i.e. number of landslides divided by total number of slopes)													
	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010
Engineered Slopes Processed by the Slope Safety System ( $\geq 50 \text{ m}^3$ )	99.97%	99.98%	99.97%	99.98%	99.98%	100%	99.99%	100%	99.98%	100%	100%	99.99%	100%	100%
Engineered Slopes Processed by the Slope Safety System ( $< 50 \text{ m}^3$ )	99.89%	99.92%	99.92%	99.91%	99.93%	99.95%	99.95%	99.97%	99.89%	99.95%	99.97%	99.89%	99.95%	99.97%

Note: See Figure 4.2 for a plot of annual success rates of engineered slopes against the target annual success rates from 1997 and 2010.



- Legend:
- Annual success rate for engineered slopes against major failures
  - Annual success rate for engineered slopes against minor failures
  - Target annual success rate for engineered slopes against major failures (i.e. 99.8%)
  - Target annual success rate for engineered slopes against minor failures (i.e. 99.5%)

**Figure 4.2 Annual Success Rates of Engineered Slopes from 1997 to 2010**

The above diagnosis re-affirms the importance of regular slope maintenance. It also serves as a reminder that even an engineered slope is liable to failure without adequate maintenance.

#### **4.6 Major Landslides Involving Consequence-to-life Category 1 Slope Features**

There were three major landslides occurring on consequence-to-life Category 1 slope features. Of these three landslides, the largest one occurred on a fill slope (No. 11NW-B/FR5) at Pak Wan Street, Shek Kip Mei on 22 July 2010 during heavy rainfall. The landslide involved a 150 m<sup>3</sup> washout failure within a construction site where preventive maintenance works to the slope were being carried out by the Highways Department. The site was located below a bend along Pak Wan Street. Overflow from a nearby drainage culvert inlet might have resulted in an overland flow along Pak Wan Street, which overspilled at the bend of Pak Wan Street, resulting in washout failure of the slope below. The incident did not cause any casualty, but it highlighted the potential landslide risk arising from overland flow.

The remaining two major landslides occurring on non-engineered slopes of consequence-to-life Category 1, affected squatter dwellings. One occurred on a 3 m high cut slope (No. 7SW-C/C990) in Shek Lei Hang Village, Kwai Chung on 22 July 2010. Another occurred on a 6 m high fill slope (No. 7SW-D/F314) in Tin Sum Pak Tin Tsuen, Shatin on 22 July 2010. The failure volumes were 80 m<sup>3</sup> and 100 m<sup>3</sup> respectively. The landslide debris damaged the squatter structures, without causing any casualty. The occupants were temporarily evacuated. The incidents indicated that some squatter dwellings could be subject to relatively high landslide risk.

### **5 Proposed Improvement Initiative**

Based on the present review, the following improvement initiative is proposed:

- (a) Review notable landslides incidents involving severe overland flow and identify areas in the slope surface drainage provisions for improvement (Section 4.6).

Improvement initiatives proposed by Li et al (2011) following a review of landslides in 2009 and the associated progress of the follow-up actions are summarised in Appendix C.

### **6 Conclusions**

Overall, 99.97% of the engineered man-made slopes performed satisfactorily without occurrence of landslides in 2010. There was no major landslide on engineered slopes in 2010.

The annual failure rate of minor landslides on engineered slopes, on a slope number basis, was 0.027% in 2010. This corresponds to an annual success rate of 99.97%, which is well within the pledged annual success rate of 99.5%.

An initiative has been proposed, as detailed in Section 5 of this report, with a view to further improving the slope engineering practice and enhancing the slope safety system in Hong Kong.

## 7 References

- ETWB (2005). *Prescriptive Measures for Stabilisation and Improvement of Man-made Slopes and Standardised Debris-resisting Barriers for Mitigation of Natural Terrain Landslide Hazards (Technical Circular (Works) No. 13/2005)*. Environment, Transport and Works Bureau, Hong Kong, 7 p.
- GEO (2004). *Registration and Upgrading of Records of Features (GEO Circular No. 15)*. Geotechnical Engineering Office, Hong Kong, 20 p.
- GEO (2007). *Guidelines for Classification of Consequence-to-Life Category for Slope Features (GEO Technical Guidance Note No. 15)*. Geotechnical Engineering Office, Hong Kong, 14 p.
- GEO (2009a). *Landslide Potential Index (GEO Information Note No. 3/2009)*. Geotechnical Engineering Office, Hong Kong, 4 p.
- GEO (2009b). *Prescriptive Measures for Man-made Slopes and Retaining Walls (GEO Publication No. 1/2009)*. Geotechnical Engineering Office, Hong Kong, 76 p.
- GEO (2010a). *Catalogue of Slopes (GEO Information Note No. 5/2010)*. Geotechnical Engineering Office, Hong Kong, 3 p.
- GEO (2010b). *Non Development Clearance (Slope Safety) of Squatters (GEO Circular No. 3)*. Geotechnical Engineering Office, Hong Kong, 20 p.
- Leung, J.C.W., Lam, H.W.K. & Chan, H.W. (2011). *Factual Report on Hong Kong Rainfall and Landslides in 2010 (SPR Report No. 3/2011)*. Geotechnical Engineering Office, Hong Kong, 93 p.
- Li, A.C.O., Lau, J.W.C. & Lam, C.L.H. (2011). *Review of Landslides in 2009 (LSR Report No. 1/2011)*. Geotechnical Engineering Office, Hong Kong, 38 p.

## Appendix A

### Landslide Incidents Involving Slopes Processed under the Slope Safety System

**Table A1 Landslide Incidents Involving Slopes Processed under the Slope Safety System (Sheet 1 of 4)**

Incident No.	Slope No.	Location	Failure Volume (m <sup>3</sup> )	Type of Slope	Remarks
1. <u>Slopes Upgraded Under the LPM Programme</u> ( $\Sigma = 3$ nos.)					
2010/06/0942	13NE-A/C102	Along South Lantau Road, near Shek Pik Reservoir, Lantau	1	Soil Cut	The works, mainly comprising installation of soil nails and raking drains, and provision of vegetated cover with erosion control mat, were completed in 2005. The shallow failure (about 0.3 m deep) involved the near-surface groundmass within the soil-nailed portion of the slope.
2010/06/0944	11SE-C/C3	Near No. 37, Repulse Bay Road	0.6 (rockfall)	Soil/ Rock Cut	The works, mainly comprising installation of soil nails and raking drains, rock dowels, concrete buttress, rock fall wire mesh, were completed in 2001.
2010/11/1079	11SE-D/C49	Near Lamp Post No. 33678 at Wan Tsui Road, Chai Wan	0.3 (rockfall)	Soil/ Rock cut	The works, mainly comprising installation of soil nails and raking drains, and provision of typical rock slope treatment works, were completed in 1999.

**Table A1 Landslide Incidents Involving Slopes Processed under the Slope Safety System (Sheet 2 of 4)**

Incident No.	Slope No.	Location	Failure Volume (m <sup>3</sup> )	Type of Slope	Remarks
2. <u>Slopes Assessed under the LPM Programme with No Upgrading Works Required</u> ( $\Sigma = 1$ no.)					
2010/06/0947	11SE-A/CR450	1-10 Sai Wan Terrace, Sai Wan Ho	40	Soil Cut	A Stage 2 Study was completed in 2001. The report concluded that the slope met the required safety standards.
3. <u>Slopes Assessed by Studies in the Late 1970's to mid-1980's with No Upgrading Works/Further Study Required</u> ( $\Sigma = 0$ no.)					
Nil.					
4. <u>Slopes Assessed by Government Departments and Checked by GEO with No Upgrading Works Required</u> ( $\Sigma = 1$ no.)					
2010/05/0940	11SW-C/C76	Queen Mary Hospital	~0.1 (rockfall)	Soil/ Rock Cut	A geotechnical assessment report by Arch SD was carried out in 1993, which was checked and accepted by the GEO in July 1993. By that time, no upgrading works were required in light that the slope had been treated with rock slope measures such as rock buttressing, rock dowels etc in 1983.
5. <u>Slopes Assessed by Private Owners and Checked by GEO with No Upgrading Works Required</u> ( $\Sigma = 0$ no.)					
Nil.					



**Table A1 Landslide Incidents Involving Slopes Processed under the Slope Safety System (Sheet 3 of 4)**

Incident No.	Slope No.	Location	Failure Volume (m <sup>3</sup> )	Type of Slope	Remarks
--------------	-----------	----------	----------------------------------	---------------	---------

6. Slopes Formed or Upgraded by Government Departments and Checked by GEO ( $\Sigma = 1$  nos.)

2010/08/1027	7SW-C/CR457	Natural Stream above, Wo Yi Hop Lane	10	Soil Cut	The geotechnical design/assessment of the slope was carried out in relation to Route 5 in Tsuen Wan Road Connections, which was checked and accepted by the GEO in 1991.
--------------	-------------	--------------------------------------	----	----------	--

7. Slopes Formed or Upgraded by Private Owners and Checked by GEO ( $\Sigma = 1$  no.)

2010/05/0939	15NE-A/CR684	No. 45 Island Road	2.5	Soil Cut	The geotechnical design/assessment of the slope was carried out in relation to the site formation works under a private development project, which was checked and accepted by the GEO in 1989.
--------------	--------------	--------------------	-----	----------	---

8. Slopes Upgraded Following Service of DH Orders and Checked by GEO ( $\Sigma = 0$  no.)

Nil.

**Table A1 Landslide Incidents Involving Slopes Processed under the Slope Safety System (Sheet 4 of 4)**

Incident No.	Slope No.	Location	Failure Volume (m <sup>3</sup> )	Type of Slope	Remarks
--------------	-----------	----------	----------------------------------	---------------	---------

9. Slopes Assessed as Not Requiring Upgrading Works But with Outstanding GEO Comments ( $\Sigma = 1$  no.)

ArchSD/SKW& IS-S/2010/02/0003	11SE-B/CR272	Hong Kong Museum of Coastal Defence	<0.1 (rockfall)	Soil/Rock Cut	The geotechnical design/assessment of the slope was carried out in relation to the Site Formation Works for Lei Yue Mun Museum, which was checked by the GEO in 1997, with outstanding comment on slope surface protection at the slope (including the rock portion where the 2010 rockfall incident occurred).
-------------------------------	--------------	-------------------------------------	-----------------	---------------	---


10. Slopes Assessed as Requiring Upgrading Works But with Outstanding GEO Comments ( $\Sigma = 0$  no.)

Nil.

Legend:



Landslide occurred on or adjacent to the soil-nailed portion of a cut slope ( $\Sigma = 1$  nos.)



Landslide involved unsupported cuts ( $\Sigma = 3$  no.)

Notes:

- (1) Slopes under Categories 1 to 8 are classified as engineered slopes.
- (2) Slopes under Categories 9 and 10 are post-1977 features but are not taken as engineered slopes for the purpose of this report.
- (3) Incident No. 2010/09/1050 involved a boulder fall near the crest of a cut slope No. 15NE-A/CR29 which had been processed under the slope safety system. However whether the boulder originated from the cut slope is not certain, due to lack of field evidence. This case is not covered in the slope list above.

## Appendix B

### List of 2010 Landslide Incidents Involving Unregistered Man-made Slopes but Registerable at the Time of Failure

**Table B1 List of 2010 Landslide Incidents Involving Unregistered Man-made Slopes but Registerable at the Time of Failure**

Incident No.	Location	Maximum Slope Height	Reported		Failure			Facility Affected	Consequence
			Date	From	Date (Time)	Feature Type	Scale (m³)		
2010/06/0949	Opposite of lamp post N2424, Clear Water Bay Road	5.3m	10/6	HyD	10/6	Soil Cut	5	Road	1 of 2 lane of Clear Water Bay Road closed
2010/06/0951	Behind No. 49 Kam Shan Village, Tai Po	3.3m	8/6	DLO	1/1 (00:00)	Retaining wall	0.5	Squatter Structures	Nil
2010/08/1032	House No. 91, Fo Tan Village, Sha Tin	5.4m	30/7	LandsD	23/7 (15:15)	Soil Cut	3	Open Area	Nil
2010/10/1071	Near L/P No. VE4584, Tseng Tau, Sai Kung North	5.6m	5/10	DLO	1/10 (11:15)	Soil cut	1	Minor footpath	Nil
2010/12/1086	House No. 173, Ha Wo Che Village, Sha Tin	4m	16/12	LandsD	09/12 (14:30)	Soil Cut	2	Village House	Nil

## Appendix C

### Progress of Follow-up Actions on the Improvement Measures Recommended in the Review of 2009 Landslides

**Table C1 Progress of Follow-up Actions on the Improvement Measures Recommended in the Review of 2009 Landslides**

Recommended Improvement Measures	Progress
1. Develop a methodology for technical screening and review of ‘signed-off’ features as a safety-net measure to identify slopes requiring follow-up actions.	Trial implementation of technical screening and review of selected ‘signed-off’ feature has been completed. The full implementation of the technical screening and review would be carried out under GEO Strategic Goal No. 2.
2. Review landslides on man-made slopes with a history of past failures and identify appropriate follow-up actions.	An initial screening has identified some man-made slopes of consequence-to-life category 1 with a history of past failures. The cases are being reviewed with respect to the actions that had been taken, so as to identify any further follow-up actions required.

## GEO PUBLICATIONS AND ORDERING INFORMATION

### 土力工程處刊物及訂購資料

A selected list of major GEO publications is given in the next page. An up-to-date full list of GEO publications can be found at the CEDD Website <http://www.cedd.gov.hk> on the Internet under "Publications". Abstracts for the documents can also be found at the same website. Technical Guidance Notes are published on the CEDD Website from time to time to provide updates to GEO publications prior to their next revision.

**Copies of GEO publications (except geological maps and other publications which are free of charge) can be purchased either by:**

Writing to  
Publications Sales Unit,  
Information Services Department,  
Room 626, 6th Floor,  
North Point Government Offices,  
333 Java Road, North Point, Hong Kong.

or

- Calling the Publications Sales Section of Information Services Department (ISD) at (852) 2537 1910
- Visiting the online Government Bookstore at <http://www.bookstore.gov.hk>
- Downloading the order form from the ISD website at <http://www.isd.gov.hk> and submitting the order online or by fax to (852) 2523 7195
- Placing order with ISD by e-mail at [puborder@isd.gov.hk](mailto:puborder@isd.gov.hk)

**1:100 000, 1:20 000 and 1:5 000 geological maps can be purchased from:**

Map Publications Centre/HK,  
Survey & Mapping Office, Lands Department,  
23th Floor, North Point Government Offices,  
333 Java Road, North Point, Hong Kong.  
Tel: (852) 2231 3187  
Fax: (852) 2116 0774

**Requests for copies of Geological Survey Sheet Reports and other publications which are free of charge should be directed to:**

For Geological Survey Sheet Reports which are free of charge:  
Chief Geotechnical Engineer/Planning,  
(Attn: Hong Kong Geological Survey Section)  
Geotechnical Engineering Office,  
Civil Engineering and Development Department,  
Civil Engineering and Development Building,  
101 Princess Margaret Road,  
Homantin, Kowloon, Hong Kong.  
Tel: (852) 2762 5380  
Fax: (852) 2714 0247  
E-mail: [jsewell@cedd.gov.hk](mailto:jsewell@cedd.gov.hk)

For other publications which are free of charge:  
Chief Geotechnical Engineer/Standards and Testing,  
Geotechnical Engineering Office,  
Civil Engineering and Development Department,  
Civil Engineering and Development Building,  
101 Princess Margaret Road,  
Homantin, Kowloon, Hong Kong.  
Tel: (852) 2762 5346  
Fax: (852) 2714 0275  
E-mail: [florenceko@cedd.gov.hk](mailto:florenceko@cedd.gov.hk)

部份土力工程處的主要刊物目錄刊載於下頁。而詳盡及最新的土力工程處刊物目錄，則登載於土木工程拓展署的互聯網網頁 <http://www.cedd.gov.hk> 的“刊物”版面之內。刊物的摘要及更新刊物內容的工程技術指引，亦可在這個網址找到。

**讀者可採用以下方法購買土力工程處刊物(地質圖及免費刊物除外):**

書面訂購  
香港北角渣華道333號  
北角政府合署6樓626室  
政府新聞處  
刊物銷售組

或

- 致電政府新聞處刊物銷售小組訂購 (電話: (852) 2537 1910)
- 進入網上「政府書店」選購，網址為 <http://www.bookstore.gov.hk>
- 透過政府新聞處的網站 (<http://www.isd.gov.hk>) 於網上遞交訂購表格，或將表格傳真至刊物銷售小組 (傳真: (852) 2523 7195)
- 以電郵方式訂購 (電郵地址: [puborder@isd.gov.hk](mailto:puborder@isd.gov.hk))

**讀者可於下列地點購買1:100 000、1:20 000及1:5 000地質圖：**

香港北角渣華道333號  
北角政府合署23樓  
地政總署測繪處  
電話: (852) 2231 3187  
傳真: (852) 2116 0774

**如欲索取地質調查報告及其他免費刊物，請致函：**

免費地質調查報告:  
香港九龍何文田公主道101號  
土木工程拓展署大樓  
土木工程拓展署  
土力工程處  
規劃部總土力工程師  
(請交:香港地質調查組)  
電話: (852) 2762 5380  
傳真: (852) 2714 0247  
電子郵件: [jsewell@cedd.gov.hk](mailto:jsewell@cedd.gov.hk)

其他免費刊物:  
香港九龍何文田公主道101號  
土木工程拓展署大樓  
土木工程拓展署  
土力工程處  
標準及測試部總土力工程師  
電話: (852) 2762 5346  
傳真: (852) 2714 0275  
電子郵件: [florenceko@cedd.gov.hk](mailto:florenceko@cedd.gov.hk)

## **MAJOR GEOTECHNICAL ENGINEERING OFFICE PUBLICATIONS**

### **土力工程處之主要刊物**

#### **GEOTECHNICAL MANUALS**

Geotechnical Manual for Slopes, 2nd Edition (1984), 302 p. (English Version), (Reprinted, 2011).

斜坡岩土工程手冊(1998) , 308頁(1984年英文版的中文譯本)。

Highway Slope Manual (2000), 114 p.

#### **GEOGUIDES**

Geoguide 1            Guide to Retaining Wall Design, 2nd Edition (1993), 258 p. (Reprinted, 2007).

Geoguide 2            Guide to Site Investigation (1987), 359 p. (Reprinted, 2000).

Geoguide 3            Guide to Rock and Soil Descriptions (1988), 186 p. (Reprinted, 2000).

Geoguide 4            Guide to Cavern Engineering (1992), 148 p. (Reprinted, 1998).

Geoguide 5            Guide to Slope Maintenance, 3rd Edition (2003), 132 p. (English Version).

岩土指南第五冊      斜坡維修指南 , 第三版(2003) , 120頁(中文版)。

Geoguide 6            Guide to Reinforced Fill Structure and Slope Design (2002), 236 p.

Geoguide 7            Guide to Soil Nail Design and Construction (2008), 97 p.

#### **GEOSPECS**

Geospec 1            Model Specification for Prestressed Ground Anchors, 2nd Edition (1989), 164 p. (Reprinted, 1997).

Geospec 3            Model Specification for Soil Testing (2001), 340 p.

#### **GEO PUBLICATIONS**

GCO Publication      Review of Design Methods for Excavations (1990), 187 p. (Reprinted, 2002).  
No. 1/90

GEO Publication      Review of Granular and Geotextile Filters (1993), 141 p.  
No. 1/93

GEO Publication      Foundation Design and Construction (2006), 376 p.  
No. 1/2006

GEO Publication      Engineering Geological Practice in Hong Kong (2007), 278 p.  
No. 1/2007

GEO Publication      Prescriptive Measures for Man-Made Slopes and Retaining Walls (2009), 76 p.  
No. 1/2009

GEO Publication      Technical Guidelines on Landscape Treatment for Slopes (2011), 217 p.  
No. 1/2011

#### **GEOLOGICAL PUBLICATIONS**

The Quaternary Geology of Hong Kong, by J.A. Fyfe, R. Shaw, S.D.G. Campbell, K.W. Lai & P.A. Kirk (2000), 210 p. plus 6 maps.

The Pre-Quaternary Geology of Hong Kong, by R.J. Sewell, S.D.G. Campbell, C.J.N. Fletcher, K.W. Lai & P.A. Kirk (2000), 181 p. plus 4 maps.

#### **TECHNICAL GUIDANCE NOTES**

TGN 1                Technical Guidance Documents