

LIST OF PLATES

| Plate No. |   | Page No. |
|-----------|---|----------|
| 1         | South Lantau Road, near Cheung Fu Street,<br>Cheung Sha, Lantau Island, Slope No.13NE-B/C3<br>(Incident MW 1/1) | 46       |
| 2         | South Lantau Road, near Cheung Fu Street,<br>Cheung Sha, Lantau Island, Slope No.13NE-B/C3<br>(Incident MW 1/1) | 46       |
| 3         | Tai Tam Road, near Junction of Shek O Road,<br>Slope No.11SE-D/C146<br>(Incident HK 3/1)                        | 47       |
| 4         | Tai Tam Road, near Junction of Shek O Road,<br>Slope No.11SE-D/C146<br>(Incident HK 3/1)                        | 47       |
| 5         | Nos.33 to 37 Blue Pool Road,<br>Slope No.11SW-D/CR178<br>(Incident HK 4/2)                                      | 48       |
| 6         | Nos.33 to 37 Blue Pool Road,<br>Slope No.11SW-D/CR178<br>(Incident HK 4/2)                                      | 48       |
| 7         | Yee King Road, opposite Islamic College and<br>near Lamp Post 33389, Slope No.11SE-A/C214<br>(Incident HK 4/21) | 49       |
| 8         | No.14A Belcher's Street, Slope No.11SW-A/C371<br>(Incident HK 4/28)   | 49       |
| 9         | No.4 Tai Wo Tsuen, Peng Chau<br>(Incident MW 4/8)   | 50       |
| 10        | No.4 Tai Wo Tsuen, Peng Chau<br>(Incident MW 4/8)   | 50       |
| 11        | Baguio Villas, Victoria Road, Pokfulam<br>(Incident HK 5/8)   | 51       |
| 12        | Baguio Villas, Victoria Road, Pokfulam<br>(Incident HK 5/8)   | 51       |

| Plate No. |   | Page No. |
|-----------|---|----------|
| 13        | Siu Sai Wan PSPS Site, Chai Wan,<br>Slope No.11SE-D/C183<br>(Incident HK 5/18)  | 52       |
| 14        | Siu Sai Wan PSPS Site, Chai Wan,<br>Slope No.11SE-D/C183<br>(Incident HK 5/18)  | 52       |
| 15        | No.92 Pokfulam Road, Kennedy Town,<br>Slope No.11SW-A/C323<br>(Incident HK 5/26)                                      | 53       |
| 16        | Kennedy Road, below Wah Yan College,<br>Happy Valley, Fill Slope above<br>Slope No.11SW-D/CR403<br>(Incident HK 5/38) | 54       |
| 17        | Kennedy Road, below Wah Yan College,<br>Happy Valley, Fill Slope above<br>Slope No.11SW-D/CR403<br>(Incident HK 5/38) | 54       |
| 18        | No.9 Middle Gap Road, Wan Chai Gap,<br>Slope No.11SW-D/CR550<br>(Incident HK 5/39)                                    | 55       |
| 19        | No.9 Middle Gap Road, Wan Chai Gap,<br>Slope No.11SW-D/CR550<br>(Incident HK 5/39)                                    | 55       |
| 20        | Below No.156 Tai Hang Road, So Kon Po<br>(Incident HK 5/50)   | 56       |
| 21        | Below No.5 Coombe Road, Magazine Gap,<br>Slope No.11SW-D/F107<br>(Incident HK 5/70)                                   | 56       |
| 22        | Choi Shek Lane, Ngau Tau Kok,<br>Slope No.11NE-A/C104<br>(Incident K 5/1)   | 57       |
| 23        | Jat's Incline, above Fung Shing Street<br>(Incident K 5/6)  | 57       |
| 24        | Wong Chuk Yeung, Fo Tan, Shatin<br>(Incident ME 5/22)   | 58       |

| Plate No. |   | Page No. |
|-----------|---|----------|
| 25        | Wong Chuk Yeung, Fo Tan, Shatin<br>(Incident ME 5/22)   | 58       |
| 26        | Hiking Trail, Kan Cho Long, Lamma Island<br>(Incident MW 5/2)   | 59       |
| 27        | Hiking Trail, Kan Cho Long, Lamma Island<br>(Incident MW 5/2)   | 59       |
| 28        | Tai Po Road, near Carlton Hotel, Kowloon<br>(Incident MW 5/3)   | 60       |
| 29        | Nos.22 to 23 Hung Hing Ye, Lamma Island<br>(Incident MW 5/6)  | 61       |
| 30        | Nos.22 to 23 Hung Hing Ye, Lamma Island<br>(Incident MW 5/6)  | 61       |
| 31        | No.14 Yung Shue Long New Village,<br>Lamma Island, Slope No.14NE-B/C10<br>(Incident MW 5/51)          | 62       |
| 32        | No.14 Yung Shue Long New Village,<br>Lamma Island, Slope No.14NE-B/C10<br>(Incident MW 5/51)          | 62       |
| 33        | Behind No.2 Shing Ka Road, Peng Chau,<br>Slope No.10SW-B/C8<br>(Incident MW 5/66)                     | 63       |
| 34        | Behind No.2, Shing Ka Road, Peng Chau,<br>Slope No.10SW-B/C8<br>(Incident MW 5/66)                    | 63       |
| 35        | Ha Wo Che Squatter Area, Shatin<br>(Incident ME 6/10)   | 64       |
| 36        | Pak Kong Treatment Works, Sai Kung<br>(Incident ME 6/13)  | 65       |
| 37        | Pak Kong Treatment Works, Sai Kung<br>(Incident ME 6/13)  | 65       |
| 38        | Urban Fringe Park opposite King Lam Estate,<br>Po Lam Road North, Tseung Kwan O<br>(Incident ME 6/14) | 66       |

| Plate<br>No. |   | Page<br>No. |
|--------------|---|-------------|
| 39           | Urban Fringe Park opposite King Lam Estate,<br>Po Lam Road North, Tseung Kwan O<br>(Incident ME 6/14) | 66          |
| 40           | Access Road to Ma On Shan Tsuen,<br>Shatin, Slope No.7NE-D/C1<br>(Incident ME 6/18)                   | 67          |
| 41           | Lung Mun Road, near Siu Lang Shui,<br>Slope No.5SE-D/C2<br>(Incident MW 6/17)                         | 68          |
| 42           | Lung Mun Road, near Siu Lang Shui,<br>Slope No.5SE-D/C2<br>(Incident MW 6/17)                         | 68          |
| 43           | Behind changing rooms at Kwun Yam Wan Beach,<br>Cheung Chau<br>(Incident MW 6/20)                     | 69          |
| 44           | Behind changing rooms at Kwun Yam Wan Beach,<br>Cheung Chau<br>(Incident MW 6/20)                     | 69          |
| 45           | Behind House UKS/GPA1/263,<br>Upper Keung Sha, Lantau Island<br>(Incident MW 6/21)                    | 70          |
| 46           | Sham Wat Road, Lantau Island<br>(Incident MW 6/33)  | 71          |
| 47           | King's Lodge, Lot 1886A in DD7, Wai Tau Tsuen<br>(Incident ME 7/4)                                    | 72          |
| 48           | Nos.21A to 23, Siu Lam Tsuen,<br>Tuen Mun, Slope No.6SW-D/N2<br>(Incident MW 7/32)                    | 73          |
| 49           | Nos.21A to 23, Siu Lam Tsuen,<br>Tuen Mun, Slope No.6SW-D/N2<br>(Incident MW 7/32)                    | 73          |





Plate 1 : Negative No. MW9200819 Taken on : 21-1-92



Plate 2 : Negative No. MW9200814A Taken on : 21-1-92

Description : Major failure (about 1000m<sup>3</sup>) of a soil cut slope resulting in the blockage of two lanes of road.

Plates 1 & 2 : South Lantau Road, near Cheung Fu Street, Cheung Sha, Lantau Island. Slope No. 13NE-B/C3 (Incident MW 1/1)





Plate 3 : Negative No. I9206505 Taken on : 4-3-92

Plate 4  
Negative No. I9206524  
Taken on : 4-3-92

Description : Failure of a rock cut slope (about 17 m<sup>3</sup>) resulting in the blockage of one lane of road.

Plates 3 & 4 : Tai Tam Road, near  
Junction of Shek O Road, Slope No.  
11SE-D/C146. (Incident HK 3/1)





Plate 5  
Negative No. I9212610  
Taken on : 7-4-92

Description : Failure of a soil cut slope (about 35 m<sup>3</sup>) resulting in the evacuation of two 4-storey apartment blocks.



Plate 6 : Negative No. I9212107 Taken on : 7-4-92

Plates 5 & 6 : Nos. 33 to 37 Blue Pool Road, Slope No. 11SW-D/CR178.  
(Incident HK 4/2)





Negative Nos. I9213709A & I9213710A Taken on : 11-4-92  
Description : Boulder fall (about 20 m<sup>3</sup>) resulting in the blockage of 1 lane of road.

Plate 7 : Yee King Road, opposite Islamic College and near Lamp Post 33389, Slope No. 11SE-A/C214.  
(Incident HK 4/21)



Negative No. I9214317 Taken on : 13-4-92  
Description : Boulder fall from a rock cut slope resulting in the evacuation of a squatter hut.

Plate 8 : No. 14A Belcher's Street, Slope No. 11SW-A/C371.  
(Incident HK 4/28)





Plate 9 : Negative No. MW9208202 Taken on : 14-4-92

Description : Failure of a soil cut slope (about 10 m<sup>3</sup>)  
resulting in the closure of a private  
pedestrian access behind a two-storey house.



Plate 10 : Negative No. MW9208200 Taken on : 14-4-92

Plates 9 & 10 : No. 4, Tai Wo Tsuen, Peng Chau. (Incident MW 4/8)



Plate 11  
Negative No. PS71111  
Taken on : 9-5-1992

Description : Major failure of a retaining wall and a fill platform (about 3500 m<sup>3</sup>). Two dead, five injured, seven apartment blocks evacuated. Block 26 illustrated.



Plate 12 : Negative No. I92210I03 Taken on : 9-5-92  
Description : Major failure of a retaining wall and fill platform (about 3500 m<sup>3</sup>).  
Two dead, five injured, seven apartment blocks evacuated. Block 44  
illustrated.  
Plates 11 & 12 : Baguio Villas, Victoria Road, Pokfulam. (Incident HK 5/8)





Plate 13 : Negative No. PS70911 Taken on : 9-5-92



Plate 14 : Negative No. SP9203901 Taken on : 9-5-92

Description : Major failure of a soil and rock cut slope (about 100 m<sup>3</sup>) affecting a construction site.

Plates 13 & 14 : Siu Sai Wan PSPS Site, Chai Wan, Slope No. 11SE-D/C183.  
(Incident HK 5/18)



Plate 15 : Negative No. I9226113 Taken on : 18-5-92

Description : Failure of a soil cut slope (5-10 m<sup>3</sup>) resulting in the blockage of a pedestrian pavement and partial blockage of one lane of road.

Plate 15 : No. 92 Pokfulam Road, Kennedy Town, Slope No. 11SW-A/C323.  
(Incident HK 5/26)






Plate 16 : Negative No. SP9205925 Taken on : 8-5-92



Plate 17 : Negative No. SP9206021 Taken on : 8-5-92  
Description : Major failure of a fill slope (about 500 m<sup>3</sup>). One dead,  
three lanes of Kennedy Road blocked.

Plates 16 & 17 : Kennedy Road, below Wah Yan College, Happy Valley,  
Fill Slope above Slope No. 11SW-D/CR403. (Incident HK 5/38)





Plate 18 : Negative No. I9220812 Taken on : 9-5-92



Plate 19 : Negative No. I9220814 Taken on : 9-5-92

Description : Failure of a soil cut slope (about 45 m<sup>3</sup>) resulting in the blockage of a private access.

Plates 18 & 19 : No. 9 Middle Gap Road, Wan Chai Gap,  
Slope No. 11SW-D/CR550. (Incident HK 5/39)





Plate 20 : Negative No. PS71003 Taken on : 9-5-92

Description : Major failure of a fill slope (about 100 m<sup>3</sup>), resulting in the exposure of a foundation column of an apartment block.

Plate 20 : Below No.156 Tai Hang Road, So Kon Po. (Incident HK 5/50)



Plate 21 : Negative No. A9206704 Taken on : 9-5-92

Description : Major failure of a retaining wall(about 55m<sup>3</sup>) resulting in ground subsidence and the closure of two road lanes.

Plate 21 : Below No.5 Coombe Road, Magazine Gap, Slope No. 11SW-D/F107.  
(Incident HK 5/70)





Plate 22 : Negative No. ME9217820 Taken on : 8-5-92  
Description : Failure of a soil and rock cut slope (about 30 m<sup>3</sup>) resulting in the partial blockage of an access road.

Plate 22 : Choi Shek Lane, Ngau Tau Kok, Slope No. 11NE-A/C104.  
(Incident K 5/1)

Plate 23  
Negative No. ME9218001  
Taken on : 8-5-92

Description : Major failure of a fill slope (about 65 m<sup>3</sup>) resulting in road closure.

Plate 23 : Jat's Incline above Fung Shing Street.  
(Incident K 5/6)







Plate 24 : Negative No. ME9218019 Taken on : 11-5-92



Plate 25 : Negative No. ME9218018 Taken on : 11-5-92

Description : Subsidence of a pedestrian pavement resulting in closure of pavement

Plates 24 & 25 : Wong Chuk Yeung, Fo Tan, Shatin. (Incident ME 5/22)





Plate 26 : Negative No. MW9210520 Taken on : 11-5-92



Plate 27 : Negative No. MW9210522 Taken on : 11-5-92

Description : Major failure of a natural slope (about 200 m<sup>3</sup>) resulting in the closure of a footpath.

Plates 26 & 27 : Hiking Trail, Kan Cho Long, Lamma Island. (Incident MW 5/2)





Plate 28 : Negative No. SP9300104 Taken on : 9-5-92

Description : Major failure of a fill slope ( $>50 \text{ m}^3$ ) resulting in the closure of one lane of road.

Plate 28 : Tai Po Road, near Carlton Hotel, Kowloon. (Incident MW 5/3)



Plate 29 : Negative No. MW9209806 Taken on : 8-5-92



Plate 30 : Negative No. MW9209807 Taken on : 8-5-92

Description : Failure of a retaining wall (about 45m<sup>3</sup>) leading to closure of a private pedestrian access and the evacuation of an apartment.

Plates 29 & 30 : Nos. 22 to 23, Hung Hing Ye, Lamma Island. (Incident MW 5/6)





Plate 31 : Negative No. MW 9211204 Taken on: 13-5-92



Plate 32 : Negative No. MW9211206 Taken on : 13-5-92

Description : Failure of a soil cut slope (about 20 m<sup>3</sup>) resulting in the evacuation of a private house.

Plates 31 & 32 : No. 14 Yung Shue Long New Village, Lamma Island, Slope No. 14NE-B/C10. (Incident MW 5/51)





Plate 33 : Negative No. MW9213100 Taken on : 20-5-92

Description : Failure of a soil cut slope (about 4 m<sup>3</sup>) resulting in the closure of a private back lane and the evacuation of two squatter huts.



Plate 34 : Negative No. MW9213101 Taken on : 16-6-92

Plates 33 & 34 : Behind No.2 Shing Ka Road, Peng Chau, Slope No. 10SW-B/C8. (Incident MW 5/66)



Negative No. SP9300105 Taken on : 14.6.92

Description : Major failure of a natural slope (about 300 m<sup>3</sup>) resulting in the evacuation of 43 squatter huts.

Plate 35 : Ha Wo Che Squatter Area, Shatin. (Incident ME 6/10)





Plate 36 : Negative No. ME9224705 Taken on : 16-6-92



Plate 37 : Negative No. ME9226111 Taken on : 16-6-92

Description : Major failure of a soil cut slope (about 9000 m<sup>3</sup>) resulting in the evacuation of private houses (due to severe cracking and subsidence) and excessive movements (bulging) of a crib wall.

Plates 36 & 37 : Pak Kong Treatment Works, Sai Kung. (Incident ME 6/13)





Plate 38 : Negative No. SP9222303 Taken on : 23-7-92

Description : Major failure of a soil/rock cut slope (about 300m<sup>3</sup>) resulting in boulder falls and damage to an urban fringe park.

Plate 39

Negative No. SP9221236

Taken on : 14-7-92

Description : Final resting place of large boulders (Location A in Plate 38) at the base of the slope.

Plates 38 & 39 : Urban Fringe Park opposite King Lam Estate, Po Lam Road North, Tseung Kwan O (Incident ME 6/14)







Plate 40 : Negative Nos. ME9225818 & ME9225819 Taken on : 23-6-92

Description : Failure of a rock cut slope (about 30 m<sup>3</sup>) resulting in the partial blockage of a rural road.

Plate 40 : Access Road to Ma On Shan Tsuen, Shatin, Slope No. 7NE-D/C1  
(Incident ME 6/18)





Plate 41 : Negative No. MW9214408 Taken on : 16-6-92

Description : Failure of a soil cut slope (about 5 m<sup>3</sup>) leading to the partial blockage of a pedestrian pavement.



Plate 42 : Negative No. MW9214407 Taken on : 16-6-92

Plates 41 & 42 : Lung Mun Road, near Siu Lang Shui, Slope No. 5SE-D/C2. (Incident MW 6/17)





Plate 43 : Negative No. MW9214920 Taken on : 16-6-92

Description : Failure of a rock cut slope ( about 10 m<sup>3</sup>) damaging several changing rooms at a beach resort.



Plate 44 : Negative No. MW9214915 Taken on : 16-6-92

Plates 43 & 44 : Behind changing rooms at Kwun Yam Wan Beach, Cheung Chau. (Incident MW 6/20)





Plate 45 : Negative No. MW9216207 Taken on : 17-6-92

Description : Failure of a fill slope (about 40 m<sup>3</sup>) resulting in the destruction of a private access and the evacuation of a private house.

Plate 45 : Behind House UKS/GPA1/263, Upper Keung Sha, Lantau Island.  
(Incident MW 6/21)



Plate 46 : Negative No. MW9216816 Taken on : 24-6-92

Description : Failure of a natural slope (about 15 m<sup>3</sup>) resulting in the blockage of one lane of road.

Plate 46 : Sham Wat Road, Lantau Island. (Incident MW 6/33)





Plate 47 : Negative Nos. ME9230621 & ME9230622 Taken on : 21-7-92

Description : Failure of a natural slope (about 30 m<sup>3</sup>), affecting the open area adjacent to a private house.

Plate 47 : King's Lodge, Lot 1886A in DD7, Wai Tau Tsuen. (Incident ME 7/4)





Plate 48 : Negative No. MW9219405 Taken on : 28-7-92



Plate 49 : Negative No. MW9219417 Taken on : 28-7-92

Description : Failure of a soil cut slope (about 25 m<sup>3</sup>) resulting in the closure of a pedestrian footpath.

Plates 48 & 49 : Nos. 21A to 23, Siu Lam Tsuen, Tuen Mun, Slope No. 6SW-D/N2.  
(Incident MW 7/32)