

- LEGEND**
- ★ Landslide incident >50m³
 - Landslide incident >5m³ ~50m³ in weathered rock or colluvium
 - ▲ Retaining wall failure
 - Minor incident <5m³
 - Surface erosion
 - Landslide scar noted in Binnie and Partners 1977-1978 slope catalogue (approximate location).
- HK025/17 Landslide Incident number
11SE-DC03 Binnie and Partners slope reference number

STUDY AREA BOUNDARY

no.	date	description	initial
REVISION			
		name	date
surveyed			
designed		N.P.Koor	
drawn			
tracked			
checked		N.P.Koor	
examined			


contract no.	
file no.	G0P2/E2/10
job no.	

project
ASSESSMENT OF GEOLOGICAL FEATURES RELATED TO RECENT LANDSLIDES IN VOLCANIC ROCKS OF HONG KONG
PHASE 2A: CHAI WAN

drawing title
MAP No. 3
LANDSLIDE INCIDENTS

drawing no.	scale
GS-SP/11-SE-D/759	1:5 000

office
 PLANNING DIVISION
 GEOTECHNICAL ENGINEERING OFFICE



CIVIL
ENGINEERING
DEPARTMENT