



LEGEND

- S1R8/7 Stage 1 Study Report
- S2R3/82 Stage 2 Study Report
- Stage 1 and 2 Study boundary
- Notes
- Landslide Study Phase I/C Area boundary
- Notes
- Island Division File boundary
- BLD Duplicate Files
- Architectural Office Projects
- Housing Projects
- Dangerous Hill Files
- GAS8 boundary
- Photointerpretation taken from GAS8 Report
- Zone of general instability taken from GAS8 Report
- 10m highly decomposed volcanics Notes from GAS8 Report
- Binrie and Partners - Slope Catalogue 1977-1978 - Slope Number
- Binrie and Partners - Slope Catalogue 1977-1978 - Slope Number
- PGA2/88 ASD Geotechnical Assesment Report
- ASD Geotechnical Assesment Report boundary

no.	date	description	initial
REVISION			
		name	d ate
surveyed			
designed		N.P. KOOR	7/96
drawn			
tracked			
checked		N.P. KOOR	7/96
examined			

contract no.	
file no.	GCP 2/E2/10
job no.	
project	ASSESSMENT OF GEOLOGICAL FEATURES RELATED TO RECENT LANDSLIDES IN VOLCANIC ROCKS OF HONG KONG
	PHASE 2A: CHAI WAN

MAP No.5
REPORT SUMMARY

drawing no.	GS-SP/11-SE-D/761	scale	1:5 000
office	PLANNING DIVISION GEOTECHNICAL ENGINEERING OFFICE		

