


LEGEND

- Seepage noted in GAS8 Report with month and year of observation
- Seepage noted in Stage 1 or 2 Study with month and year of observation
- Seepage noted in Binnie and Partners Slope Catalogue with month and year of observation
- Seepage noted in Binnie and Partners Landslide Study Phase IIC with year of observation
- Seepage noted during Field Survey as part of this report (June/July 1996)
- Seepage (S) - from API Map No. 1
- Cut slope, GEO registration number as shown for slopes referred to in the report
- Retaining wall, GEO registration number as shown for walls referred to in the report
- Cut slopes which may have Engineering Geological conditions similar to those at Fei Tsui Road

no.	date	description	initial
REVISION			
		name	date
surveyed		Survey Division	
designed		S.D.G. CAMPBELL / N.P. Koor	7/96
drawn			
traced			
checked		S.D.G. CAMPBELL / N.P. Koor	7/96
examined			
contract no.			
file no. GCP 2 / E2 / 10			
job no.			
project			
ASSESSMENT OF GEOLOGICAL FEATURES RELATED TO RECENT LANDSLIDES IN VOLCANIC ROCKS OF HONG KONG			
PHASE 2A: CHAI WAN			
drawing title			
MAP No. 6			
SEEPAGES AND REGISTERED SLOPES (EXCLUDING FILL SLOPES)			
drawing no.		scale	
GS-SP/11-SE-D/762		1:5 000	
office			
PLANNING DIVISION GEOTECHNICAL ENGINEERING OFFICE			
 CIVIL ENGINEERING DEPARTMENT			