

LEGEND

- 5.1967F — Landslide Scar with date of aerial photographs first observed
  - A - natural slope relict feature with obvious head scarp
  - B - natural slope relict feature with no obvious head scarp
  - D- fresh landslide scar in natural slope, bare of vegetation
  - F - fresh landslide scar in cut slope, bare of vegetation
  - (for relict features, no date is given)
- (SP) — Seepage with date of aerial photographs first observed
- Area inferred to susceptible to landsliding (E)
- 18.11.85 GCP 1/1/250 II — Features extracted from API Report with date and file reference (e.g. GCP 1/1/250 ⊡ as shown
- 1949 coastline
- Photolineament

no.	date	description	initial

REVISION

	name	date
surveyed	W.L.Shum	
designed	W.L.Shum	11/96
drawn	Y.H.CHIU	11/96
traced		
checked		
examined		
contract no.		
file no.	GCP 2/E2/10	
job no.		

project

ASSESSMENT OF GEOLOGICAL FEATURES RELATED TO RECENT LANDSLIDES IN VOLCANIC ROCKS OF HONG KONG

PHASE 2B: ABERDEEN

drawing title

MAP No. 1

AERIAL PHOTOGRAPH INTERPRETATION

drawing no.	scale
GS-SP/15-NW-B/752	1:5 000

office

PLANNING DIVISION

GEOTECHNICAL ENGINEERING OFFICE

CIVIL ENGINEERING DEPARTMENT