

LIST OF FIGURES

| Figure No. |                                                                                                              | Page No. |
|------------|--------------------------------------------------------------------------------------------------------------|----------|
| 1          | Location Plan                                                                                                | 50       |
| 2          | Site Location Plan for Landslides B and C                                                                    | 51       |
| 3          | Regional Geology                                                                                             | 52       |
| 4          | Past Landslides                                                                                              | 53       |
| 5          | Plan of the Source Area of Landslides B and B1                                                               | 54       |
| 6          | Section A-A through Landslide B                                                                              | 55       |
| 7          | Section B-B through Landslide B                                                                              | 56       |
| 8          | Section C-C through Landslide B1                                                                             | 57       |
| 9          | Plan of Upper Section of Debris Trail for Landslide B                                                        | 58       |
| 10         | Plan of Lower Section of Debris Trail for Landslide B                                                        | 59       |
| 11         | Section D-D through Landslide B                                                                              | 60       |
| 12         | Plan of the Source Area of Landslide C                                                                       | 61       |
| 13         | Section E-E through Landslide C                                                                              | 62       |
| 14         | Plan of the Debris Trail for Landslide C                                                                     | 63       |
| 15         | Section F-F through Landslide C                                                                              | 64       |
| 16         | Schematic Representation Showing the Inferred Development of a Possible Debris Dam located below Landslide B | 65       |
| 17         | Location Plan of Ground Investigation Works                                                                  | 66       |
| 18         | Sketch of the Eastern Main Scarp                                                                             | 67       |
| 19         | Stereoplot of the Measured Orientations of Discontinuities at Landslide B                                    | 68       |
| 20         | Sketch of West Face of Trial Trench LKTT1                                                                    | 69       |

| Figure<br>No. |                                                                                           | Page<br>No. |
|---------------|-------------------------------------------------------------------------------------------|-------------|
| 21            | Sketch Plan of Fractures/Joints on Floor of Landslide B                                   | 70          |
| 22            | Stereoplots of Main Release Surface, Landslide B                                          | 71          |
| 23            | Profile of Main Release Surface, Landslide B                                              | 72          |
| 24            | Rainfall Recorded at GEO Raingauge No. N07                                                | 73          |
| 25            | Rainfall Distribution between 07:00 hours on 13 April and<br>07:00 hours on 14 April 2000 | 74          |
| 26            | Maximum Rainfall Preceding the Landslides of 14 April<br>2000 at Raingauge No. N07        | 75          |
| 27            | Location Plan of Photographs Taken                                                        | 76          |




Figure 1 - Location Plan




Figure 2 - Site Location Plan for Landslides B and C




Figure 3 - Regional Geology




Figure 4 - Past Landslides





Figure 5 - Plan of the Source Area of Landslides B and B1






Figure 7 - Section B-B through Landslide B




Figure 8 - Section C-C through Landslide B1




Figure 9 - Plan of Upper Section of Debris Trail for Landslide B





Figure 10 - Plan of Lower Section of Debris Trail for Landslide B






Figure 12 - Plan of the Source Area of Landslide C




Figure 13 - Section E-E through Landslide C





Figure 14 - Plan of the Debris Trial for Landslide C






Figure 16 - Schematic Representation Showing the Inferred Development of a Possible Debris Dam located below Landslide B





Figure 17 - Location Plan of Ground Investigation Works



Note: Sketch based on Plates 17 and 18.

Figure 18 - Sketch of the Eastern Main Scarp




Figure 19 - Stereoplot of the Measured Orientations of Discontinuities at Landslide B




Figure 20 - Sketch of West Face of Trial Trench LKTT1




Figure 21 - Sketch Plan of Fractures/Joints on Floor of Landslide B




Figure 22 - Stereoplots of Main Release Surface, Landslide B






Figure 23 - Profile of Main Release Surface, Landslide B



(a) Daily Rainfall Recorded between 13 March and 16 April 2000



(b) Hourly Rainfall Recorded between 00:00 hour on 13 April and 24:00 hours on 14 April 2000

Figure 24 - Rainfall Recorded at GEO Raingauge No. N07




Figure 25 - Rainfall Distribution between 07:00 hours on 13 April and 07:00 hours on 14 April 2000




Figure 26 - Maximum Rainfall Preceding the Landslides of 14 April 2000 at Raingauge No. N07




Figure 27 - Location Plan of Photographs Taken