



Figure 1 - TDR Test Results at an LPM Site in Chai Wan



E8 (Blue)



Pulse width = 10 ns

R12-N3 (Blue)

Soil Nail No. R12-N3,
Wire with blue plastic
sheath

Measurements are taken at
Side A

Figure 2 - TDR Test Results at an LPM Site in Chai Wan




Figure 3 - TDR Test Results at an LPM Site in Chai Wan




Figure 4 - TDR Test Results at an LPM Site in Chai Wan




Figure 5 - TDR Test Results at an LPM Site in Chai Wan




Figure 6 - TDR Test Results at an LPM Site in Chai Wan