




Figure 1 - TDR Test Results at an LPM Site along Tai Po Road




Figure 2 - TDR Test Results at an LPM Site along Tai Po Road




Figure 3 - TDR Test Results at an LPM Site along Tai Po Road




Figure 4 - TDR Test Results at an LPM Site along Tai Po Road